

**FINAL**  
**Hazardous Building**  
**Materials Assessment**  
**(Management)**

Thousand Islands Secondary  
School  
2510 Parkedale Avenue,  
Brockville, Ontario

Prepared for:

**Upper Canada District School  
Board**

225 Central Avenue West  
Brockville, Ontario, K6V 5X1

September 15, 2023

Pinchin File: 302783.034



**Hazardous Building Materials Assessment (Management)**

Thousand Islands Secondary School, 2510 Parkedale Avenue, Brockville, Ontario  
Upper Canada District School Board

September 15, 2023  
Pinchin File: 302783.034  
FINAL

**Issued to:** Upper Canada District School Board  
**Issued on:** September 15, 2023  
**Pinchin File:** 302783.034  
**Issuing Office:** Kingston, ON

---

Author: 

---

Kristen Vanderburgt  
Project Coordinator  
613.541.1013  
[kvanderburgt@pinchin.com](mailto:kvanderburgt@pinchin.com)

Reviewer: 

---

Halie MacKillican  
Project Manager  
613.541.1013  
[hmackillican@pinchin.com](mailto:hmackillican@pinchin.com)

Reviewer: 

---

Mark Stroombergen, CET, EMBA  
Executive Vice President  
902.393.4376  
[mstroombergen@pinchin.com](mailto:mstroombergen@pinchin.com)



## **EXECUTIVE SUMMARY**

Upper Canada District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct a hazardous building materials assessment at Thousand Islands Secondary School located at 2510 Parkedale Avenue, Brockville, Ontario. Pinchin performed the assessment on July 19, 2022, July 20, 2022 and August 11, 2022.

The objective of the assessment was to document the locations of specified hazardous building materials, evaluate their condition and develop corrective action plans as required for the purposes of long-term management. The results of this assessment can be used for construction, renovation, demolition or project tendering purposes conditional that additional intrusive investigations are completed and excluded materials are sampled prior to disturbance, if required.

## **SUMMARY OF FINDINGS**

### Asbestos:

- Parging cement insulation
- Caposite insulation
- Acoustic ceiling tiles
- Smooth and textured plaster
- Vinyl sheet flooring
- Vinyl floor tiles
- Caulking and butyl sealants
- Paint on concrete block walls (Building Phase E)
- All asbestos-containing materials were observed to be in good condition with the exception of the following:
  - Parging cement insulation damage and debris present in Locations 1022, 1091, 1097, 1115, 1885, 1978, 2977 and 2979
  - Caposite insulation damage and debris present in Location 1983

### Lead:

- Lead is present in paints and coatings
- Batteries of emergency lights and fire alarm control panels contain solid lead
- Caulking on cast iron pipe joints (bell and spigot) contains lead



Silica: Crystalline silica is present in concrete and other materials such as masonry, mortar, ceramic tiles, grout, ceiling tiles, terrazzo, drywall and plaster.

Mercury: Mercury vapour is present in lamp tubes and liquid mercury is present in instrumentation.

Polychlorinated Biphenyls (PCBs): PCBs may be present in light ballasts.

Mould and Water Damage: Visible mould growth was observed on the drywall wall in Location 1012. Water damage was observed on the acoustic ceiling tiles in Location 2160.

## **SUMMARY OF RECOMMENDATIONS**

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations:

1. Remediate materials listed in Section 5.2.
2. Assess and/or sample materials listed as excluded or presumed prior to disturbance.
3. Prepare an Asbestos Management Program (AMP).
4. Perform a re-assessment of ACM on an annual basis.
5. Perform a pre-construction assessment and remove all ACM prior to alteration or maintenance work if ACM may be disturbed by the work.
6. Remove and properly dispose of PCB ballasts when fixtures are decommissioned. All PCB lamp ballasts must be removed from service and properly disposed of by December 31, 2025.
7. Recycle mercury-containing lamp tubes and instrumentation when removed from service.
8. Follow appropriate safe work procedures when handling or disturbing asbestos, lead, silica and mould.

*This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.*



## TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE .....	1
1.1	Scope of Assessment .....	1
2.0	METHODOLOGY .....	2
3.0	BACKGROUND INFORMATION .....	2
3.1	Building Description .....	2
3.2	Existing Reports .....	3
3.3	Inaccessible Locations .....	3
4.0	FINDINGS .....	3
4.1	Asbestos .....	3
4.2	Lead .....	18
4.3	Silica .....	20
4.4	Mercury .....	20
4.5	Polychlorinated Biphenyls .....	20
4.6	Mould and Water Damage .....	21
5.0	RECOMMENDATIONS .....	22
5.1	General .....	22
5.2	Remedial Work .....	22
5.3	On-going Management and Maintenance .....	24
6.0	TERMS AND LIMITATIONS .....	26
7.0	REFERENCES .....	26

## APPENDICES

APPENDIX I	Drawings
APPENDIX II-A	Asbestos Analytical Certificates
APPENDIX II-B	Lead Analytical Certificates
APPENDIX II-C	PCB Analytical Certificates
APPENDIX III	Methodology and Evaluation Criteria
APPENDIX IV	Location Summary Report
APPENDIX V	Hazardous Materials Summary Report / Sample Log
APPENDIX VI	HMIS All Data Report



## 1.0 INTRODUCTION AND SCOPE

Upper Canada District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct a hazardous building materials assessment at Thousand Islands Secondary School located at 2510 Parkedale Avenue, Brockville, Ontario.

Pinchin performed the assessment on July 19, 2022, July 20, 2022 and August 11, 2022. The assessed area was occupied at the time of the assessment.

The objective of the assessment was to document the locations of specified hazardous building materials, evaluate their condition and develop corrective action plans as required. This assessment is to be used for the purposes of long-term management and routine maintenance. The results of this assessment can be used for construction, renovation, demolition or project tendering purposes conditional that additional intrusive investigations are completed and excluded materials are sampled prior to disturbance, if required.

### 1.1 Scope of Assessment

The **assessed area** consisted of all interior and exterior areas of the building, excluding the roof.

The assessment was performed to establish the type of specified hazardous building materials, locations and approximate quantities incorporated in the structure(s) and its finishes.

For the purpose of the assessment and this report, hazardous building materials are defined as follows:

- Asbestos
- Lead
- Silica
- Mercury
- Polychlorinated Biphenyls (PCBs)
- Mould

The following Designated Substances are not typically found in building materials in a composition/state that is hazardous and were not included in this assessment:

- Arsenic
- Acrylonitrile
- Benzene
- Coke oven emissions



- Ethylene oxide
- Isocyanates
- Vinyl chloride monomer

## 2.0 METHODOLOGY

Pinchin conducted a room-by-room assessment (rooms, corridors, service areas, exterior, etc.) to identify the hazardous building materials as defined in the scope.

The assessment was limited to non-intrusive testing. Concealed spaces such as those above solid ceilings and within shafts and pipe chases were accessed via existing access panels only. Destructive testing of flooring was not conducted (under carpets or multiple layers of flooring). Demolition of walls, solid ceilings, structural items, interior finishes or exterior building finishes, to determine the presence of concealed materials was not conducted. Sampling of roofing materials was not conducted.

For further details on the methodology including test methods and evaluation criteria, refer to Appendix III.

## 3.0 BACKGROUND INFORMATION

### 3.1 Building Description

Description Item	Details
Use	Secondary School
Number of Floors	The building is two storeys
Total Area	The total area of the building is 153,219 square feet
Year of Construction	Building Phase C: 1960 Building Phase D: 1963 Building Phase E: 1967
Structure	Structural steel, wood and concrete
Exterior Cladding	Brick and concrete
HVAC	Boiler with hot water heating to radiators, suspended unit heaters and air handling units
Roof	Flat (outside of scope)
Flooring	Vinyl sheet flooring, vinyl floor tiles, terrazzo, concrete, rubber, ceramic tiles and hardwood
Interior Walls	Laminate, brick, drywall, concrete block, poured concrete, prefabricated concrete panels, plaster, wood, metal and ceramic tiles
Ceilings	Laminate, acoustic ceiling tiles, wood, metal, plaster, drywall and wicker acoustic panels



### 3.2 Existing Reports

Pinchin previously prepared the following reports, which have been reviewed as part of this assessment:

- *“Hazardous Building Materials Assessment, Thousand Islands Secondary School, 2510 Parkedale Avenue, Ontario”, prepared by Pinchin Ltd. dated January 24, 2012, File No. 71528.*

### 3.3 Inaccessible Locations

The following rooms or areas were not accessible and are therefore not included in the report.

Area or Room	Reason
Locations 1722, 1732 and 2480	Locked, no key

## 4.0 FINDINGS

The following section summarizes the findings of the assessment and provides a general description of the hazardous building materials identified. For details on approximate quantities, condition, friability, accessibility, and locations of hazardous building materials; refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI.

Any quantities listed in this report or data tables are estimated based on visual approximations only and are subject to variation.

### 4.1 Asbestos

#### 4.1.1 Spray-Applied Insulation

Spray-applied fireproofing and overspray present on a steel column in the second floor corridor of Building Phase E (Location 2979) does not contain asbestos (samples S0073A-C).





Non-asbestos sprayed fireproofing present on the steel column.

#### 4.1.2 Pipe Insulation

Parging cement, containing asbestos, is present on pipe fittings (elbows, ends, joints, tees, etc.), on various pipe systems throughout the building (previous Pinchin samples 0006A-C).

A white corrugated paper insulation (trade name Aircell), containing asbestos, previously reported as being present on straight sections of domestic hot water system pipes in the Boiler Room (Location 1892) was abated prior to the 2022 assessment (previous Pinchin samples 0026A-C).

A brown preformed fibrous block insulation (trade name Caposite), containing asbestos, is present on straight sections of unknown system pipes in the first floor corridor of Building Phase C (Location 1983) (samples S0056A-C).

Sweatwrap insulation (brown layered paper) present on straight sections of various pipe systems in isolated locations throughout the building does not contain asbestos (previous Pinchin samples 0005A-C).

A brown corrugated paper insulation (trade name Aircell) covered with sweatwrap insulation (brown layered paper) present on straight sections of various pipe systems in isolated locations does not contain asbestos (previous Pinchin samples 0003A-C).

Remaining pipes in the assessed area are either uninsulated or insulated with non-asbestos fiberglass or other non-asbestos insulation such as mineral fibre or elastomeric foam insulation.

Pipes insulated with asbestos-containing insulations may be present in inaccessible spaces such as above solid ceilings, in chases, in column enclosures and within shafts.



Asbestos-containing paring cement insulation on pipe elbows.



Asbestos-containing Caposite insulation.



Non-asbestos sweatwrap insulation.

#### 4.1.3 Duct Insulation and Mastic

A brown preformed fibrous block insulation (trade name Caposite), containing asbestos, previously reported as being present on the straight sections of the boiler exhaust ductwork in the Boiler Room (Location 1083) was abated prior to the 2022 assessment (previous Pinchin samples 0007A-C).

Preformed block insulation, containing asbestos, previously reported as being present on the elbows of the boiler exhaust ductwork in the Boiler Room (Location 1083) was abated prior to the 2022 assessment (previous Pinchin samples 0008A-C).

Remaining ducts are either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas jacketing).

#### 4.1.4 Mechanical Equipment Insulation

Gaskets, presumed to contain asbestos, previously reported as being present at doors and sealed components of boilers in the Boiler Room (Location 1083) have been abated prior to the 2022 assessment.

Mechanical equipment (e.g., hot water tanks, boilers, suspended unit heaters, air handling units) is either uninsulated or insulated with non-asbestos fibreglass.



Non-asbestos insulated boilers.



Non-asbestos fibreglass insulated suspended unit heater.





#### 4.1.5 Vermiculite




Destructive testing of concrete block walls to investigate for loose fill vermiculite was not conducted due to the current building use.

Loose fill vermiculite debris was not observed in the spaces/areas inspected.



#### 4.1.6 Acoustic Ceiling Tiles

The following is a summary of acoustic ceiling tiles sampled, for a complete list of locations, refer to Appendix V.

Description	Sample Location	Sample Number, Date Code or Material Composition	Asbestos	Photo
1'x1', mechanically fastened, large and medium uniform pinholes	Office (Location 1081) Workroom (Location 1530) Classroom (Location 2180)	Previous Pinchin Samples 0004A-C	No	
1'x1', glued-on, large and medium random pinholes	Staff Lounge (Location 1031)	Previous Pinchin Samples 0009A-C	No	
2'x4', lay-in, textured finish and pinholes	Library (Location 1511)	Previous Pinchin Samples 0011A-C	No	
<i>2'x4', lay-in, fine textured surface</i>	<i>Corridor (Location 1091)</i>	<i>Previous Pinchin Samples 0012A-C</i>	<i>No (No Longer Present)</i>	
2'x4', lay-in, lengthwise deep wide fissures and pinholes	Corridor (Location 1091)	Previous Pinchin Samples 0013A-C	No	

Description	Sample Location	Sample Number, Date Code or Material Composition	Asbestos	Photo
1'x1', splined, fissures and pinholes	Conference Room (Location 1010)	Previous Pinchin Samples 0016A-C	No	
1'x1', splined, smooth textured finish	Vestibule (Location 1982)	Previous Pinchin Samples 0017A-C	No	
1'x1', mechanically fastened, coarse texture and fissures	Office (Location 1111) Washroom (Location 1970)	Previous Pinchin Samples 0020A-C	No	
1'x1', mechanically fastened, smooth	Drama (Location 1110) Classroom (Location 2180)	Previous Pinchin Samples 0021A-C	No	
1'x1', mechanically fastened, smooth fissures	Corridor Ramp and Stairwell (Location 2996)	Previous Pinchin Samples 0029A-C	No	



Description	Sample Location	Sample Number, Date Code or Material Composition	Asbestos	Photo
2'x4', lay-in, textured finish and pinholes	Classroom (Location 2250)	Previous Pinchin Samples 0036A-C	Yes	
2'x4', lay-in, dense pinholes and short and medium widthwise fissures	Washroom (Location 1012) Storage (Location 1013)	Samples S0050A-C	No	

Adhesive associated with 1'x1' acoustic ceiling tiles throughout the building does not contain asbestos (previous Pinchin samples 0010A-C).

Remaining ceiling tiles are presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles or based on the composition of the tiles (e.g., wicker). The tiles were manufactured after asbestos stopped being used in acoustic ceiling tiles.



Non-asbestos acoustic ceiling tile mastic.

#### 4.1.7 *Plaster and Stucco*

Plaster (base coat only), containing asbestos, is present on walls and ceilings in isolated locations of Building Phase C and Building Phase D (samples S0052A-G). The plaster is applied to metal lath.

Smooth two-layer plaster present on walls and ceilings throughout Building Phase C does not contain asbestos (previous Pinchin samples 0001A, B, E and F and samples S0057A-G).

Smooth plaster, containing asbestos in the finish layer, is present on walls and ceilings throughout Building Phase E (previous Pinchin samples 0001D and G and samples S0062A-G). A total of nine samples of plaster were collected and it was found that one sample contains asbestos. The asbestos-positive result indicates that at a minimum, a portion of the plaster application contains asbestos, and all smooth plaster present throughout the 1967 addition is presumed to contain asbestos. Further sampling may be considered to delineate asbestos-containing plaster from newer, non-asbestos plaster. The plaster is applied to metal lath.


Smooth two-layer plaster present on walls and ceilings throughout Building Phase D does not contain asbestos (previous Pinchin samples 0001C and samples S0071A-E).

Textured plaster present on the exterior canopies of Building Phase C and Building Phase E does not contain asbestos (samples S0080A-C and S0078A-C, respectively).

Textured plaster, containing asbestos, is present on the exterior canopies of Building Phase D (samples S0081A-C). The plaster is applied to metal lath.



Asbestos-containing plaster base coat in Building Phase D.



Asbestos-containing smooth plaster in Building Phase E.



Asbestos-containing textured plaster on exterior canopy of Building Phase D.


#### 4.1.8 Drywall Joint Compound

Drywall joint compound present on wall and ceiling finishes throughout the building does not contain asbestos (previous Pinchin samples 0002A-G and samples S0048A-G, S0055A-G and S0065A-E).




Asbestos in drywall joint compound was banned in Canada in 1980. Drywall joint compound in the Boiler Room (Location 1083) was installed on or after 2016 and is presumed to contain no asbestos.

#### 4.1.9 Vinyl Sheet Flooring

The following is a summary of vinyl sheet flooring sampled, for a complete list of locations, refer to Appendix V.

Description	Sample Location (Loc #)	Sample Number	Asbestos (Backing / Adhesive)	Photo
Grey, stone pattern	Music Room (Location 1170)	Previous Pinchin Samples S0023A-C	No / No	



Description	Sample Location (Loc #)	Sample Number	Asbestos (Backing / Adhesive)	Photo
Beige, large cubes pattern	Elevator (Location 1) Storage (Location 1261)	Previous Pinchin Samples 0024A-C	Yes	
Grey, blue and red, small stone pattern	Transportation Technology (Location 1250)	Previous Pinchin Samples 0025A-C	No / No	
Beige, large cubes pattern	Classroom (Location 2020)	Previous Pinchin Samples 0031A-C	No / No	
Green, large cubes pattern	Office (Location 2430)	Previous Pinchin Samples 0039A-C	Yes	

Remaining vinyl sheet flooring is presumed to be non-asbestos based on historical knowledge of the type of flooring (linoleum) or based on the lack of a paper backing layer (underpad).

#### 4.1.10 Vinyl Floor Tiles, Baseboard, and Stair Flooring

The following is a summary of vinyl floor tiles sampled, for a complete list of locations, refer to Appendix V.

Description	Sample Location (Location #)	Sample Number	Asbestos (Tile / Adhesive)	Photo
9"x9", white with grey streaks	Office (Location 1989) Classroom (Location 2050)	Previous Pinchin Samples 0014A-C	Yes / No	
9"x9", teal	Classroom (Location 1070) Office (Location 1989) Classroom (Location 2110)	Previous Pinchin Samples 0015A-C	Yes / No	
9"x9", white with multicoloured streaks	Vestibule (Location 1034)	Previous Pinchin Samples 0018A-C	Yes / No (Abated - No Longer Present)	
9"x9", pinkish beige with brown and white streaks	Classroom (Location 1070) Classroom (Location 2030) Classroom (Location 2110)	Previous Pinchin Samples 0019A-C	Yes / No (Abated - No Longer Present)	
9"x9", grey with white streaks	Mechanical Room (Location 1710)	Previous Pinchin Samples 0022A-C	Yes / No	

**Hazardous Building Materials Assessment (Management)**

Thousand Islands Secondary School, 2510 Parkedale Avenue, Brockville, Ontario  
Upper Canada District School Board

September 15, 2023  
Pinchin File: 302783.034  
FINAL

<b>Description</b>	<b>Sample Location (Location #)</b>	<b>Sample Number</b>	<b>Asbestos (Tile / Adhesive)</b>	<b>Photo</b>
9"x9", red with white streaks	Security/Telecom Equip Room (Location 1886)	Previous Pinchin Samples 0027A-C	Yes / No (Abated - No Longer Present)	
12"x12", white with black and grey fleck	Security/Telecom Equip Room (Location 1886)	Previous Pinchin Samples 0028A-C	No / No (No Longer Present)	
9"x9", brown with grey and white streaks	Bood Storage (Locations 2001) Storage (2161) Classroom (Location 2230)	Previous Pinchin Samples 0030A-C	Yes / No (Abated - No Longer Present)	
9"x9", yellow with brown and white streaks	Classroom (Location 2030)	Previous Pinchin Samples 0032A-C	Yes / No (Abated - No Longer Present)	
9"x9", green with white streaks	Classroom (Location 2230) Office (Location 2440) Mechanical Room (Location 2978)	Previous Pinchin Samples 0033A-C	Yes / No (Abated - No Longer Present)	
9"x9", black with white streaks	Classroom (Location 2050)	Previous Pinchin Samples 0034A-C	Yes / No (Abated - No Longer Present)	
9"x9", blue with white streaks	Classroom (Location 2230)	Previous Pinchin Samples 0035A-C	Yes / No (Abated - No Longer Present)	
9"x9", olive with white and grey streaks	Classroom (Location 2250)	Previous Pinchin Samples 0037A-C	Yes / No (Abated - No Longer Present)	
9"x9", white with olive and grey streaks	Classroom (Location 2250)	Previous Pinchin Samples 0038A-C	Yes / No (Abated - No Longer Present)	

Description	Sample Location (Location #)	Sample Number	Asbestos (Tile / Adhesive)	Photo
12"X12", white with brown streaks	Classroom (Location 2270)	Previous Pinchin Samples 0040A-C	Yes / No (Abated - No Longer Present)	
12"X12", brown with white and purple streaks	Classroom (Location 2270)	Previous Pinchin Samples 0041A-C	Yes / No (Abated - No Longer Present)	

Remaining vinyl floor tiles were presumed to be non-asbestos based on historical knowledge of the date of installation (i.e., post 1995).



Mastic associated with the remaining vinyl floor tiles present throughout the building does not contain asbestos (samples S0042A-H, S0051A-C, S0054A-C, S0068A-C).

#### 4.1.11 Sealants, Caulking, and Putty

The following is a summary of sealants, caulking, and putties sampled, for a complete list of locations, refer to Appendix V.

Material, Description and Application	Sample Location (Location #)	Sample Number	Asbestos	Photo
Caulking, grey, door frames	Kitchen (Location 1009) Music Room (Location 1170) Kitchen Prep (Location 3001)	S0044A-C	No	
Caulking, light grey, window frames	Kitchen (Location 1009) Classroom (Location 2090) Classroom (Location 2230)	S0045A-C	No	

Material, Description and Application	Sample Location (Location #)	Sample Number	Asbestos	Photo
Butyl sealant, black, window liners	Kitchen (Location 1009) Music Room (Location 1170) Kitchen Prep (Location 3001)	S0046A-C	No	
Butyl sealant, grey, window liners	Classroom (Location 1020) Welding Technology (Location 1020) Computer Room (Location 2190)	S0058A-C	Yes	
Butyl sealant, grey, window liners	Library (Location 1040) Stairwell (Location 1093) Corridor (Location 2979)	S0066A-C	Yes	
Caulking, white, door frames	Storage (Location 1101) Communication Technology (Location 1192) Woodworking (Location 1240)	S0070A-C	No	
Butyl sealant, black, window liners	Exterior Phase E (Location 3007) Exterior Phase C (Location 3008)	S0076A-C	No	

Material, Description and Application	Sample Location (Location #)	Sample Number	Asbestos	Photo
Caulking, grey, door frames	Exterior Phase E (Location 3007) Exterior Phase C (Location 3008) Exterior Phase D (Location 3009)	S0077A-C	No	
Caulking, hard grey, expansion joints	Exterior Phase E (Location 3007) Exterior Phase D (Location 3009)	S0083A-C	Yes	
Silicone, grey, window frames	Not Sampled	N/A	None based on non-asbestos composition	

#### 4.1.12 Other Building Materials

Paint, containing asbestos, is present on the concrete block walls throughout Building Phase E (samples S0063A-G).

Paint present on concrete block walls throughout Building Phase C Building and Building Phase D does not contain asbestos (samples S0043A-G and S0049A-G).

Paint present on the concrete structure in the Boiler Room (Location 1083) and the exterior concrete canopy of Building Phase D does not contain asbestos (samples S0069A-C and S0082A-C).

#### 4.1.13 Excluded Materials

The following is a list of materials which may contain asbestos and was excluded from the assessment. These materials are presumed to contain asbestos until otherwise proven by sampling and analysis:

- Roofing felts and tar, mastics
- Ceramic tile setting compound
- Elevator and lift brakes

- Electrical components
- Mechanical packing, ropes, and gaskets
- Vermiculite
- Adhesives and duct mastics
- Baseboard adhesives
- Fire resistant doors
- Terrazzo
- Ropes and gaskets in cast-iron bell and spigot joints
- Sealants on pipe threads
- Firestopping sealants
- Materials concealed or outside of the assessed area

## 4.2 Lead

### 4.2.1 Paints and Surface Coatings

Refer to the lab report(s) in Appendix II-B and the Hazardous Material Summary / Sample Log in Appendix V for details on paints sampled and their locations.

The following table summarizes the analytical results for paints sampled contain above 0.009% (90 mg/kg) lead.

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)
L0003	Red, steel structure (Phase C)	Kitchen (Location 1009) Passage (Location 1981)	0.0880
L0006	Red, steel structure (composite) (Phase D)	Storage Under Stair (Location 1963) Stairwell (Location 2980) Kitchen Prep (Location 3001)	0.110
L0007	Beige, plaster (Phase D)	Mechanical Room (Location 1360)	0.0262
L0008	White, plaster (composite) (Phase C)	Kitchen (Location 1001) Girls Change Room (Location 1891) Bood Storage (Location 2001) Pipe Chase (Location 2988)	0.0339





## Hazardous Building Materials Assessment (Management)

Thousand Islands Secondary School, 2510 Parkedale Avenue, Brockville, Ontario  
Upper Canada District School Board

September 15, 2023  
Pinchin File: 302783.034  
FINAL

Sample Number	Colour, Substrate Description	Sample Location	Lead (%)
L0009	Grey and green concrete floor (composite) (Phase C)	Freezer (Location 1003) Custodial Storage (Location 1976) Pipe Chase (Location 2988) Custodial Storage (Location 2990)	0.0369
L0013	Dark grey, plaster (Phase C)	Office (Location 1090)	0.0320
L0015	Red, steel structure (Phase E)	Classroom (Location 2250) Stairwell (Location 2976)	0.330
L0016	White, concrete block (composite) (Phase E)	Corridor (Locations 1097) Welding Technology (1270) Storage (Location 2252)	0.0281
L0017	White, plaster (composite) (Phase E)	Electrical Room (Location 1094) Welding Technology (Location 1270) Classroom (Location 2350)	0.0123
L0022	Off-white, plaster (composite) (Phase D)	Shower (Locations 1971) Computer Room (Location 2190) Classroom (Location 3004)	0.0092
L0025	Green, plaster (Phase D)	Storage (Location 1721)	0.0094
L0028	Grey, concrete floor (Phase D and E)	Mechanical Room (Location 1290) Mechanical Room (Location 1711)	0.111
L0031	White, textured plaster (Phase D)	Exterior Phase D (Location 3009)	0.138
L0033	White, steel structure/canopy (Phase D)	Exterior Phase D (Location 3009)	0.0556

Results above 0.1% (1,000 mg/kg) are considered lead-containing.

Results less than or equal to 0.1% (1,000 mg/kg), but equal to or greater than 0.009% (90 mg/kg), are considered low-level lead paints or surface coatings in accordance with the EACC guideline.

Paint containing less than 0.009% (90 mg/kg) lead is assumed to be insignificant.

### 4.2.2 Lead Products and Applications

Lead-containing batteries are present in emergency lighting and fire control panels.





Lead caulking is present in bell and spigot fittings on cast iron pipes.

#### *4.2.3 Excluded Lead Materials*

Lead is known to be present in several materials which were not assessed or sampled. The following materials, where found, should be presumed to contain lead:

- Electrical components, including wiring connectors, grounding conductors, and solder
- Solder on pipe connections
- Glazing on ceramic tiles

### **4.3 Silica**

Crystalline silica is assumed to be a component of the following materials where present in the building:

- Concrete
- Masonry and mortar
- Ceramic tiles and grout
- Plaster
- Drywall
- Ceiling tiles
- Terrazzo

### **4.4 Mercury**

#### *4.4.1 Lamps*

Mercury vapour is present in fluorescent lamp tubes.

#### *4.4.2 Mercury-Containing Devices*

Thermostats inspected did not contain liquid mercury ampules.

Mercury is present as a liquid in instrumentation in boiler and mechanical rooms.

### **4.5 Polychlorinated Biphenyls**

#### *4.5.1 Caulking and Sealants*

Refer to the Hazardous Material Summary / Sample Log in Appendix V for details on caulking sampled and their locations.

All caulking sampled are considered non-PCB solids based on the threshold (50 mg/kg).

#### 4.5.2 Lighting Ballasts

The building has not been comprehensively re-lamped with energy efficient light fixtures (evidence of T-12 fixtures), and as such, a percentage of light ballasts may be manufactured prior to 1980 and may contain PCBs.

#### 4.5.3 Transformers

All transformers in the building are dry type transformers and do not contain PCB-containing dielectric fluids; however, may contain capacitors, which could not be assessed for PCBs as the equipment was in service.

#### 4.5.4 Excluded PCB Materials

PCBs are known to be present in several materials and equipment which were not assessed or sampled. The following materials, where found, should be presumed to contain PCBs until sampling proves otherwise:

- Applications of caulking or sealants on the roof.

### 4.6 Mould and Water Damage

Visible mould growth and water staining is present on the drywall wall in the Washroom (Location 1012).

Visible water staining is present on acoustic ceiling tiles in the Classroom (Location 2160).



Mould growth and water staining present on the drywall wall in the Washroom (Location 1012).



Water staining present on acoustic ceiling tiles in the Classroom (Location 2160).




## 5.0 RECOMMENDATIONS

### 5.1 General

This report does not provide sufficient detail for most renovation or demolition. Perform a detailed intrusive assessment prior to building renovation or demolition operations. The assessment should include; destructive testing (e.g., coring and/or removal of building finishes and components), and sampling of other materials not previously tested (e.g., roofing materials, caulking, mastics).

### 5.2 Remedial Work

The following remedial work is recommended.






Material, Quantity & Condition	Location	Recommended Procedure	Photo
Parging cement insulation, 5 elbows, poor condition	Location 1022	Remove or repair in accordance with O.Reg.278/05 Type 2 or Glove Bag asbestos abatement procedures	
Parging cement insulation, 1 elbow, poor condition	Location 1091		
Parging cement insulation, 2 square feet, debris			
Parging cement insulation, 1 elbow, poor condition	Location 1097		






# Hazardous Building Materials Assessment (Management)

Thousand Islands Secondary School, 2510 Parkedale Avenue, Brockville, Ontario  
Upper Canada District School Board

September 15, 2023  
Pinchin File: 302783.034  
FINAL

Material, Quantity & Condition	Location	Recommended Procedure	Photo
Parging cement insulation, 1 joint, poor condition	Location 1115		
Parging cement insulation, 1 end, poor condition			
Parging cement insulation, 1 elbow, poor condition	Location 1885		
Parging cement insulation, 3 elbows, poor condition	Location 1978		
Parging cement insulation, 1 tee, poor condition			

Material, Quantity & Condition	Location	Recommended Procedure	Photo
Caposite insulation, 2 linear feet, poor condition	Location 1983		
Caposite insulation, 2 square feet, debris			
Parging cement insulation, 2 elbows, poor condition			
Drywall wall, 6 square feet, mould growth	Location 1012	Remove following EACC Level 2 Mould Abatement Procedures	

### 5.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the hazardous materials identified.

#### 5.3.1 Asbestos

Prepare an Asbestos Management Program (AMP). The AMP should address and document: written work practices, worker training, notifications, policies and responsibilities.



Perform a reassessment of asbestos-containing materials (ACM) on an annual basis.

Remove ACM prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.

Asbestos-containing materials must be disposed of at a landfill approved to accept asbestos waste.

Update the asbestos inventory upon completion of the abatement and removal of asbestos-containing materials and any other relevant findings.

#### **5.3.2 Lead**

For lead-containing paints (i.e., greater than the EACC guideline of 0.1% (1,000 mg/kg)), construction disturbance may result in over-exposure to lead dust or fumes. The need for work procedures, engineering controls and personal protective equipment should be assessed on a site-specific basis to comply with Ministry of Labour, Training and Skills Development regulations, and guidelines.

For paints identified as having low levels of lead (i.e., equal to or above 0.009% (90 mg/kg) but less than or equal to the EACC guideline of 0.1% (1,000 mg/kg) for lead-containing paints) special precautions are not recommended unless aggressive disturbance (grinding, blasting, torching) is planned. Exposure from construction disturbance of paints containing lead less than 0.009% (90 mg/kg) is assumed to be insignificant.

Items painted with paints containing elevated levels of lead may be a hazardous waste. Test lead-painted materials for leachable lead and other metals prior to disposal. Metallic components coated with lead paint do not require leachate testing and can be disposed of as non-hazardous construction and demolition (C&D) waste.

Lead-containing items should be recycled when taken out of service.

#### **5.3.3 Silica**

Disturbance of silica-containing products during maintenance activities may result in excessive exposures to airborne silica, especially if performed indoors and dry. Cutting, grinding, drilling or demolition of materials containing silica should be completed only with proper respiratory protection and other worker safety precautions that comply with applicable regulations and guidelines.

#### **5.3.4 Mercury**

Do not break lamps or separate liquid mercury from components. Recycle and reclaim mercury from fluorescent lamps and instrumentation when taken out of service. Mercury is classified as a hazardous waste and must be disposed of in accordance with applicable regulations.





#### 5.3.5 PCBs

When light fixtures are removed from service, examine light ballasts for PCB content. If ballasts are not clearly labelled as “non-PCB”, or are suspected to contain PCBs; package and ship ballasts for destruction at a federally permitted facility. All ballasts that contain PCBs must be removed from service and disposed of by December 31, 2025.

#### 5.3.6 Mould

Conduct an intrusive mould investigation to determine the extent of mould growth. The investigation should identify the source of the water intrusion that contributed to the mould growth and water damage observed during this assessment.

### 6.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

### 7.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.
3. Lead on Construction Projects, Ministry of Labour Guidance Document.
4. The Environmental Abatement Council of Canada (EACC) Lead Guideline for Construction, Renovation, Maintenance or Repair.
5. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 347 as amended.
6. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 362 as amended.
7. Silica on Construction Projects, Ministry of Labour Guidance Document.
8. Alert – Mould in Workplace Buildings, Ontario Ministry of Labour.



## **Hazardous Building Materials Assessment (Management)**

Thousand Islands Secondary School, 2510 Parkedale Avenue, Brockville, Ontario  
Upper Canada District School Board

September 15, 2023  
Pinchin File: 302783.034  
FINAL

9. PCB Regulations, SOR/2008-273, Canadian Environmental Protection Act.
10. Surface Coating Materials Regulations, SOR/2016-193, Canada Consumer Product Safety Act.

\\pinchin.com\kgn\Job\302000s\0302783.000 UCDSB, various, HAZ, Reasmt\0302783.034 UCDSB, Thousand Islands SS, HAZ, ReAsmt\Deliverables\302783.034 HBMA TISS  
2510 Parkedale Ave Brockville ON UCDSB.docx

Template: Master Report for Hazardous Materials Assessment Report (Management), HAZ, October 31, 2022



**APPENDIX I**  
**Drawings**





LEGEND

- ASBESTOS BULK SAMPLE
- LEAD BULK SAMPLE
- PCB BULK SAMPLE
- PINCHIN LOCATION NUMBER
- NAR NO ACCESS TO ROOM/AREA

IDENTIFIED MOULD GROWTH

ASBESTOS-CONTAINING MATERIALS:

- THERMAL SYSTEM INSULATION
- VINYL FLOOR TILES
- ACOUSTIC CEILING TILES
- VINYL SHEET FLOORING
- PLASTER

FOR CLARITY, THE FOLLOWING ASBESTOS-CONTAINING MATERIALS, ARE PRESENT IN THE ASSESSED AREA, BUT HAVE NOT BEEN HATCHED ON THE DRAWING:

- BUTYL SEALANT ON WINDOWS THROUGHOUT THE BUILDING
- PAINT PRESENT ON CONCRETE BLOCK WALLS THROUGHOUT THE 1967 ADDITION
- HARD GREY CAULKING PRESENT ON EXPANSION JOINTS THROUGHOUT THE EXTERIOR OF THE BUILDING.

NOT ALL KNOWN OR SUSPECTED HAZARDOUS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



PROJECT NAME:  
HAZARDOUS BUILDING MATERIALS ASSESSMENT

CLIENT NAME:  
UPPER CANADA DISTRICT SCHOOL BOARD

PROJECT LOCATION:  
THOUSAND ISLANDS SS  
2510 PARKEDALE AVENUE  
BROCKVILLE, ONTARIO

FIGURE NAME:  
SECOND FLOOR PLAN

PROJECT NUMBER:  
302783.034


SCALE:  
NOT TO SCALE

DRAWN BY:  
KV

REVIEWED BY:  
SY

DATE:  
AUGUST 2023

FIGURE NUMBER:  
2 OF 2



**APPENDIX II-A**  
**Asbestos Analytical Certificates**



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0001A - A	Plaster - Location 1081, Custodian Office	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_1	finish				Crushed
0001A - B	Plaster - Location 1081, Custodian Office	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1117705PLM_132	base				Crushed
0001B - A	Plaster - Location 1980, Corridor	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_2	finish small sample				Crushed
0001B - B	Plaster - Location 1980, Corridor	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1117705PLM_133	base				Crushed
0001C - A	Plaster - Location 1973, Corridor	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_3	finish				Crushed
0001C - B	Plaster - Location 1973, Corridor	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1117705PLM_134	base small sample				Crushed
0001D - A	Plaster - Location 1270, Classroom	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_4	finish				Crushed
0001D - B	Plaster - Location 1270, Classroom	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1117705PLM_135	base				Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0001E - A	Plaster - Location 2001, Storage	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_5	finish				Crushed
0001E - B	Plaster - Location 2001, Storage	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1117705PLM_136	base				Crushed
0001F - A	Plaster - Location 2991, Corridor	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_6	finish				Crushed
0001F - B	Plaster - Location 2991, Corridor	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1117705PLM_137	base				Crushed
0001G - A	Plaster - Location 2979, Corridor	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_7	finish				Crushed
0001G - B	Plaster - Location 2979, Corridor	None Detected	2% Cellulose	98% Other	Gray Non Fibrous Heterogeneous
1117705PLM_138	base				Crushed
0002A	Drywall Joint Compound - Location 1031 Staff Lounge	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_8					Crushed
0002B	Drywall Joint Compound - Location 1000 Classroom	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_9					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Project:** 71528

**Date Reported:** 12/20/2011

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0002C	Drywall Joint Compound - Location 1200 Photography	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_10					Crushed
0002D	Drywall Joint Compound - Location 1270 Classroom	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_11					Crushed
0002E	Drywall Joint Compound - Location 2020 Classroom	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_12					Crushed
0002F	Drywall Joint Compound - Location 2120 Office	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_13					Crushed
0002G	Drywall Joint Compound - Location 2420 Workroom	None Detected		100% Other	White Non Fibrous Homogeneous
1117705PLM_14					Crushed
0003A - A	Sweatwrap/Aircell Debris - Location 1973 Corridor	None Detected	95% Cellulose	5% Other	Tan Non Fibrous Homogeneous
1117705PLM_15	tan layer				Teased
0003A - B	Sweatwrap/Aircell Debris - Location 1973 Corridor	None Detected	70% Cellulose	30% Other	Black Non Fibrous Homogeneous
1117705PLM_139	black layer				Dissolved
0003B - A	Sweatwrap/Aircell Debris - Location 1973 Corridor	None Detected	95% Cellulose	5% Other	Tan Non Fibrous Homogeneous
1117705PLM_16	tan layer				Teased

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0003B - B	Sweatwrap/Aircell Debris - Location 1973 Corridor	None Detected	70% Cellulose	30% Other	Black Non Fibrous Homogeneous
1117705PLM_140	black layer				Dissolved
0003C - A	Sweatwrap/Aircell Debris - Location 1973 Corridor	None Detected	95% Cellulose	5% Other	Tan Non Fibrous Homogeneous
1117705PLM_17	tan layer				Teased
0003C - B	Sweatwrap/Aircell Debris - Location 1973 Corridor	None Detected	70% Cellulose	30% Other	Black Non Fibrous Homogeneous
1117705PLM_141	black layer				Dissolved
0004A	AT-3 1x1 Mechanically Fastened Ceiling Tiles, Large and medium uniform holes	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_18					Teased
0004B	AT-3 1x1 Mechanically Fastened Ceiling Tiles, Large and medium uniform holes	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_19					Teased
0004C	AT-3 1x1 Mechanically Fastened Ceiling Tiles, Large and medium uniform holes	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_20					Teased
0005A - A	Sweatwrap Pipe Insulation - Location 1081 Custodian Office	None Detected	95% Cellulose	5% Other	Tan Non Fibrous Homogeneous
1117705PLM_21	tan layer				Teased
0005A - B	Sweatwrap Pipe Insulation - Location 1081 Custodian Office	None Detected	70% Cellulose	30% Other	Black Non Fibrous Homogeneous
1117705PLM_142	black layer				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0005B - A	Sweatwrap Pipe Insulation - Location 1092 Storage Under Stairs	None Detected	95% Cellulose	5% Other	Tan Non Fibrous Homogeneous
1117705PLM_22	tan layer				Teased
0005B - B	Sweatwrap Pipe Insulation - Location 1092 Storage Under Stairs	None Detected	70% Cellulose	30% Other	Black Non Fibrous Homogeneous
1117705PLM_143	black layer				Dissolved
0005C - A	Sweatwrap Pipe Insulation - Location 1892 Pipe Chase	None Detected	95% Cellulose	5% Other	Tan Non Fibrous Homogeneous
1117705PLM_23	tan layer				Teased
0005C - B	Sweatwrap Pipe Insulation - Location 1892 Pipe Chase	None Detected	70% Cellulose	30% Other	Black Non Fibrous Homogeneous
1117705PLM_144	black layer				Dissolved
0006A	Parging Cement Pipe Fitting Insulation - Location 1081 Custodian Office	10% Chrysotile		90% Other	Gray Non Fibrous Homogeneous
1117705PLM_24					Crushed
0006B	Parging Cement Pipe Fitting Insulation - Location 1092 Storage Under Stairs	Not Analyzed			
1117705PLM_25					
0006C	Parging Cement Pipe Fitting Insulation - Location 1975 Corridor	Not Analyzed			
1117705PLM_26					
0007A	Caposite Boiler Exhaust Duct Insulation - Location 1083 Boiler Room	25% Amosite		75% Other	Gray Non Fibrous Homogeneous
1117705PLM_27					Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0007B	Caposite Boiler Exhaust Duct Insulation - Location 1083 Boiler Room	Not Analyzed			
1117705PLM_28					
0007C	Caposite Boiler Exhaust Duct Insulation - Location 1083 Boiler Room	Not Analyzed			
1117705PLM_29					
0008A	Preformed Block Boiler Exhaust Duct Elbow Insulation - Location 1083	15% Chrysotile		85% Other	Gray Non Fibrous Homogeneous
1117705PLM_30	unable to separate wrap				Crushed
0008B	Preformed Block Boiler Exhaust Duct Elbow Insulation - Location 1083	Not Analyzed			
1117705PLM_31					
0008C	Preformed Block Boiler Exhaust Duct Elbow Insulation - Location 1083	Not Analyzed			
1117705PLM_32					
0009A	AT-4 1x1 Glued on Ceiling Tile, Large and Medium Random holes - Location	None Detected	95% Fiber Glass	5% Other	White Non Fibrous Homogeneous
1117705PLM_33					Teased
0009B	AT-4 1x1 Glued on Ceiling Tile, Large and Medium Random holes - Location	None Detected	95% Fiber Glass	5% Other	White Non Fibrous Homogeneous
1117705PLM_34					Teased
0009C	AT-4 1x1 Glued on Ceiling Tile, Large and Medium Random holes - Location	None Detected	95% Fiber Glass	5% Other	White Non Fibrous Homogeneous
1117705PLM_35					Teased

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0010A	Ceiling Tile Glue - Location 1031 Staff Room	None Detected		100% Other	Brown Non Fibrous Homogeneous
1117705PLM_36					Dissolved
0010B	Ceiling Tile Glue - Location 1007 Cafeteria	None Detected		100% Other	Brown Non Fibrous Homogeneous
1117705PLM_37					Dissolved
0010C	Ceiling Tile Glue - Location 1031 Staff Room	None Detected		100% Other	Brown Non Fibrous Homogeneous
1117705PLM_38					Dissolved
0011A	AT-6 2x4 Dropped Lay in Ceiling Tile with Textured Surface and Pinholes -	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_39					Teased
0011B	AT-6 2x4 Dropped Lay in Ceiling Tile with Textured Surface and Pinholes -	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_40					Teased
0011C	AT-6 2x4 Dropped Lay in Ceiling Tile with Textured Surface and Pinholes -	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_41					Teased
0012A	AT-7 2x4 Lay In Ceiling Tile with Fine Textured Surface - Location 1091 Corridor	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_42					Teased
0012B	AT-7 2x4 Lay In Ceiling Tile with Fine Textured Surface - Location 1091 Corridor	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_43					Teased

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0012C	AT-7 2x4 Lay In Ceiling Tile with Fine Textured Surface - Location 1091 Corridor	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_44					Teased
0013A	AT-9 2x4 Lay In Ceiling Tile, Lengthwise Deep Wide Fissures and Pinholes with	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_45					Teased
0013B	AT-9 2x4 Lay In Ceiling Tile, Lengthwise Deep Wide Fissures and Pinholes with	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_46					Teased
0013C	AT-9 2x4 Lay In Ceiling Tile, Lengthwise Deep Wide Fissures and Pinholes with	None Detected	40% Cellulose 40% Fiber Glass	20% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_47					Teased
0014A - A	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 1989 Office	3% Chrysotile		97% Other	White Non Fibrous Homogeneous
1117705PLM_48	tile				Dissolved
0014A - B	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 1989 Office	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_145	mastic				Dissolved
0014B - A	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 2050 Classroom	Not Analyzed			
1117705PLM_49	tile				
0014B - B	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 2050 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_146	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0014C - A	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 2050 Classroom	Not Analyzed			
1117705PLM_50	tile				
0014C - B	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 2050 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_147	mastic				Dissolved
0015A - A	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 1989 Office	5% Chrysotile		95% Other	Green Non Fibrous Homogeneous
1117705PLM_51	tile				Dissolved
0015A - B	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 1989 Office	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_148	mastic				Dissolved
0015B - A	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 1070	Not Analyzed			
1117705PLM_52	tile				
0015B - B	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 1070	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_149	mastic				Dissolved
0015C - A	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 2110	Not Analyzed			
1117705PLM_53	tile				
0015C - B	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 2110	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_150	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0016A	AT-10 1x1 Splined Ceiling Tiles with Fissures and Pinholes - Location 1010	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_54					Teased
0016B	AT-10 1x1 Splined Ceiling Tiles with Fissures and Pinholes - Location 1010	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_55					Teased
0016C	AT-10 1x1 Splined Ceiling Tiles with Fissures and Pinholes - Location 1010	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_56					Teased
0017A	AT-12 1x1 Splined Ceiling Tiles with Smooth Textured Surface - Location 1982	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_57					Teased
0017B	AT-12 1x1 Splined Ceiling Tiles with Smooth Textured Surface - Location 1982	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_58					Teased
0017C	AT-12 1x1 Splined Ceiling Tiles with Smooth Textured Surface - Location 1982	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_59					Teased
0018A - A	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034	5% Chrysotile		95% Other	White Non Fibrous Homogeneous
1117705PLM_60	tile				Dissolved
0018A - B	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_151	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0018B - A	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034	Not Analyzed			
1117705PLM_61	tile				
0018B - B	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_152	mastic				Dissolved
0018C - A	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034	Not Analyzed			
1117705PLM_62	tile				
0018C - B	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_153	mastic				Dissolved
0019A - A	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location	3% Chrysotile		97% Other	Beige Non Fibrous Homogeneous
1117705PLM_63	tile				Dissolved
0019A - B	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_154	mastic				Dissolved
0019B - A	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location	Not Analyzed			
1117705PLM_64	tile				
0019B - B	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_155	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0019C - A	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location	Not Analyzed			
1117705PLM_65	tile				
0019C - B	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_156	mastic				Dissolved
0020A	AT-13 1x1 Splined Ceiling Tiles with coarse texture and fissures - Location 1970 Gym	None Detected	95% Fiber Glass	5% Other	White Non Fibrous Homogeneous
1117705PLM_66					Teased
0020B	AT-13 1x1 Splined Ceiling Tiles with coarse texture and fissures - Location 1111	None Detected	95% Fiber Glass	5% Other	White Non Fibrous Homogeneous
1117705PLM_67					Teased
0020C	AT-13 1x1 Splined Ceiling Tiles with coarse texture and fissures - Location 1970 Gym	None Detected	95% Fiber Glass	5% Other	White Non Fibrous Homogeneous
1117705PLM_68					Teased
0021A	AT-15 1x1 Splined Ceiling Tiles with Smooth Surface - Location 1110 Classroom	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_69					Teased
0021B	AT-15 1x1 Splined Ceiling Tiles with Smooth Surface - Location 2180 Classroom	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_70					Teased
0021C	AT-15 1x1 Splined Ceiling Tiles with Smooth Surface - Location 1110 Classroom	None Detected	95% Cellulose	5% Other	Brown, White Non Fibrous Homogeneous
1117705PLM_71					Teased

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0022A - A	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical	3% Chrysotile		97% Other	Gray Non Fibrous Homogeneous
1117705PLM_72	tile				Dissolved
0022A - B	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_157	mastic				Dissolved
0022B - A	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical	Not Analyzed			
1117705PLM_73	tile				
0022B - B	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_158	mastic				Dissolved
0022C - A	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical	Not Analyzed			
1117705PLM_74	tile				
0022C - B	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_159	mastic				Dissolved
0023A - A	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music	None Detected	15% Cellulose 10% Fiber Glass	75% Other	Gray Non Fibrous Homogeneous
1117705PLM_75	vinyl				Teased
0023A - B	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_160	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0023B - A	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music	None Detected	15% Cellulose 10% Fiber Glass	75% Other	Gray Non Fibrous Homogeneous
1117705PLM_76	vinyl				Teased
0023B - B	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_161	mastic				Dissolved
0023C - A	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music	None Detected	15% Cellulose 10% Fiber Glass	75% Other	Gray Non Fibrous Homogeneous
1117705PLM_77	vinyl				Teased
0023C - B	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_162	mastic				Dissolved
0024A	VSF-2 Brown Vinyl Sheet Flooring, Large Cubes - Location 1261 Office	15% Chrysotile	10% Cellulose	75% Other	Brown Non Fibrous Homogeneous
1117705PLM_78	unable to separate mastic				Teased
0024B	VSF-2 Brown Vinyl Sheet Flooring, Large Cubes - Location 1 Elevator	Not Analyzed			
1117705PLM_79					
0024C	VSF-2 Brown Vinyl Sheet Flooring, Large Cubes - Location 1261 Office	Not Analyzed			
1117705PLM_80					
0025A - A	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location	None Detected	15% Cellulose 10% Synthetic Fibers	75% Other	Gray Non Fibrous Homogeneous
1117705PLM_81	vinyl				Teased

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0025A - B	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_163	mastic				Dissolved
0025B - A	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location	None Detected	15% Cellulose 10% Synthetic Fibers	75% Other	Gray Non Fibrous Homogeneous
1117705PLM_82	vinyl				Teased
0025B - B	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_164	mastic				Dissolved
0025C - A	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location	None Detected	15% Cellulose 10% Synthetic Fibers	75% Other	Gray Non Fibrous Homogeneous
1117705PLM_83	vinyl				Teased
0025C - B	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_165	mastic				Dissolved
0026A	Aircell Pipe Insulation - 1892 Pipe Chase	20% Chrysotile	60% Cellulose	20% Other	White Non Fibrous Homogeneous
1117705PLM_84					Teased
0026B	Aircell Pipe Insulation - 1892 Pipe Chase	Not Analyzed			
1117705PLM_85					
0026C	Aircell Pipe Insulation - 1892 Pipe Chase	Not Analyzed			
1117705PLM_86					

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0027A - A	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886	3% Chrysotile		97% Other	Red Non Fibrous Homogeneous
1117705PLM_87	tile				Dissolved
0027A - B	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_166	mastic				Dissolved
0027B - A	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886	Not Analyzed			
1117705PLM_88	tile				
0027B - B	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_167	mastic				Dissolved
0027C - A	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886	Not Analyzed			
1117705PLM_89	tile				
0027C - B	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_168	mastic				Dissolved
0028A - A	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886	None Detected		100% Other	Gray Non Fibrous Homogeneous
1117705PLM_90	tile				Dissolved
0028A - B	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_169	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0028B - A	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886	None Detected		100% Other	Gray Non Fibrous Homogeneous
1117705PLM_91	tile				Dissolved
0028B - B	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_170	mastic				Dissolved
0028C - A	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886	None Detected		100% Other	Gray Non Fibrous Homogeneous
1117705PLM_92	tile				Dissolved
0028C - B	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_171	mastic				Dissolved
0029A	AT-16 1x1 Splined Ceiling Tiles with Smooth Fissures - Location 2996 Corridor	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_93					Teased
0029B	AT-16 1x1 Splined Ceiling Tiles with Smooth Fissures - Location 2996 Corridor	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_94					Teased
0029C	AT-16 1x1 Splined Ceiling Tiles with Smooth Fissures - Location 2996 Corridor	None Detected	40% Cellulose 40% Fiber Glass	20% Other	White Non Fibrous Homogeneous
1117705PLM_95					Teased
0030A - A	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location	3% Chrysotile		97% Other	Brown Non Fibrous Homogeneous
1117705PLM_96	tile				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0030A - B	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_172	mastic				Dissolved
0030B - A	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location	Not Analyzed			
1117705PLM_97	tile				
0030B - B	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_173	mastic				Dissolved
0030C - A	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location	Not Analyzed			
1117705PLM_98	tile				
0030C - B	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_174	mastic				Dissolved
0031A - A	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom	None Detected	15% Cellulose 10% Fiber Glass 5% Synthetic Fibers	70% Other	Beige Non Fibrous Homogeneous
1117705PLM_99	vinyl				Dissolved
0031A - B	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_175	mastic				Dissolved
0031B - A	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom	None Detected	15% Cellulose 10% Fiber Glass 5% Synthetic Fibers	70% Other	Beige Non Fibrous Homogeneous
1117705PLM_100	vinyl				Teased

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0031B - B	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_176	mastic				Dissolved
0031C - A	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom	None Detected	15% Cellulose 10% Fiber Glass 5% Synthetic Fibers	70% Other	Beige Non Fibrous Homogeneous
1117705PLM_101	vinyl				Teased
0031C - B	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom	None Detected		100% Other	Yellow Non Fibrous Homogeneous
1117705PLM_177	mastic				Dissolved
0032A - A	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location	3% Chrysotile		97% Other	Yellow Non Fibrous Homogeneous
1117705PLM_102	tile				Dissolved
0032A - B	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_178	mastic				Dissolved
0032B - A	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location	Not Analyzed			
1117705PLM_103	tile				
0032B - B	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_179	mastic				Dissolved
0032C - A	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location	Not Analyzed			
1117705PLM_104	tile				

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0032C - B	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_180	mastic				Dissolved
0033A - A	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	3% Chrysotile		97% Other	Green Non Fibrous Homogeneous
1117705PLM_105	tile				Dissolved
0033A - B	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_181	mastic				Dissolved
0033B - A	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2978 Mechanical	Not Analyzed			
1117705PLM_106	tile				
0033B - B	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2978 Mechanical	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_182	mastic				Dissolved
0033C - A	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2440 Office	Not Analyzed			
1117705PLM_107	tile				
0033C - B	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2440 Office	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_183	mastic				Dissolved
0034A - A	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom	3% Chrysotile		97% Other	Black Non Fibrous Homogeneous
1117705PLM_108	tile				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0034A - B	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_184	mastic				Dissolved
0034B - A	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom	Not Analyzed			
1117705PLM_109	tile				
0034B - B	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_185	mastic				Dissolved
0034C - A	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom	Not Analyzed			
1117705PLM_110	tile				
0034C - B	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_186	mastic				Dissolved
0035A - A	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	3% Chrysotile		97% Other	Blue Non Fibrous Homogeneous
1117705PLM_111	tile				Dissolved
0035A - B	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_187	mastic				Dissolved
0035B - A	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	Not Analyzed			
1117705PLM_112	tile				

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0035B - B	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_188	mastic				Dissolved
0035C - A	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	Not Analyzed			
1117705PLM_113	tile				
0035C - B	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_189	mastic				Dissolved
0036A	AT-17 2x4 Lay-in Ceiling Tiles with Textured Surface and Pinholes - Location 2250	3% Amosite	95% Fiber Glass	2% Other	White Non Fibrous Homogeneous
1117705PLM_114					Teased
0036B	AT-17 2x4 Lay-in Ceiling Tiles with Textured Surface and Pinholes - Location 2250	Not Analyzed			
1117705PLM_115					
0036C	AT-17 2x4 Lay-in Ceiling Tiles with Textured Surface and Pinholes - Location 2250	Not Analyzed			
1117705PLM_116					
0037A - A	VT-24 9x9 Olive with White and Grey Streaks - Location 2250 Classroom	3% Chrysotile		97% Other	Olive Non Fibrous Homogeneous
1117705PLM_117	tile				Dissolved
0037A - B	VT-24 9x9 Olive with White and Grey Streaks - Location 2250 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_190	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0037B - A	VT-24 9x9 Olive with White and Grey Streaks - Location 2250 Classroom	Not Analyzed			
1117705PLM_118	tile				
0037B - B	VT-24 9x9 Olive with White and Grey Streaks - Location 2250 Classroom	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_191	mastic				Dissolved
0037C - A	VT-24 9x9 Olive Vinyl Floor Tiles with White and Grey Streaks - Location 2250	Not Analyzed			
1117705PLM_119	tile				
0037C - B	VT-24 9x9 Olive Vinyl Floor Tiles with White and Grey Streaks - Location 2250	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_192	mastic				Dissolved
0038A - A	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250	3% Chrysotile		97% Other	White Non Fibrous Homogeneous
1117705PLM_120	tile				Dissolved
0038A - B	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_193	mastic				Dissolved
0038B - A	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250	Not Analyzed			
1117705PLM_121	tile				
0038B - B	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_194	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)


Analyst

Nathaniel Durham, MS or Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0038C - A	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250	Not Analyzed			
1117705PLM_122	tile				
0038C - B	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_195	mastic				Dissolved
0039A	VSF-5 Green Vinyl Sheet Flooring, Large Cubes - Location 2430 Office	15% Chrysotile	10% Cellulose	75% Other	Green Non Fibrous Homogeneous
1117705PLM_123	unable to separate mastic				Teased
0039B	VSF-5 Green Vinyl Sheet Flooring, Large Cubes - Location 2430 Office	Not Analyzed			
1117705PLM_124					
0039C	VSF-5 Green Vinyl Sheet Flooring, Large Cubes - Location 2430 Office	Not Analyzed			
1117705PLM_125					
0040A - A	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270	3% Chrysotile		97% Other	White Non Fibrous Homogeneous
1117705PLM_126	tile				Dissolved
0040A - B	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_196	mastic				Dissolved
0040B - A	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270	Not Analyzed			
1117705PLM_127	tile				

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0040B - B	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_197	mastic				Dissolved
0040C - A	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270	Not Analyzed			
1117705PLM_128	tile				
0040C - B	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_198	mastic				Dissolved
0041A - A	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location	3% Chrysotile		97% Other	Brown Non Fibrous Homogeneous
1117705PLM_129	tile				Dissolved
0041A - B	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_199	mastic				Dissolved
0041B - A	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location	Not Analyzed			
1117705PLM_130	tile				
0041B - B	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_200	mastic				Dissolved
0041C - A	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location	Not Analyzed			
1117705PLM_131	tile				

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 600/M4-82-020



**Customer:** Pinchin Environmental Ltd  
135 Ontario Street, Unit 1  
Kingston, ON K7L 0A5

**Attn:** Sarah Young

**Lab Order ID:** 1117705

**Analysis ID:** 1117705PLM

**Date Received:** 12/14/2011

**Date Reported:** 12/20/2011

**Project:** 71528

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
0041C - B	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location	None Detected		100% Other	Black Non Fibrous Homogeneous
1117705PLM_201	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Bart Huber (201)

Analyst

Nathaniel Durham, MS or Approved Signatory



1117705

Professional Engineers  
Ontario**Pinchin Environmental Ltd. - Asbestos Laboratory  
Internal Asbestos Bulk Sample Chain of Custody**

<b>Client Name:</b>	Upper Canada District School Board	<b>Project Address:</b>	2510 Parkdale Avenue, Brockville, Ontario
<b>Portfolio/Building No:</b>	Thousand Islands Secondary School	<b>Pinchin File:</b>	71528
<b>Submitted by:</b>	Sarah Young	<b>Email:</b>	syoung@pinchin.com
<b>CC Results to:</b>		<b>CC Email:</b>	
<b>Date Submitted:</b>	December 7 2011	<b>Required by:</b>	December 16 2011
<b># of Samples:</b>	131	<b>Priority:</b>	Regular Turnaround
<b>Year of Building Construction:</b>	1960		
<b>Do NOT Stop on Positive (Sample Numbers):</b>			

**To be Completed by Lab Personnel Only:**

<b>Lab Reference #:</b>		<b>Time:</b>	24 hour clock		
<b>Received by:</b>		<b>Date:</b>	Month	Day	Year
<b>Name(s) of Analyst(s):</b>					

Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0001	A	Plaster - Location 1081, Custodian Office
	0001	B	Plaster - Location 1980, Corridor
	0001	C	Plaster - Location 1973, Corridor
	0001	D	Plaster - Location 1270, Classroom
	0001	E	Plaster - Location 2001, Storage
	0001	F	Plaster - Location 2991, Corridor
	0001	G	Plaster - Location 2979, Corridor
	0002	A	Drywall Joint Compound - Location 1031 Staff Lounge

Accepted ☒Rejected ☐12-14  
9:30A



1117705



Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0002	B	Drywall Joint Compound - Location 1000 Classroom
	0002	C	Drywall Joint Compound - Location 1200 Photography
	0002	D	Drywall Joint Compound - Location 1270 Classroom
	0002	E	Drywall Joint Compound - Location 2020 Classroom
	0002	F	Drywall Joint Compound - Location 2120 Office
	0002	G	Drywall Joint Compound - Location 2420 Workroom
	0003	A	Sweatwrap/Aircell Debris - Location 1973 Corridor
	0003	B	Sweatwrap/Aircell Debris - Location 1973 Corridor
	0003	C	Sweatwrap/Aircell Debris - Location 1973 Corridor
	0004	A	AT-3 1x1 Mechanically Fastened Ceiling Tiles, Large and medium uniform holes - Location 1530 Classroom
	0004	B	AT-3 1x1 Mechanically Fastened Ceiling Tiles, Large and medium uniform holes - Location 1000 Classroom
	0004	C	AT-3 1x1 Mechanically Fastened Ceiling Tiles, Large and medium uniform holes - Location 2180 Classroom
	0005	A	Sweatwrap Pipe Insulation - Location 1081 Custodian Office
	0005	B	Sweatwrap Pipe Insulation - Location 1092 Storage Under Stairs
	0005	C	Sweatwrap Pipe Insulation - Location 1892 Pipe Chase
	0006	A	Parging Cement Pipe Fitting Insulation - Location 1081 Custodian Office



1117705



Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0006	B	Parging Cement Pipe Fitting Insulation - Location 1092 Storage Under Stairs
	0006	C	Parging Cement Pipe Fitting Insulation - Location 1975 Corridor
	0007	A	Caposite Boiler Exhaust Duct Insulation - Location 1083 Boiler Room
	0007	B	Caposite Boiler Exhaust Duct Insulation - Location 1083 Boiler Room
	0007	C	Caposite Boiler Exhaust Duct Insulation - Location 1083 Boiler Room
	0008	A	Preformed Block Boiler Exhaust Duct Elbow Insulation - Location 1083 Boiler Room
	0008	B	Preformed Block Boiler Exhaust Duct Elbow Insulation - Location 1083 Boiler Room
	0008	C	Preformed Block Boiler Exhaust Duct Elbow Insulation - Location 1083 Boiler Room
	0009	A	AT-4 1x1 Glued on Ceiling Tile, Large and Medium Random holes - Location 1031 Staff Room
	0009	B	AT-4 1x1 Glued on Ceiling Tile, Large and Medium Random holes - Location 1031 Staff Room
	0009	C	AT-4 1x1 Glued on Ceiling Tile, Large and Medium Random holes - Location 1031 Staff Room
	0010	A	Ceiling Tile Glue - Location 1031 Staff Room
	0010	B	Ceiling Tile Glue - Location 1007 Cafeteria
	0010	C	Ceiling Tile Glue - Location 1031 Staff Room
	0011	A	AT-6 2x4 Dropped Lay in Ceiling Tile with Textured Surface and Pinholes - Location 1511 - Library
	0011	B	AT-6 2x4 Dropped Lay in Ceiling Tile with Textured Surface and Pinholes - Location 1511 - Library



1117705




Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0011	C	AT-6 2x4 Dropped Lay in Ceiling Tile with Textured Surface and Pinholes - Location 1511 - Library
	0012	A	AT-7 2x4 Lay In Ceiling Tile with Fine Textured Surface - Location 1091 Corridor
	0012	B	AT-7 2x4 Lay In Ceiling Tile with Fine Textured Surface - Location 1091 Corridor
	0012	C	AT-7 2x4 Lay In Ceiling Tile with Fine Textured Surface - Location 1091 Corridor
	0013	A	AT-9 2x4 Lay In Ceiling Tile, Lenghtwise Deep Wide Fissures and Pinholes with Pink Backing - Location 1998 Washroom
	0013	B	AT-9 2x4 Lay In Ceiling Tile, Lenghtwise Deep Wide Fissures and Pinholes with Pink Backing - Location 1998 Washroom
	0013	C	AT-9 2x4 Lay In Ceiling Tile, Lenghtwise Deep Wide Fissures and Pinholes with Pink Backing - Location 1998 Washroom
	0014	A	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 1989 Office
	0014	B	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 2050 Classroom
	0014	C	VT-7 9x9 White Vinyl Floor Tiles with Grey Streaks - Location 2050 Classroom
	0015	A	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 1989 Office
	0015	B	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 1070 Classroom
	0015	C	VT-8 9x9 Teal Vinyl Floor Tiles with Grey and White Streaks - Location 2110 Classroom
	0016	A	AT-10 1x1 Splined Ceiling Tiles with Fissures and Pinholes - Location 1010 Classroom
	0016	B	AT-10 1x1 Splined Ceiling Tiles with Fissures and Pinholes - Location 1010 Classroom
	0016	C	AT-10 1x1 Splined Ceiling Tiles with Fissures and Pinholes - Location 1010 Classroom

Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0017	A	AT-12 1x1 Splined Ceiling Tiles with Smooth Textured Surface - Location 1982 Vestibule
	0017	B	AT-12 1x1 Splined Ceiling Tiles with Smooth Textured Surface - Location 1982 Vestibule
	0017	C	AT-12 1x1 Splined Ceiling Tiles with Smooth Textured Surface - Location 1982 Vestibule
	0018	A	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034 Vestibule
	0018	B	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034 Vestibule
	0018	C	VT-13 9x9 White Vinyl Floor Tiles with Multicoloured Streaks - Location 1034 Vestibule
	0019	A	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location 1070 Classroom
	0019	B	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location 2030 Classroom
	0019	C	VT-14 9x9 Pinkish beige Vinyl Floor Tiles with Brown and White Streaks - Location 2110 Classroom
	0020	A	AT-13 1x1 Splined Ceiling Tiles with course texture and fissures - Location 1970 Gym D Washroom
	0020	B	AT-13 1x1 Splined Ceiling Tiles with course texture and fissures - Location 1111 Office
	0020	C	AT-13 1x1 Splined Ceiling Tiles with course texture and fissures - Location 1970 Gym D Washroom
	0021	A	AT-15 1x1 Splined Ceiling Tiles with Smooth Surface - Locaiton 1110 Classroom
	0021	B	AT-15 1x1 Splined Ceiling Tiles with Smooth Surface - Locaiton 2180 Classroom
	0021	C	AT-15 1x1 Splined Ceiling Tiles with Smooth Surface - Locaiton 1110 Classroom
	0022	A	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical Room



Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0022	B	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical Room
	0022	C	VT-15 9x9 Grey Vinyl Floor Tiles with White Streaks - Location 1710 Mechanical Room
	0023	A	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music
	0023	B	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music
	0023	C	VSF-1 Grey Vinyl Sheet Flooring, Stone Appearance - Location 1170 Music
	0024	A	VSF-2 Brown Vinyl Sheet Flooring, Large Cubes - Location 1261 Office
	0024	B	VSF-2 Brown Vinyl Sheet Flooring, Large Cubes - Location 1 Elevator
	0024	C	VSF-2 Brown Vinyl Sheet Flooring, Large Cubes - Location 1261 Office
	0025	A	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location 1250 Auto
	0025	B	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location 1250 Auto
	0025	C	VSF-3 Grey, Blue and Red Vinyl Sheet Flooring, Small Stone Appearance - Location 1250 Auto
	0026	A	Aircell Pipe Insulation - 1892 Pipe Chase
	0026	B	Aircell Pipe Insulation - 1892 Pipe Chase
	0026	C	Aircell Pipe Insulation - 1892 Pipe Chase
	0027	A	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886 Communication Room
	0027	B	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886 Communication Room






Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0027	C	VT-16 9x9 Red Vinyl Floor Tiles with White Streaks - Location 1886 Communication Room
	0028	A	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886 Communications Room
	0028	B	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886 Communications Room
	0028	C	VT-17 12x12 White Vinyl Floor Tiles with Black and Grey Fleck - Location 1886 Communications Room
	0029	A	AT-16 1x1 Splined Ceiling Tiles with Smooth Fissures - Location 2996 Corridor
	0029	B	AT-16 1x1 Splined Ceiling Tiles with Smooth Fissures - Location 2996 Corridor
	0029	C	AT-16 1x1 Splined Ceiling Tiles with Smooth Fissures - Location 2996 Corridor
	0030	A	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location 2001 Storage
	0030	B	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location 2161 Storage
	0030	C	VT-19 9x9 Brown Vinyl Floor Tiles with Grey and White Streaks - Location 2230 Classroom
	0031	A	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom
	0031	B	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom
	0031	C	VSF-4 Beige Vinyl Sheet Flooring, Large Cubes - Location 2020 Classroom
	0032	A	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location 2030 Classroom
	0032	B	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location 2130 Classroom
	0032	C	VT-20 9x9 Yellow Vinyl Floor Tiles with Brown and White Streaks - Location 2030 Classroom



Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0033	A	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2230 Classroom
	0033	B	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2978 Mechanical Room
	0033	C	VT-21 9x9 Green Vinyl Floor Tiles with White Streaks - Location 2440 Office
	0034	A	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom
	0034	B	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom
	0034	C	VT-22 9x9 Black Vinyl Floor Tiles with White Streaks - Location 2050 Classroom
	0035	A	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom
	0035	B	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom
	0035	C	VT-23 9x9 Blue Vinyl Floor Tiles with White Streaks - Location 2230 Classroom
	0036	A	AT-17 2x4 Lay-in Ceiling Tiles with Textured Surface and Pinholes - Location 2250 Classroom
	0036	B	AT-17 2x4 Lay-in Ceiling Tiles with Textured Surface and Pinholes - Location 2250 Classroom
	0036	C	AT-17 2x4 Lay-in Ceiling Tiles with Textured Surface and Pinholes - Location 2250 Classroom
	0037	A	VT-24 9x9 Olive with White and Grey Streaks - Location 2250 Classroom
	0037	B	VT-24 9x9 Olive with White and Grey Streaks - Location 2250 Classroom
	0037	C	VT-24 9x9 Olive Vinyl Floor Tiles with White and Grey Streaks - Location 2250 Classroom
	0038	A	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250 Classroom



Sample Prefix	Sample No.	Sample Suffix	Sample Description/Location (Mandatory)
	0038	B	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250 Classroom
	0038	C	VT-25 9x9 White Vinyl Floor Tiles with Olive and Grey Streaks - Location 2250 Classroom
	0039	A	VSF-5 Green Vinyl Sheet Flooring, Large Cubes - Location 2430 Office
	0039	B	VSF-5 Green Vinyl Sheet Flooring, Large Cubes - Location 2430 Office
	0039	C	VSF-5 Green Vinyl Sheet Flooring, Large Cubes - Location 2430 Office
	0040	A	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270 Classroom
	0040	B	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270 Classroom
	0040	C	VT-26 12x12 White Vinyl Floor Tiles with Brown Streaks - Location 2270 Classroom
	0041	A	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location 2270 Classroom
	0041	B	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location 2270 Classroom
	0041	C	VT-27 12x12 Brown Vinyl Floor Tiles with White and Purple Streaks - Location 2270 Classroom

# TRANSMITTAL

TO: SA 1.

**ATTENTION:**

**COPIES TO:**

FROM: Yolanda - Miss. Lab.

PINCHIN FILE: 71528/71526

CLIENT FILE: DATE: Dec 13, 2011

**SENT BY:**

☐ MAIL

☐ BY HAND

☐ PRINTER

☐ TO BE PICKED UP


☒ COURIER

☐ SEPARATE COVER

**ITEM NO. COPIES DESCRIPTION**

	71526	Samples from Sarah Young.
	71528	

**REMARKS:**

  
(SIGNATURE)



Your Project #: 302783.034

Site Location: `

Your C.O.C. #: n/a

**Attention: Laura Skoblenick**

Pinchin Ltd  
1456 Centennial Drive  
Suite 2  
Kingston, ON  
CANADA K7P 0K4

**Report Date: 2022/12/19**

Report #: R7436134

Version: 1 - Final

**CERTIFICATE OF ANALYSIS**

**BUREAU VERITAS JOB #: C2AF251**

**Received: 2022/12/13, 09:34**

Sample Matrix: Solid  
# Samples Received: 134

Analyses	Date		Date Analyzed	Laboratory Method	Analytical Method
	Quantity	Extracted			
Asbestos by PLM - 0.5 RDL (1)	94	N/A	2022/12/19	COR3SOP-00002	EPA 600R-93/116
Asbestos by PLM - 0.5 RDL (1)	40	N/A	N/A	COR3SOP-00002	EPA 600R-93/116

**Remarks:**

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, MELCC, EPA, APHA.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Bureau Veritas' Asbestos Laboratory is accredited by NVLAP for bulk asbestos analysis by polarized light microscopy, NVLAP Code 600136-0.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas Canada. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Bureau Veritas' scope of accreditation includes EPA -- 40 CFR Appendix E to Subpart E of Part 763, "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" and EPA-600/R-93/116: "Method for the Determination of Asbestos in Bulk Building Materials".

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

\* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.



Your Project #: 302783.034  
Site Location: `  
Your C.O.C. #: n/a

**Attention: Laura Skoblenick**

Pinchin Ltd  
1456 Centennial Drive  
Suite 2  
Kingston, ON  
CANADA K7P 0K4

**Report Date: 2022/12/19**  
Report #: R7436134  
Version: 1 - Final

**CERTIFICATE OF ANALYSIS**

**BUREAU VERITAS JOB #: C2AF251**

**Received: 2022/12/13, 09:34**

(1) P.O.B. - Percent of Bulk

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.

Encryption Key



**AUTHORIZED REPORT  
RAPPORT AUTORISÉ**

Bureau Veritas

19 Dec 2022 10:42:03

Please direct all questions regarding this Certificate of Analysis to:

Julie Clement, Technical Account Manager

Email: Julie.CLEMENT@bureauveritas.com

Phone# (613)868-6079

=====

This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0042A FLOOR,MASTIC,LOC:1009,KITCHEN

Bureau Veritas ID: UOL771		Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

#### S0042B FLOOR,MASTIC,LOC:1012,WASHROOM

Bureau Veritas ID: UOL772		Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

#### S0042C FLOOR,MASTIC,LOC:1200,PHOTOGRAPHY

Bureau Veritas ID: UOL773		Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd





Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0042D FLOOR,MASTIC,LOC:1090,OFFICE

Bureau Veritas  
ID: UOL774

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	30	Homogeneous black mastic	Not Detected		Non-Fibrous
Layer 2	70	Homogeneous yellow mastic	Not Detected		Non-Fibrous

#### S0042E FLOOR,MASTIC,LOC:1094,ELECTRICAL ROOM

Bureau Veritas  
ID: UOL775

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous yellow mastic	Not Detected		Non-Fibrous

#### S0042F FLOOR,MASTIC,LOC:1040,LIBRARY

Bureau Veritas  
ID: UOL776

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0042G FLOOR,MASTIC,LOC:2410,OFFICE					
Bureau Veritas ID: UOL777		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	30	Homogeneous black mastic	Not Detected		Non-Fibrous
Layer 2	70	Homogeneous brown mastic	Not Detected		Non-Fibrous

S0042H FLOOR,MASTIC,LOC:2000,AMPITHEATRE					
Bureau Veritas ID: UOL778		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

S0043A WALL,PAINT,WHITE,LOC:1009,KITCHEN					
Bureau Veritas ID: UOL779		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0043B WALL,PAINT,WHITE,LOC:1020,CLASSROOM					
Bureau Veritas ID: UOL780		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

S0043C WALL,PAINT,WHITE,LOC:1899,GYM A					
Bureau Veritas ID: UOL781		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

S0043D WALL,PAINT,WHITE,LOC:1976,CUSTODIAL STORAGE					
Bureau Veritas ID: UOL782		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0043E WALL,PAINT,WHITE,LOC:2150,CLASSROOM

Bureau Veritas ID:		UOL783	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous	

#### S0043F WALL,PAINT,WHITE,LOC:2990,CUSTODIAL STORAGE

Bureau Veritas ID:		UOL784	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous	

#### S0043G WALL,PAINT,WHITE,LOC:2998,BLEACHERS

Bureau Veritas ID:		UOL785	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous	

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0044A WALL,DOOR,CAULKING,GREY,LOC:1009,KITCHEN					
Bureau Veritas ID: UOL786		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

S0044B WALL,DOOR,CAULKING,GREY,LOC:3001,KITCHEN PREP					
Bureau Veritas ID: UOL787		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

S0044C WALL,DOOR,CAULKING,GREY,LOC:1170,MUSIC ROOM					
Bureau Veritas ID: UOL788		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0045A WALL,WINDOW,CAULKING,LIGHT GREY,LOC:1009,KITCHEN

Bureau Veritas  
ID: UOL789

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

#### S0045B WALL,WINDOW,CAULKING,LIGHT GREY,LOC:2230,CLASSROOM

Bureau Veritas  
ID: UOL790

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

#### S0045C WALL,WINDOW,CAULKING,LIGHT GREY,LOC:2090,CLASSROOM

Bureau Veritas  
ID: UOL791

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0046A WALL, WINDOW LINER, CAULKING, BUTYL SEALANT, BLACK, LOC:1009, KITCHEN

Bureau Veritas  
ID: UOL792

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black sealant	Not Detected		Non-Fibrous

#### S0046B WALL, WINDOW LINER, CAULKING, BUTYL SEALANT, BLACK, LOC:3001, KITCHEN PREP

Bureau Veritas  
ID: UOL793

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black sealant	Not Detected		Non-Fibrous

#### S0046C WALL, WINDOW LINER, CAULKING, BLACK, BUTYL SEALANT, LOC:1170, MUSIC ROOM

Bureau Veritas  
ID: UOL794

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black sealant	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd





Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0048A WALL,ALL,DRYWALL AND JOINT COMPOUND,LOC:1012,WASHROOM

Bureau Veritas  
ID: UOL795

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous off-white drywall joint compound	Not Detected		Non-Fibrous

#### S0048B WALL,DRYWALL AND JOINT COMPOUND,LOC:3002,CLASSROOM

Bureau Veritas  
ID: UOL796

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous off-white drywall joint compound	Not Detected		Non-Fibrous

#### S0048C WALL,DRYWALL AND JOINT COMPOUND,LOC:1192,COMMUNICATION TECHNOLOGY

Bureau Veritas  
ID: UOL797

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0048D CEILING,BULKHEAD,DRYWALL AND JOINT COMPOUND,LOC:2161,STORAGE

Bureau Veritas  
ID: UOL798

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0048E WALL,DRYWALL AND JOINT COMPOUND,LOC:1230,COMPUTER DESIGN

Bureau Veritas  
ID: UOL799

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0048F WALL,DRYWALL AND JOINT COMPOUND,LOC:1190,CLASSROOM

Bureau Veritas  
ID: UOL800

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0048G WALL, DRYWALL AND JOINT COMPOUND, LOC:1220, WOODWORKING

Bureau Veritas  
ID: UOL801

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0049A WALL, PAINT, WHITE, LOC:1012, WASHROOM

Bureau Veritas  
ID: UOL802

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

#### S0049B WALL, PAINT, WHITE, LOC:3000, CAFETERIA

Bureau Veritas  
ID: UOL803

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0049C WALL,PAINT,WHITE,LOC:3004,CLASSROOM					
Bureau Veritas ID: UOL804		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

S0049D WALL,PAINT,WHITE,LOC:1711,MECHANICAL ROOM					
Bureau Veritas ID: UOL805		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

S0049E WALL,PAINT,WHITE,LOC:2170,COMPUTER ROOM					
Bureau Veritas ID: UOL806		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0049F WALL,PAINT,WHITE,LOC:2171,OFFICE					
Bureau Veritas ID: UOL807		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous beige/grey paint/cementitious material	Not Detected		Non-Fibrous

S0049G WALL,PAINT,WHITE,LOC:2160,CLASSROOM					
Bureau Veritas ID: UOL808		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

S0050A CEILING,CEILING TILES (LAY-IN),2X4 DENSE PINHOLES AND SHORT/MEDIUM WIDTHWISE FISSURES, 08/07/20,LOC:1012,WASHROOM						
Bureau Veritas ID:		UOL809			Date Analyzed: 2022/12/16	
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>		<u>Particulate</u>
Layer 1	100	Homogeneous grey ceiling tile	Not Detected	Cellulose	35%	Non-Fibrous
				Fibrous Glass	45%	

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0050B CEILING,CEILING TILES (LAY-IN),2X4 DENSE PINHOLES AND SHORT/MEDIUM WIDTHWISE FISSURES,,LOC:1013,STORAGE

Bureau Veritas  
ID: UOL810

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey ceiling tile	Not Detected	Cellulose 35% Fibrous Glass 45%	Non-Fibrous

#### S0050C CEILING,CEILING TILES (LAY-IN),2X4 DENSE PINHOLES AND SHORT/MEDIUM WIDTHWISE FISSURES, 08/07/20,LOC:1012,WASHROOM

Bureau Veritas  
ID: UOL811

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey ceiling tile	Not Detected	Cellulose 35% Fibrous Glass 45%	Non-Fibrous

#### S0051A FLOOR,MASTIC,LOC:3000,CAFETERIA

Bureau Veritas  
ID: UOL812

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0051B FLOOR,MASTIC,LOC:1007,CAFETERIA

Bureau Veritas ID: UOL813		Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

#### S0051C FLOOR,MASTIC,LOC:2210,CLASSROOM

Bureau Veritas ID: UOL814		Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous

#### S0052A CEILING,ALL,PLASTER,LOC:1360,MECHANICAL ROOM

Bureau Veritas ID: UOL815		Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd





Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0052B CEILING,ALL,PLASTER,LOC:1360,MECHANICAL ROOM					
Bureau Veritas ID:	UOL816			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0052C CEILING,ALL,PLASTER,LOC:1360,MECHANICAL ROOM					
Bureau Veritas ID:	UOL817			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0052D CEILING,ALL,PLASTER,LOC:1981,PASSAGE					
Bureau Veritas ID:	UOL818			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0052E CEILING,PLASTER,LOC:1984,VESTIBULE

Bureau Veritas ID:		UOL819	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous light grey plaster	Chrysotile 1%		Non-Fibrous	

#### S0052F CEILING,ALL,PLASTER,LOC:1971,SHOWER

Bureau Veritas ID:		UOL820	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous grey plaster	Not Detected		Non-Fibrous	

#### S0052G CEILING,BULKHEAD,PLASTER,LOC:1250,TRANSPORT ATION TECHNOLOGY

Bureau Veritas ID:		UOL821	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous grey plaster	Not Detected		Non-Fibrous Vermiculite	

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0054A FLOOR,MASTIC,LOC:1000,CLASSROOM

Bureau Veritas ID:		UOL822	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous black/yellow mastic	Not Detected		Non-Fibrous	

#### S0054B FLOOR,MASTIC,LOC:3002,CLASSROOM

Bureau Veritas ID:		UOL823	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous	

#### S0054C FLOOR,MASTIC,LOC:1991,COPIER

Bureau Veritas ID:		UOL824	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous	

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0055A WALL, DRYWALL AND JOINT COMPOUND, LOC:1000, CLASSROOM

Bureau Veritas  
ID: UOL825

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0055B WALL, ALL, DRYWALL AND JOINT COMPOUND, LOC:1981, PASSAGE

Bureau Veritas  
ID: UOL826

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0055C WALL, DRYWALL AND JOINT COMPOUND, LOC:1099, STAIRWELL AND CORRIDOR

Bureau Veritas  
ID: UOL827

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0055D CEILING, DRYWALL AND JOINT COMPOUND, LOC:2996, CORRIDOR RAMP AND STAIRWELL					
Bureau Veritas ID: UOL828		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

S0055E CEILING, ALL, DRYWALL AND JOINT COMPOUND, LOC:1102, WASHROOM					
Bureau Veritas ID: UOL829		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

S0055F WALL, DRYWALL AND JOINT COMPOUND, LOC:3006, CLASSROOM					
Bureau Veritas ID: UOL830		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0055G WALL,ALL,DRYWALL AND JOINT COMPOUND,LOC:1031,STAFF LOUNGE

Bureau Veritas  
ID: UOL831

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0056A PIPING,ALL,CAPOSITE,LOC:1983,CORRIDOR

Bureau Veritas  
ID: UOL832

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey fibrous material	Amosite 60%		Non-Fibrous

#### S0056B PIPING,ALL,CAPOSITE,LOC:1983,CORRIDOR

Bureau Veritas  
ID: UOL833

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		
Comment: Not Analyzed - Positive Stop					

#### S0056C PIPING,ALL,CAPOSITE,LOC:1983,CORRIDOR

Bureau Veritas  
ID: UOL834

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		
Comment: Not Analyzed - Positive Stop					

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0057A WALL,ALL,PLASTER,LOC:1983,CORRIDOR

Bureau Veritas ID: UOL835		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	10	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0057B CEILING,ALL,PLASTER,LOC:1890,SHOWERS

Bureau Veritas ID: UOL836		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	50	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0057C CEILING,ALL,PLASTER,LOC:2988,PIPE CHASE

Bureau Veritas ID: UOL837		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	80	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	20	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0057D WALL, PLASTER, LOC:2991, CORRIDOR

Bureau Veritas  
ID: UOL838

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	10	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0057E WALL, PLASTER, LOC:2996, CORRIDOR RAMP AND STAIRWELL

Bureau Veritas  
ID: UOL839

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	10	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd





Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0057F WALL,PLASTER,LOC:2001,BOOD STORAGE

Bureau Veritas ID: UOL840		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	10	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0057G CEILING,ALL,PLASTER,LOC:1084,WORKSHOP

Bureau Veritas ID: UOL841		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	10	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	90	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0058A WALL,WINDOW LINER,CAULKING,BUTYL SEALANT, GREY,LOC:1020,CLASSROOM

Bureau Veritas ID: UOL842		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey/black sealant	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0058B WALL,WINDOW LINER,CAULKING,GREY BUTYL SEALANT,LOC:2190,COMPUTER ROOM

Bureau Veritas  
ID: UOL843

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey putty	Chrysotile 1%		Non-Fibrous

#### S0058C WALL,WINDOW LINER,CAULKING,GREY, BUTYL SEALANT,LOC:1270,WELDING TECHNOLOGY

Bureau Veritas  
ID: UOL844

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		
<b>Comment:</b> Not Analyzed - Positive Stop					

#### S0062A WALL,ALL,PLASTER,LOC:1097,CORRIDOR

Bureau Veritas  
ID: UOL845

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	60	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	40	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0062B CEILING,ALL,PLASTER,LOC:1094,ELECTRICAL ROOM					
Bureau Veritas ID: UOL846		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos		Particulate
Layer 1	80	Homogeneous off-white/white plaster	Chrysotile	1%	Non-Fibrous
Layer 2	20	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0062C WALL,ALL,PLASTER,LOC:1270,WELDING TECHNOLOGY					
Bureau Veritas ID: UOL847		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos		Particulate
Layer 1	50	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0062D WALL,PLASTER,LOC:1270,WELDING TECHNOLOGY					
Bureau Veritas ID: UOL848		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	90	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	10	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0062E WALL,PLASTER,LOC:2979,CORRIDOR					
Bureau Veritas ID: UOL849		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	80	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	20	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0062F WALL,PLASTER,LOC:2976,STAIRWELL

Bureau Veritas  
ID: UOL850

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	20	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	80	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0062G CEILING,ALL,PLASTER,LOC:2978,MECHANICAL ROOM

Bureau Veritas  
ID: UOL851

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	50	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0063A WALL, PAINT, WHITE, LOC:1097, CORRIDOR					
Bureau Veritas ID: UOL852		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous pink/off-white/grey paint/cementitious material	Chrysotile 2%		Non-Fibrous

S0063B WALL, PAINT, WHITE, LOC:1096, WASHROOM					
Bureau Veritas ID: UOL853		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey paint	Not Detected		Non-Fibrous

S0063C WALL, PAINT, PURPLE, LOC:1094, ELECTRICAL ROOM					
Bureau Veritas ID: UOL854		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous purple/grey paint/cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0063D WALL,PAINT,WHITE,LOC:1270,WELDING TECHNOLOGY

Bureau Veritas ID: UOL855

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Non-homogeneous off-white/grey paint/cementitious material	Chrysotile 1%		Non-Fibrous

#### S0063E WALL,PAINT,WHITE,LOC:2978,MECHANICAL ROOM

Bureau Veritas ID: UOL856

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Non-homogeneous off-white/grey paint/cementitious material	Not Detected		Non-Fibrous

#### S0063F WALL,ALL,PAINT,WHITE,LOC:2280,CLASSROOM

Bureau Veritas ID: UOL857

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Non-homogeneous off-white/grey paint/cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

<b>S0063G</b>					
<b>WALL,ALL,PAINT,WHITE,LOC:2330,CLASSROOM</b>					
Bureau Veritas ID:	UOL858			Date Analyzed:	2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Non-homogeneous off-white/grey paint/cementitious material	Not Detected		Non-Fibrous

<b>S0065A WALL,ALL,DRYWALL AND JOINT COMPOUND,LOC:1094,ELECTRICAL ROOM</b>					
Bureau Veritas ID:	UOL859			Date Analyzed:	2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

<b>S0065B WALL,DRYWALL AND JOINT COMPOUND,LOC:1270,WELDING TECHNOLOGY</b>					
Bureau Veritas ID:	UOL860			Date Analyzed:	2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd





Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0065C WALL,ALL,DRYWALL AND JOINT COMPOUND,LOC:2252,STORAGE

Bureau Veritas  
ID: UOL861

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0065D WALL,DRYWALL AND JOINT COMPOUND,LOC:1041,SEMINAR ROOM

Bureau Veritas  
ID: UOL862

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

#### S0065E CEILING,BULKHEAD,DRYWALL AND JOINT COMPOUND,LOC:2020,CLASSROOM

Bureau Veritas  
ID: UOL863

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous white drywall joint compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0066A WALL, WINDOW LINER, CAULKING, BUTYL SEALANT, GREY, LOC:1093, STAIRWELL

Bureau Veritas ID:	UOL864			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

#### S0066B WALL, WINDOW LINER, CAULKING, BUTYL SEALANT, GREY, LOC:1040, LIBRARY

Bureau Veritas ID:	UOL865			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey caulking	Chrysotile 2%		Non-Fibrous

#### S0066C WALL, WINDOW LINER, CAULKING, BUTYL SEALANT, GREY, LOC:2979, CORRIDOR

Bureau Veritas ID:	UOL866			Date Analyzed:	2022/12/19
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1			N/A		
	Comment: Not Analyzed - Positive Stop				

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0068A FLOOR,MASTIC,LOC:1041,SEMINAR ROOM

Bureau Veritas ID:		UOL867	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous	

#### S0068B FLOOR,MASTIC,LOC:1043,WORKROOM

Bureau Veritas ID:		UOL868	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous black mastic	Not Detected		Non-Fibrous	

#### S0068C FLOOR,MASTIC,LOC:1070,CLASSROOM

Bureau Veritas ID:		UOL869	Date Analyzed:			2022/12/16
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>	
Layer 1	100	Homogeneous black/brown mastic	Not Detected		Non-Fibrous	

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0069A STRUCTURE,PAINT,WHITE,LOC:1083,BOILER ROOM					
Bureau Veritas ID:	UOL870			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

S0069B STRUCTURE,PAINT,WHITE,LOC:1083,BOILER ROOM					
Bureau Veritas ID:	UOL871			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

S0069C STRUCTURE,PAINT,WHITE,LOC:1083,BOILER ROOM					
Bureau Veritas ID:	UOL872			Date Analyzed:	2022/12/16
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Non-homogeneous white/grey paint/cementitious material	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0070A WALL,DOOR,CAULKING,WHITE,LOC:1101,STORAGE					
Bureau Veritas ID: UOL873		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous white caulking	Not Detected		Non-Fibrous

S0070B WALL,DOOR,CAULKING,WHITE,LOC:1192,COMMUN ICATION TECHNOLOGY					
Bureau Veritas ID: UOL874		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous beige caulking	Not Detected		Non-Fibrous

S0070C WALL,DOOR,CAULKING,WHITE,LOC:1240,WOODW ORKING					
Bureau Veritas ID: UOL875		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous beige caulking	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0071A WALL,PLASTER,LOC:3004,CLASSROOM					
Bureau Veritas ID: UOL876		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	50	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0071B WALL,PLASTER,LOC:1973,CORRIDOR					
Bureau Veritas ID: UOL877		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	20	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	80	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0071C WALL,PLASTER,LOC:1974,CORRIDOR					
Bureau Veritas ID: UOL878		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	60	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	40	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0071D WALL,PLASTER,LOC:2170,COMPUTER ROOM					
Bureau Veritas ID: UOL879		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	80	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	20	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0071E WALL,PLASTER,LOC:2985,CORRIDOR					
Bureau Veritas ID: UOL880		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	40	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	60	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0073A STRUCTURE,BEAM,FIREPROOFING (CEMENTITIOUS),LOC:2979,CORRIDOR					
Bureau Veritas ID: UOL882		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey drywall joint compound	Not Detected		Non-Fibrous Vermiculite

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0073B STRUCTURE,BEAM,FIREPROOFING (CEMENTITIOUS),LOC:2979,CORRIDOR					
Bureau Veritas ID: UOL883		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey drywall joint compound	Not Detected		Non-Fibrous Vermiculite

S0073C STRUCTURE,BEAM,FIREPROOFING (CEMENTITIOUS),LOC:2979,CORRIDOR					
Bureau Veritas ID: UOL884		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous grey drywall joint compound	Not Detected		Non-Fibrous Vermiculite

S0076A WALL,CAULKING,BUTYL SEALANT, BLACK,LOC:3007,EXTERIOR					
Bureau Veritas ID: UOL885		Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	100	Homogeneous black sealant	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd





Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0076B WALL,CAULKING,BUTYL SEALANT, BLACK,LOC:3008,EXTERIOR

Bureau Veritas  
ID: UOL886

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black sealant	Not Detected		Non-Fibrous

#### S0076C WALL,CAULKING,BUTYL SEALANT, BLACK,LOC:3008,EXTERIOR

Bureau Veritas  
ID: UOL887

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous black sealant	Not Detected		Non-Fibrous

#### S0077A WALL,WINDOW,CAULKING,GREY,LOC:3007,EXTERIOR

Bureau Veritas  
ID: UOL888

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

<b>S0077B</b> <b>WALL,WINDOW,CAULKING,GREY,LOC:3008,EXTERIOR</b>					
Bureau Veritas ID:	UOL889	Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

<b>S0077C</b> <b>WALL,WINDOW,CAULKING,GREY,LOC:3009,EXTERIOR</b>					
Bureau Veritas ID:	UOL890	Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey caulking	Not Detected		Non-Fibrous

<b>S0078A</b> <b>STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3007,EXTERIOR</b>					
Bureau Veritas ID:	UOL891	Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	60	Homogeneous beige textured plaster	Not Detected		Non-Fibrous
Layer 2	40	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0078B STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3007 ,EXTERIOR					
Bureau Veritas ID:	UOL892	Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	60	Homogeneous beige textured plaster	Not Detected		Non-Fibrous
Layer 2	40	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0078C STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3007 ,EXTERIOR					
Bureau Veritas ID:	UOL893	Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	60	Homogeneous beige textured plaster	Not Detected		Non-Fibrous
Layer 2	40	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0080A STRUCTURE,CANOPY,PLASTER,TEXTURED, SWIRLED,LOC:3008,EXTERIOR

Bureau Veritas ID:		UOL894	Date Analyzed: 2022/12/16		
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	50	Homogeneous white textured plaster	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0080B STRUCTURE,CANOPY,PLASTER,TEXTURED, SWIRLED,LOC:3008,EXTERIOR

Bureau Veritas ID:		UOL895	Date Analyzed: 2022/12/16		
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	50	Homogeneous white textured plaster	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0080C STRUCTURE,CANOPY,PLASTER,TEXTURED, SWIRLED,LOC:3008,EXTERIOR

Bureau Veritas  
ID: UOL896

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	50	Homogeneous white textured plaster	Not Detected		Non-Fibrous
Layer 2	50	Homogeneous grey plaster	Not Detected		Non-Fibrous

#### S0081A STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3009 ,EXTERIOR

Bureau Veritas  
ID: UOL897

Date Analyzed: 2022/12/16

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	20	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	40	Homogeneous brown plaster	<b>Chrysotile</b> 1%		Non-Fibrous
Layer 3	40	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0081B STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3009 ,EXTERIOR					
Bureau Veritas ID:	UOL898	Date Analyzed: 2022/12/19			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	40	Homogeneous brown plaster	Chrysotile 1%		Non-Fibrous
Layer 2	60	Homogeneous grey plaster	Not Detected		Non-Fibrous

S0081C STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3009 ,EXTERIOR					
Bureau Veritas ID:	UOL899	Date Analyzed: 2022/12/16			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	60	Homogeneous white plaster	Not Detected		Non-Fibrous
Layer 2	40	Homogeneous grey plaster	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

<b>S0082A</b> <b>STRUCTURE,CANOPY,PAINT,BEIGE,LOC:3009,EXTERIOR</b>					
Bureau Veritas ID:	UOL900	Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey drywall joint compound	Not Detected		Non-Fibrous

<b>S0082B</b> <b>STRUCTURE,CANOPY,PAINT,BEIGE,LOC:3009,EXTERIOR</b>					
Bureau Veritas ID:	UOL901	Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey drywall joint compound	Not Detected		Non-Fibrous

<b>S0082C</b> <b>STRUCTURE,CANOPY,PAINT,BEIGE,LOC:3009,EXTERIOR</b>					
Bureau Veritas ID:	UOL902	Date Analyzed: 2022/12/16			
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey drywall joint compound	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

#### S0083A WALL, EXPANSION JOINT, CAULKING, GREY, HARD, LOC: 3009, EXTERIOR

Bureau Veritas  
ID: UOL903

Date Analyzed: 2022/12/19

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1	100	Homogeneous grey caulking	Chrysotile 2%		Non-Fibrous

#### S0083B WALL, EXPANSION JOINT, CAULKING, GREY, HARD, LOC: 3007, EXTERIOR

Bureau Veritas  
ID: UOL904

Date Analyzed: 2022/12/19

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		
Comment: Not Analyzed - Positive Stop					

#### S0083C WALL, EXPANSION JOINT, CAULKING, GREY, HARD, LOC: 3009, EXTERIOR

Bureau Veritas  
ID: UOL905

Date Analyzed: 2022/12/19

	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>	<u>Particulate</u>
Layer 1			N/A		
Comment: Not Analyzed - Positive Stop					

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)  
Date Format : yyyy/mm/dd





BUREAU  
VERITAS

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL771  
**Sample ID:** S0042A FLOOR,MASTIC,LOC:1009,KITCHEN  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL772  
**Sample ID:** S0042B FLOOR,MASTIC,LOC:1012,WASHROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL773  
**Sample ID:** S0042C FLOOR,MASTIC,LOC:1200,PHOTOGRAPHY  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL774  
**Sample ID:** S0042D FLOOR,MASTIC,LOC:1090,OFFICE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL775  
**Sample ID:** S0042E FLOOR,MASTIC,LOC:1094,ELECTRICAL ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL776  
**Sample ID:** S0042F FLOOR,MASTIC,LOC:1040,LIBRARY  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL777  
**Sample ID:** S0042G FLOOR,MASTIC,LOC:2410,OFFICE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos



BUREAU  
VERITAS

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL778  
**Sample ID:** S0042H FLOOR,MASTIC,LOC:2000,AMPITHEATRE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL779  
**Sample ID:** S0043A WALL,PAINT,WHITE,LOC:1009,KITCHEN  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL780  
**Sample ID:** S0043B WALL,PAINT,WHITE,LOC:1020,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL780 Dup  
**Sample ID:** S0043B WALL,PAINT,WHITE,LOC:1020,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL781  
**Sample ID:** S0043C WALL,PAINT,WHITE,LOC:1899,GYM A  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL782  
**Sample ID:** S0043D WALL,PAINT,WHITE,LOC:1976,CUSTODIAL STORAGE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL783  
**Sample ID:** S0043E WALL,PAINT,WHITE,LOC:2150,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL784  
**Sample ID:** S0043F WALL,PAINT,WHITE,LOC:2990,CUSTODIAL STORAGE  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL785  
**Sample ID:** S0043G WALL,PAINT,WHITE,LOC:2998,BLEACHERS  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL786  
**Sample ID:** S0044A WALL,DOOR,CAULKING,GREY,LOC:1009,KITCHEN  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL787  
**Sample ID:** S0044B WALL,DOOR,CAULKING,GREY,LOC:3001,KITCHEN PREP  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL788  
**Sample ID:** S0044C WALL,DOOR,CAULKING,GREY,LOC:1170,MUSIC ROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL789  
**Sample ID:** S0045A WALL,WINDOW,CAULKING,LIGHT GREY,LOC:1009,KITCHEN  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL790  
**Sample ID:** S0045B WALL,WINDOW,CAULKING,LIGHT GREY,LOC:2230,CLASSROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos



BUREAU  
VERITAS

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL790 Dup  
**Sample ID:** S0045B WALL, WINDOW, CAULKING, LIGHT GREY, LOC:2230, CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL791  
**Sample ID:** S0045C WALL, WINDOW, CAULKING, LIGHT GREY, LOC:2090, CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL792  
**Sample ID:** S0046A WALL, WINDOW LINER, CAULKING, BUTYL SEALANT, BLACK, LOC:1009, KITCHEN  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL793  
**Sample ID:** S0046B WALL, WINDOW LINER, CAULKING, BUTYL SEALANT, BLACK, LOC:3001, KITCHEN PREP  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL794  
**Sample ID:** S0046C WALL, WINDOW LINER, CAULKING, BLACK, BUTYL SEALANT, LOC:1170, MUSIC ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL795  
**Sample ID:** S0048A WALL, ALL, DRYWALL AND JOINT COMPOUND, LOC:1012, WASHROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL796  
**Sample ID:** S0048B WALL, DRYWALL AND JOINT COMPOUND, LOC:3002, CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

<b>Bureau Veritas ID:</b>	UOL797	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0048C WALL, DRYWALL AND JOINT COMPOUND, LOC:1192, COMMUNICATION TECHNOLOGY	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL798	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0048D CEILING,BULKHEAD,DRYWALL AND JOINT COMPOUND,LOC:2161,STORAGE	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL799	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0048E WALL,DRYWALL AND JOINT COMPOUND,LOC:1230,COMPUTER DESIGN	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL800	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0048F WALL, DRYWALL AND JOINT COMPOUND, LOC:1190, CLASSROOM	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL800 Dup	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0048F WALL, DRYWALL AND JOINT COMPOUND, LOC:1190, CLASSROOM	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL801	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0048G WALL, DRYWALL AND JOINT COMPOUND, LOC:1220, WOODWORKING	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL802	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0049A WALL,PAINT,WHITE,LOC:1012,WASHROOM	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos



**BUREAU  
VERITAS**

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL803  
**Sample ID:** S0049B WALL,PAINT,WHITE,LOC:3000,CAFETERIA  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL804  
**Sample ID:** S0049C WALL,PAINT,WHITE,LOC:3004,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL805  
**Sample ID:** S0049D WALL,PAINT,WHITE,LOC:1711,MECHANICAL ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL806  
**Sample ID:** S0049E WALL,PAINT,WHITE,LOC:2170,COMPUTER ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL807  
**Sample ID:** S0049F WALL,PAINT,WHITE,LOC:2171,OFFICE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL808  
**Sample ID:** S0049G WALL,PAINT,WHITE,LOC:2160,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL809  
**Sample ID:** S0050A CEILING,CEILING TILES (LAY-IN),2X4 DENSE PINHOLES AND SHORT/MEDIUM WIDTH CRACKS, 08/07/20,LOC:1012,WASH  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407610	N/A	2022/12/19	Jon Delos Santos

012, WASHROOM



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

<b>Bureau Veritas ID:</b>	UOL810	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0050B CEILING,CEILING TILES (LAY-IN),2X4 DENSE PINHOLES AND SHORT/MEDIUM WIDTH	<b>Shipped:</b>	2022/12/13
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

<b>Bureau Veritas ID:</b>	UOL810 Dup	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0050B CEILING,CEILING TILES (LAY-IN),2X4 DENSE PINHOLES AND SHORT/MEDIUM WIDTH	<b>Shipped:</b>	2022/12/12
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

<b>Bureau Veritas ID:</b>	UOL811	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0050C CEILING,CEILING TILES (LAY-IN),2X4 DENSE PINHOLES AND SHORT/MEDIUM WIDTH CRACKS, 08/07/20,LOC:1012,WASH	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

<b>Bureau Veritas ID:</b>	UOL812	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0051A FLOOR,MASTIC,LOC:3000,CAFETERIA	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

<b>Bureau Veritas ID:</b>	UOL813	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0051B FLOOR,MASTIC,LOC:1007,CAFETERIA	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

<b>Bureau Veritas ID:</b>	UOL814	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0051C FLOOR,MASTIC,LOC:2210,CLASSROOM	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

<b>Bureau Veritas ID:</b>	UOL815	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0052A CEILING,ALL,PLASTER,LOC:1360,MECHANICAL ROOM	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13



012,WASHROOM



BUREAU  
VERITAS

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL816  
**Sample ID:** S0052B CEILING,ALL,PLASTER,LOC:1360,MECHANICAL ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL817  
**Sample ID:** S0052C CEILING,ALL,PLASTER,LOC:1360,MECHANICAL ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL818  
**Sample ID:** S0052D CEILING,ALL,PLASTER,LOC:1981,PASSAGE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL819  
**Sample ID:** S0052E CEILING,PLASTER,LOC:1984,VESTIBULE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL820  
**Sample ID:** S0052F CEILING,ALL,PLASTER,LOC:1971,SHOWER  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL820 Dup  
**Sample ID:** S0052F CEILING,ALL,PLASTER,LOC:1971,SHOWER  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL821  
**Sample ID:** S0052G CEILING,BULKHEAD,PLASTER,LOC:1250,TRANSPORTATION TECHNOLOGY  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos



**BUREAU  
VERITAS**

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL822  
**Sample ID:** S0054A FLOOR,MASTIC,LOC:1000,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL823  
**Sample ID:** S0054B FLOOR,MASTIC,LOC:3002,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL824  
**Sample ID:** S0054C FLOOR,MASTIC,LOC:1991,COPIER  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL825  
**Sample ID:** S0055A WALL,DRYWALL AND JOINT COMPOUND,LOC:1000,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL826  
**Sample ID:** S0055B WALL,ALL,DRYWALL AND JOINT COMPOUND,LOC:1981,PASSAGE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL827  
**Sample ID:** S0055C WALL,DRYWALL AND JOINT COMPOUND,LOC:1099,STAIRWELL AND CORRIDOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL828  
**Sample ID:** S0055D CEILING,DRYWALL AND JOINT COMPOUND,LOC:2996,CORRIDOR RAMP AND STAIRWELL  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos



**BUREAU  
VERITAS**

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL829  
**Sample ID:** S0055E CEILING,ALL,DRYWALL AND JOINT COMPOUND,LOC:1102,WASHROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL830  
**Sample ID:** S0055F WALL,DRYWALL AND JOINT COMPOUND,LOC:3006,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL830 Dup  
**Sample ID:** S0055F WALL,DRYWALL AND JOINT COMPOUND,LOC:3006,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL831  
**Sample ID:** S0055G WALL,ALL,DRYWALL AND JOINT COMPOUND,LOC:1031,STAFF LOUNGE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL832  
**Sample ID:** S0056A PIPING,ALL,CAPOSITE,LOC:1983,CORRIDOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL833  
**Sample ID:** S0056B PIPING,ALL,CAPOSITE,LOC:1983,CORRIDOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL834  
**Sample ID:** S0056C PIPING,ALL,CAPOSITE,LOC:1983,CORRIDOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM



**BUREAU  
VERITAS**

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL841  
**Sample ID:** S0057G CEILING,ALL,PLASTER,LOC:1084,WORKSHOP  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL842  
**Sample ID:** S0058A WALL,WINDOW LINER,CAULKING,BUTYL SEALANT, GREY,LOC:1020,CLASSROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL843  
**Sample ID:** S0058B WALL,WINDOW LINER,CAULKING,GREY BUTYL SEALANT,LOC:2190,COMPUTER ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL844  
**Sample ID:** S0058C WALL,WINDOW LINER,CAULKING,GREY, BUTYL SEALANT,LOC:1270,WELDING TECHNOLOGY  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL845  
**Sample ID:** S0062A WALL,ALL,PLASTER,LOC:1097,CORRIDOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL846  
**Sample ID:** S0062B CEILING,ALL,PLASTER,LOC:1094,ELECTRICAL ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL847  
**Sample ID:** S0062C WALL,ALL,PLASTER,LOC:1270,WELDING TECHNOLOGY  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos



**BUREAU  
VERITAS**

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL848  
**Sample ID:** S0062D WALL,PLASTER,LOC:1270,WELDING TECHNOLOGY  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL849  
**Sample ID:** S0062E WALL,PLASTER,LOC:2979,CORRIDOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL850  
**Sample ID:** S0062F WALL,PLASTER,LOC:2976,STAIRWELL  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL850 Dup  
**Sample ID:** S0062F WALL,PLASTER,LOC:2976,STAIRWELL  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL851  
**Sample ID:** S0062G CEILING,ALL,PLASTER,LOC:2978,MECHANICAL ROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL852  
**Sample ID:** S0063A WALL,PAINT,WHITE,LOC:1097,CORRIDOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos

**Bureau Veritas ID:** UOL853  
**Sample ID:** S0063B WALL,PAINT,WHITE,LOC:1096,WASHROOM  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407611	N/A		Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM





Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

<b>Bureau Veritas ID:</b>	UOL860 Dup	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0065B WALL, DRYWALL AND JOINT COMPOUND, LOC:1270, WELDING TECHNOLOGY	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL861	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0065C WALL,ALL,DRYWALL AND JOINT COMPOUND,LOC:2252,STORAGE	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL862	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0065D WALL, DRYWALL AND JOINT COMPOUND, LOC:1041, SEMINAR ROOM	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL863	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0065E CEILING,BULKHEAD,DRYWALL AND JOINT COMPOUND,LOC:2020,CLASSROOM	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL864	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0066A WALL,WINDOW LINER,CAULKING,BUTYL SEALANT, GREY,LOC:1093,STAIRWELL	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL865	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0066B WALL,WINDOW LINER,CAULKING,BUTYL SEALANT, GREY,LOC:1040,LIBRARY	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

<b>Bureau Veritas ID:</b>	UOL866	<b>Collected:</b>	2022/12/12
<b>Sample ID:</b>	S0066C WALL,WINDOW LINER,CAULKING,BUTYL SEALANT, GREY,LOC:2979,CORRIDOR	<b>Shipped:</b>	
<b>Matrix:</b>	Solid	<b>Received:</b>	2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `   
Sampler Initials: HM

**Bureau Veritas ID:** UOL867  
**Sample ID:** S0068A FLOOR,MASTIC,LOC:1041,SEMINAR ROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL868  
**Sample ID:** S0068B FLOOR,MASTIC,LOC:1043,WORKROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL869  
**Sample ID:** S0068C FLOOR,MASTIC,LOC:1070,CLASSROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL870  
**Sample ID:** S0069A STRUCTURE,PAINT,WHITE,LOC:1083,BOILER ROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL870 Dup  
**Sample ID:** S0069A STRUCTURE,PAINT,WHITE,LOC:1083,BOILER ROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL871  
**Sample ID:** S0069B STRUCTURE,PAINT,WHITE,LOC:1083,BOILER ROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL872  
**Sample ID:** S0069C STRUCTURE,PAINT,WHITE,LOC:1083,BOILER ROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL873  
**Sample ID:** S0070A WALL,DOOR,CAULKING,WHITE,LOC:1101,STORAGE  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL874  
**Sample ID:** S0070B WALL,DOOR,CAULKING,WHITE,LOC:1192,COMMUNICATION TECHNOLOGY  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL875  
**Sample ID:** S0070C WALL,DOOR,CAULKING,WHITE,LOC:1240,WOODWORKING  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL876  
**Sample ID:** S0071A WALL,PLASTER,LOC:3004,CLASSROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL877  
**Sample ID:** S0071B WALL,PLASTER,LOC:1973,CORRIDOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL878  
**Sample ID:** S0071C WALL,PLASTER,LOC:1974,CORRIDOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL879  
**Sample ID:** S0071D WALL,PLASTER,LOC:2170,COMPUTER ROOM  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

**Bureau Veritas ID:** UOL880  
**Sample ID:** S0071E WALL,PLASTER,LOC:2985,CORRIDOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL880 Dup  
**Sample ID:** S0071E WALL,PLASTER,LOC:2985,CORRIDOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL882  
**Sample ID:** S0073A STRUCTURE,BEAM,FIREPROOFING (CEMENTITIOUS),LOC:2979,CORRIDOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL883  
**Sample ID:** S0073B STRUCTURE,BEAM,FIREPROOFING (CEMENTITIOUS),LOC:2979,CORRIDOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL884  
**Sample ID:** S0073C STRUCTURE,BEAM,FIREPROOFING (CEMENTITIOUS),LOC:2979,CORRIDOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL885  
**Sample ID:** S0076A WALL,CAULKING,BUTYL SEALANT, BLACK,LOC:3007,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL886  
**Sample ID:** S0076B WALL,CAULKING,BUTYL SEALANT, BLACK,LOC:3008,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos



**BUREAU  
VERITAS**

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL887  
**Sample ID:** S0076C WALL,CAULKING,BUTYL SEALANT, BLACK,LOC:3008,EXTERIOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL888  
**Sample ID:** S0077A WALL,WINDOW,CAULKING,GREY,LOC:3007,EXTERIOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL889  
**Sample ID:** S0077B WALL,WINDOW,CAULKING,GREY,LOC:3008,EXTERIOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL890  
**Sample ID:** S0077C WALL,WINDOW,CAULKING,GREY,LOC:3009,EXTERIOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL891  
**Sample ID:** S0078A STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3007,EXTERIOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL891 Dup  
**Sample ID:** S0078A STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3007,EXTERIOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL892  
**Sample ID:** S0078B STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3007,EXTERIOR  
**Matrix:** Solid

**Collected:** 2022/12/12  
**Shipped:**  
**Received:** 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL893  
**Sample ID:** S0078C STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3007,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL894  
**Sample ID:** S0080A STRUCTURE,CANOPY,PLASTER,TEXTURED, SWIRLED,LOC:3008,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL895  
**Sample ID:** S0080B STRUCTURE,CANOPY,PLASTER,TEXTURED, SWIRLED,LOC:3008,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL896  
**Sample ID:** S0080C STRUCTURE,CANOPY,PLASTER,TEXTURED, SWIRLED,LOC:3008,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL897  
**Sample ID:** S0081A STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL898  
**Sample ID:** S0081B STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL899  
**Sample ID:** S0081C STRUCTURE,CANOPY,PLASTER,TEXTURED,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos



Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## TEST SUMMARY

**Bureau Veritas ID:** UOL900  
**Sample ID:** S0082A STRUCTURE,CANOPY,PAINT,BEIGE,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL901  
**Sample ID:** S0082B STRUCTURE,CANOPY,PAINT,BEIGE,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL901 Dup  
**Sample ID:** S0082B STRUCTURE,CANOPY,PAINT,BEIGE,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL902  
**Sample ID:** S0082C STRUCTURE,CANOPY,PAINT,BEIGE,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407612	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL903  
**Sample ID:** S0083A WALL,EXPANSION JOINT,CAULKING,GREY, HARD,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407615	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL904  
**Sample ID:** S0083B WALL,EXPANSION JOINT,CAULKING,GREY, HARD,LOC:3007,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407615	N/A	2022/12/19	Jon Delos Santos

**Bureau Veritas ID:** UOL905  
**Sample ID:** S0083C WALL,EXPANSION JOINT,CAULKING,GREY, HARD,LOC:3009,EXTERIOR  
**Matrix:** Solid

Collected: 2022/12/12  
Shipped:  
Received: 2022/12/13

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	8407615	N/A	2022/12/19	Jon Delos Santos



**BUREAU  
VERITAS**

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

## GENERAL COMMENTS

Results relate only to the items tested.





BUREAU  
VERITAS

Bureau Veritas Job #: C2AF251  
Report Date: 2022/12/19

Pinchin Ltd  
Client Project #: 302783.034  
Site Location: `  
Sampler Initials: HM

### VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Jon Delos Santos, Laboratory Supervisor

---

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by {0}, {1} responsible for {2} {3} laboratory operations.

**APPENDIX II-B**  
**Lead Analytical Certificates**

## Certificate of Analysis

### Pinchin Ltd. (Kingston)

1456 Centennial Drive, Suite 2  
Kingston, ON K7P 0K4  
Attn: Halie MacKillican

Client PO:  
Project: 302783.034  
Custody:

Report Date: 15-Dec-2022  
Order Date: 12-Dec-2022

**Order #: 2251016**

This Certificate of Analysis contains analytical data applicable to the following samples as submitted:

Paracel ID	Client ID		
2251016-01	L0001 - White/off-white, concrete block, composite sample	2251016-31	L0033 - White, steel structure/canopy, Loc 3009
2251016-02	L0002 - White/off-white, drywall, composite sample		
2251016-03	L0003 - Red, steel structure, Loc 1009 & 1981		
2251016-04	L0004 - White/off-white, concrete block, Loc 1012, 1711 & 2330		
2251016-05	L0005 - White/off-white, drywall, Loc 1012, 1974 & 1192		
2251016-06	L0006 - Red, steel structure, Loc 3001, 2980 & 1963		
2251016-07	L0007 - Beige, plaster, Loc 1360		
2251016-08	L0008 - White, plaster, composite sample		
2251016-09	L0009 - Grey/green, concrete floor, composite sample		
2251016-10	L0010 - White wood wall, Loc 1003		
2251016-11	L0011 - Grey/green/beige, concrete floor, Loc 1002		
2251016-12	L0012 - Beige/black, concrete block, Loc 1898		
2251016-13	L0013 - Dark grey, plaster, Loc 1090		
2251016-14	L0014 - Pink, plaster, Loc 1097		
2251016-15	L0015 - Red, steel structure, Loc 2250 & 2976		
2251016-16	L0016 - White, concrete block, Loc 1097, 1270 & 2252		
2251016-17	L0017 - White, plaster, Loc 1094, 1270 & 2350		
2251016-18	L0018 - Purple, brick, Loc 1094 & 1040		
2251016-19	L0019 - Purple, drywall, Loc 1094 & 1040		
2251016-20	L0020 - Off-white, drywall, Loc 2252 & 1041		
2251016-21	L0021 - Off-white, concrete structure, Loc 1083		
2251016-22	L0022 - Off-white, plaster, Loc 3004, 1971, 2190		
2251016-23	L0024 - Black/green, concrete block, Loc 1200 & 1721		
2251016-24	L0025 - Green, plaster, Loc 1721		
2251016-25	L0027 - Black, drywall, Loc 1200		
2251016-26	L0028 - Grey, concrete floor, Loc 1711 & 1290		
2251016-27	L0029 - Yellow, textured plaster, soffit, Loc 3007		
2251016-28	L0030 - White, textured plaster, soffit, Loc 3008		
2251016-29	L0031 - White, textured plaster, soffit, Loc 3009		
2251016-30	L0032 - Beige, concrete canopy, Loc 3009		

Approved By:



Mark Foto, M.Sc.  
Lab Supervisor

Any use of these results implies your agreement that our total liability in connection with this work, however arising shall be limited to the amount paid by you for this work, and that our employees or agents shall not under circumstances be liable to you in connection with this work

Certificate of Analysis

Client: Pinchin Ltd. (Kingston)

Client PO:

Report Date: 15-Dec-2022

Order Date: 12-Dec-2022

Project Description: 302783.034

**Analysis Summary Table**

Analysis	Method Reference/Description	Extraction Date	Analysis Date
Metals, ICP-MS	EPA 6020 - Digestion - ICP-MS	14-Dec-22	14-Dec-22

**Qualifier Notes:***Sample Qualifiers :*

- 1 : Complete separation of paint from substrate not possible for this sample and a small amount of substrate has been included in the paint digestion.

**Sample Data Revisions**

None

**Work Order Revisions/Comments:**

None

**Other Report Notes:**

n/a: not applicable

ND: Not Detected

MDL: Method Detection Limit

Source Result: Data used as source for matrix and duplicate samples

%REC: Percent recovery.

RPD: Relative percent difference.

Certificate of Analysis  
 Client: Pinchin Ltd. (Kingston)  
 Client PO:

Report Date: 15-Dec-2022  
 Order Date: 12-Dec-2022  
 Project Description: 302783.034

## Sample Results

Lead					Matrix: Other
Paracel ID	Client ID	Sample Date	Units	MDL	Result
2251016-27	L0029 - Yellow, textured plaster, soffit, Loc 3007	11-Aug-22	% by Wt.	0.0001	0.0005

Lead					Matrix: Paint
Paracel ID	Client ID	Sample Date	Units	MDL	Result
2251016-01	L0001 - White/off-white, concrete block, composite sample	11-Aug-22	% by Wt.	0.0005	0.0085 [1]
2251016-02	L0002 - White/off-white, drywall, composite sample	11-Aug-22	% by Wt.	0.0005	0.0005 [1]
2251016-03	L0003 - Red, steel structure, Loc 1009 & 1981	11-Aug-22	% by Wt.	0.0005	0.0880
2251016-04	L0004 - White/off-white, concrete block, Loc 1012, 1711 & 1981	11-Aug-22	% by Wt.	0.0005	0.0078 [1]
2251016-05	L0005 - White/off-white, drywall, Loc 1012, 1974 & 1191	11-Aug-22	% by Wt.	0.0005	<0.0005 [1]
2251016-06	L0006 - Red, steel structure, Loc 3001, 2980 & 1963	11-Aug-22	% by Wt.	0.0005	0.110
2251016-07	L0007 - Beige, plaster, Loc 1360	11-Aug-22	% by Wt.	0.0005	0.0262 [1]
2251016-08	L0008 - White, plaster, composite sample	11-Aug-22	% by Wt.	0.0005	0.0339
2251016-09	L0009 - Grey/green, concrete floor, composite sample	11-Aug-22	% by Wt.	0.0005	0.0369 [1]
2251016-10	L0010 - White wood wall, Loc 1003	11-Aug-22	% by Wt.	0.0005	0.0013 [1]
2251016-11	L0011 - Grey/green/beige, concrete floor, Loc 1002	11-Aug-22	% by Wt.	0.0005	0.0065
2251016-12	L0012 - Beige/black, concrete block, Loc 1898	11-Aug-22	% by Wt.	0.0005	0.0018
2251016-13	L0013 - Dark grey, plaster, Loc 1090	11-Aug-22	% by Wt.	0.0005	0.0320
2251016-14	L0014 - Pink, plaster, Loc 1097	11-Aug-22	% by Wt.	0.0005	0.0013 [1]
2251016-15	L0015 - Red, steel structure, Loc 2250 & 2976	11-Aug-22	% by Wt.	0.0005	0.330
2251016-16	L0016 - White, concrete block, Loc 1097, 1270 & 2252	11-Aug-22	% by Wt.	0.0005	0.0281 [1]
2251016-17	L0017 - White, plaster, Loc 1094, 1270 & 2350	11-Aug-22	% by Wt.	0.0005	0.0123 [1]
2251016-18	L0018 - Purple, brick, Loc 1094 & 1040	11-Aug-22	% by Wt.	0.0005	0.0082 [1]
2251016-19	L0019 - Purple, drywall, Loc 1094 & 1040	11-Aug-22	% by Wt.	0.0005	0.0011 [1]
2251016-20	L0020 - Off-white, drywall, Loc 2252 & 1041	11-Aug-22	% by Wt.	0.0005	<0.0005
2251016-21	L0021 - Off-white, concrete structure, Loc 1083	11-Aug-22	% by Wt.	0.0005	0.0057
2251016-22	L0022 - Off-white, plaster, Loc 3004, 1971, 2190	11-Aug-22	% by Wt.	0.0005	0.0092
2251016-23	L0024 - Black/green, concrete block, Loc 1200 & 1721	11-Aug-22	% by Wt.	0.0005	0.0021 [1]
2251016-24	L0025 - Green, plaster, Loc 1721	11-Aug-22	% by Wt.	0.0005	0.0094
2251016-25	L0027 - Black, drywall, Loc 1200	11-Aug-22	% by Wt.	0.0005	0.0066
2251016-26	L0028 - Grey, concrete floor, Loc 1711 & 1290	11-Aug-22	% by Wt.	0.0005	0.111
2251016-28	L0030 - White, textured plaster, soffit, Loc 3008	11-Aug-22	% by Wt.	0.0005	0.0015
2251016-29	L0031 - White, textured plaster, soffit, Loc 3009	11-Aug-22	% by Wt.	0.0005	0.138
2251016-30	L0032 - Beige, concrete canopy, Loc 3009	11-Aug-22	% by Wt.	0.0005	0.0037 [1]
2251016-31	L0033 - White, steel structure/canopy, Loc 3009	11-Aug-22	% by Wt.	0.0005	0.0556

Certificate of Analysis

Client: Pinchin Ltd. (Kingston)

Client PO:

Report Date: 15-Dec-2022

Order Date: 12-Dec-2022

Project Description: 302783.034

## Laboratory Internal QA/QC

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
<b>Matrix Blank</b>									
Lead	ND	0.0001	% by Wt.						
<b>Matrix Duplicate</b>									
Lead	0.347	0.0005	% by Wt.	0.342			1.44	50	
<b>Matrix Spike</b>									
Lead	175	5.00	% by Wt.	137	75.8	70-130			



Client Name: Pinchin Ltd.		Project Ref:		Page 1 of 4	
Contact Name: Halie MacKillican		Quote #: 302783.034		<b>Turnaround Time</b> <input type="checkbox"/> 1 day <input type="checkbox"/> 3 day <input type="checkbox"/> 2 day <input checked="" type="checkbox"/> Regular Date Required: _____	
Address: 1456 Centennial Drive, Kingston, ON		PO #:			
Telephone: 613.541.1013		E-mail: hmackillican@pinchin.com			

<input type="checkbox"/> REG 153/04 <input type="checkbox"/> REG 406/19		Other Regulation		Matrix Type: S (Soil/Sed.) GW (Ground Water) SW (Surface Water) SS (Storm/Sanitary Sewer) P (Paint) A (Air) O (Other)		Required Analysis															
<input type="checkbox"/> Table 1 <input type="checkbox"/> Res/Park <input type="checkbox"/> Med/Fine <input type="checkbox"/> Table 2 <input type="checkbox"/> Ind/Comm <input type="checkbox"/> Coarse <input type="checkbox"/> Table 3 <input type="checkbox"/> Agri/Other <input type="checkbox"/> Table _____ For RSC: <input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> REG 558 <input type="checkbox"/> PWQO <input type="checkbox"/> CCME <input type="checkbox"/> MISA <input type="checkbox"/> SU - Sani <input type="checkbox"/> SU - Storm Mun: _____ <input type="checkbox"/> Other: _____																			
Sample ID/Location Name				Matrix	Air Volume	# of Containers	Sample Taken		Lead												
							Date	Time													
1	L0001-White/off-white, concrete block, composite sample			p		1	Aug 11 2022	PM	✓												
2	L0002-White/off-white, drywall, composite sample			p		1	Aug 11 2022	PM	✓												
3	L0003-Red, steel structure, Loc 1009 & 1981			p		1	Aug 11 2022	PM	✓												
4	L0004-White/off-white, concrete block, Loc 1012,1711&2330			p		1	Aug 11 2022	PM	✓												
5	L0005-White/off-white, drywall, Loc 1012, 1974 & 1192			p		1	Aug 11 2022	PM	✓												
6	L0006-Red, steel structure, Loc 3001, 2980 & 1963			p		1	Aug 11 2022	PM	✓												
7	L0007-Beige, plaster, Loc 1360			p		1	Aug 11 2022	PM	✓												
8	L0008-White, plaster, composite sample			p		1	Aug 11 2022	PM	✓												
9	L0009-Grey/green, concrete floor, composite sample			p		1	Aug 11 2022	PM	✓												
10	L0010-White wood wall, Loc 1003			p		1	Aug 11 2022	PM	✓												

Comments: cc lskoblenick@pinchin.com Please report results in percent			Method of Delivery:		
Relinquished By (Sign):	Received By Driver/Depot:	Received at Lab:	Verified By:		
Relinquished By (Print): Halie MacKillican	Date/Time:	Date/Time: Dec 12 2022 8:57	Date/Time: Dec 12 2022 10:55		
Date/Time: Dec 9 2022	Temperature: °C	Temperature:	pH Verified: <input type="checkbox"/> By:		





PARACE  
LABORATORIES



### Chain Of Custody

(Lab Use Only)

Client Name: Pinchin Ltd.	Project Ref:	Page <u>2</u> of <u>4</u>
Contact Name: Halie MacKillican	Quote #: 302783.034	<b>Turnaround Time</b> <input type="checkbox"/> 1 day <input type="checkbox"/> 3 day <input type="checkbox"/> 2 day <input checked="" type="checkbox"/> Regular Date Required: _____
Address: 1456 Centennial Drive, Kingston, ON	PO #:	
Telephone: 613.541.1013	E-mail: hmackillican@pinchin.com	

[illegible]

Comments: cc Iskobenick@pinchin.com Please report results in percent			Method of Delivery: <i>Parabola</i>	
Relinquished By (Sign):	Received By Driver/Depot:	Received At:	Verified By:	
		<i>Be</i>	<i>Be</i>	
Relinquished By (Print): Halie MacKilican	Date/Time:	Date/Time:	Date/Time:	
		<i>Dec 12 2015</i>	<i>Dec 12 2015</i>	
Date/Time: Dec 9 2022	Temperature: °C	Temperature:	pH Verified: <input type="checkbox"/> By:	
Chain of Custody (Blank) v1.0				



Revision 4.0

Parcel Order Number (Lab Use Only)	Chain Of Custody (Lab Use Only)
	Page <u>4</u> of <u>4</u>
	Turnaround Time
	<input type="checkbox"/> 1 day <input type="checkbox"/> 3 day
	<input type="checkbox"/> 2 day <input checked="" type="checkbox"/> Regular
	Date Required: _____

Client Name: Pinchin Ltd.		Project Ref:		Page 4 of 4	
Contact Name: Halie MacKillican		Quote #: 302783.034		<b>Turnaround Time</b> <input type="checkbox"/> 1 day <input type="checkbox"/> 3 day <input type="checkbox"/> 2 day <input checked="" type="checkbox"/> Regular	
Address: 1456 Centennial Drive, Kingston, ON		PO #:			
Telephone: 613.541.1013		E-mail: hmackillican@pinchin.com			
<input type="checkbox"/> 250-1500 Inc.				Date Required:	

[illegible]

Comments: cc Iskobenick@pinchin.com Please report results in percent		Method of Delivery:	
Relinquished By (Sign):	Received By Driver/Depot:	Received at Lab:	Verified By:
Relinquished By (Print): Halie MacKillican	Date/Time:	Date/Time:	Date/Time:
Date/Time: Dec 9 2022	Temperature: °C	Temperature:	pH Verified: <input type="checkbox"/> By:

**APPENDIX II-C**  
**PCB Analytical Certificates**

## Certificate of Analysis

**Pinchin Ltd. (Kingston)**

1456 Centennial Drive, Suite 2  
Kingston, ON K7P 0K4  
Attn: Halie MacKillican

Client PO:  
Project: 302783.034  
Custody:

Report Date: 14-Dec-2022  
Order Date: 12-Dec-2022

**Order #: 2251013**

This Certificate of Analysis contains analytical data applicable to the following samples as submitted :

Paracel ID	Client ID
2251013-01	P0001 - Caulking, various colours, window/doors, composite
2251013-02	P0002 - Butyl sealant, black/grey, windows, composite
2251013-03	P0003 - Butyl sealant, grey, windows/doors, Loc 1040 & 1093
2251013-04	P0004 - Butyl sealant, black, windows, composite
2251013-05	P0005 - Caulking, grey, window frames, Loc 3008 & 3007
2251013-06	P0006 - Caulking, hard grey, expansion joints, Loc3007 & 3009

Approved By:



Mark Foto, M.Sc.  
Lab Supervisor

Certificate of Analysis

Report Date: 14-Dec-2022

Client: Pinchin Ltd. (Kingston)

Order Date: 12-Dec-2022

Client PO:

Project Description: 302783.034

**Analysis Summary Table**

Analysis	Method Reference/Description	Extraction Date	Analysis Date
PCBs, total	SW846 8082A - GC-ECD	12-Dec-22	13-Dec-22

Certificate of Analysis

Report Date: 14-Dec-2022

Client: Pinchin Ltd. (Kingston)

Order Date: 12-Dec-2022

Client PO:

Project Description: 302783.034

<b>Client ID:</b>	P0001 - Caulking, various colours, window/doors, composite	P0002 - Butyl sealant, black/grey, windows, composite	P0003 - Butyl sealant, grey, windows/doors, Loc 1040 & 1093	P0004 - Butyl sealant, black, windows, composite
<b>Sample Date:</b>	11-Aug-22 12:00	11-Aug-22 12:00	11-Aug-22 12:00	11-Aug-22 12:00
<b>Sample ID:</b>	2251013-01	2251013-02	2251013-03	2251013-04
<b>MDL/Units</b>	Other	Other	Other	Other

**PCBs**

PCBs, total	5 ppm	<5	<5	<5	<5
Decachlorobiphenyl	Surrogate	128%	93%	94%	97%

<b>Client ID:</b>	P0005 - Caulking, grey, window frames, Loc 3008 & 3007	P0006 - Caulking, hard grey, expansion joints, Loc3007 & 3009	-	-
<b>Sample Date:</b>	11-Aug-22 12:00	11-Aug-22 12:00	-	-
<b>Sample ID:</b>	2251013-05	2251013-06	-	-
<b>MDL/Units</b>	Other	Other	-	-

**PCBs**

PCBs, total	5 ppm	<5	<5	-	-
Decachlorobiphenyl	Surrogate	132%	94%	-	-

Certificate of Analysis

Report Date: 14-Dec-2022

Client: Pinchin Ltd. (Kingston)

Order Date: 12-Dec-2022

Client PO:

Project Description: 302783.034

### Method Quality Control: Blank

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
<b>PCBs</b>									
PCBs, total	ND	5	ppm						
Surrogate: Decachlorobiphenyl	4.55		ppm		91.0	60-140			

Certificate of Analysis

Report Date: 14-Dec-2022

Client: Pinchin Ltd. (Kingston)

Order Date: 12-Dec-2022

Client PO:

Project Description: 302783.034

### Method Quality Control: Duplicate

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
<b>PCBs</b>									
PCBs, total	ND	5	ppm	ND			NC	40	
Surrogate: Decachlorobiphenyl	5.03		ppm		101	60-140			



Certificate of Analysis

Report Date: 14-Dec-2022

Client: Pinchin Ltd. (Kingston)

Order Date: 12-Dec-2022

Client PO:

Project Description: 302783.034

### Method Quality Control: Spike

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
<b>PCBs</b>									
PCBs, total	26	5	ppm	ND	129	60-140			
Surrogate: Decachlorobiphenyl	4.39		ppm		87.7	60-140			

Certificate of Analysis

Client: Pinchin Ltd. (Kingston)

Client PO:

Report Date: 14-Dec-2022

Order Date: 12-Dec-2022

Project Description: 302783.034

Qualifier Notes:

Sample Data Revisions

None

Work Order Revisions / Comments:

None

Other Report Notes:

n/a: not applicable

ND: Not Detected

MDL: Method Detection Limit

Source Result: Data used as source for matrix and duplicate samples

%REC: Percent recovery.

RPD: Relative percent difference.

NC: Not Calculated



**APPENDIX III**  
**Methodology and Evaluation Criteria**



## 1.0 GENERAL

An inspection was conducted to identify the type of Hazardous Building Materials incorporated in the structure and its finishes.

Information regarding the location and condition of hazardous building materials encountered and visually estimated quantities were recorded. The locations of any samples collected were recorded on small-scale plans. As-built drawings and previous reports were referenced where provided.

Sample collection was conducted in accordance with our Standard Operating Procedures.

### 1.1 Asbestos

The inspection for asbestos included friable and non-friable asbestos-containing materials (ACM). A friable material is a material that when dry can be crumbled, pulverized or powdered by hand pressure.

A separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

The analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.

Analytical results were compared to the following criteria:

Jurisdiction	Friable	Non-Friable
Ontario	0.5%	0.5%

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials were evaluated in order to make recommendations regarding any remedial work. The priority for remedial action was based on several factors:

- Friability (friable or non-friable).
- Condition (good, fair, poor, debris).
- Accessibility (ranking from accessible to all building users to inaccessible).
- Visibility (whether the material is obscured by other building components).
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition).

For a complete description of the Evaluation Criteria and Basis of Recommendations, refer to Annex A.

## **1.2 Lead**

Samples of distinctive paint finishes, and surface coatings present in more than a limited application, where removal of the paint is possible was collected. The samples were collected by scraping the painted finish to include base and covering applications.

Analysis for lead in paints or surface coatings was performed in accordance with EPA Method No. 3050B/Method No. 7420; flame atomic absorption, or equivalent.

Analytical results were compared to the following criteria:

<b>Jurisdiction</b>	<b>Units (%)</b>	<b>Units (ppm) / (mg/kg)</b>
Ontario	0.1	1000

Other lead building products (e.g. batteries, lead sheeting, flashing) were identified by visual observation only.

## **1.3 Silica**

Building materials known to contain crystalline silica (e.g. concrete, cement, tile, brick, masonry, mortar) were identified by visual inspection only. Pinchin did not perform sampling of these materials for laboratory analysis of crystalline silica content.

## **1.4 Mercury**

Building materials, products or equipment (e.g. thermostats, barometers, pressure gauges, lamp tubes), suspected to contain mercury was identified by visually inspection only. Dismantling of equipment suspected of containing mercury was not performed. Sampling of these materials for laboratory analysis of mercury content was not performed.



### **1.5 Polychlorinated Biphenyls**

The potential for light ballast and oil filled transformers to contain PCBs was based on the age of the building, a review of maintenance records and examination of labels or nameplates on equipment, where present and accessible. The information was compared to known ban dates of PCBs and Environment Canada publications.

Dry type transformers were presumed to be free of dielectric fluids and hence non-PCB.

Fluids (mineral oil, hydraulic, Aroclor or Askarel) in transformers or other equipment were not sampled for PCB content.

Caulking, sealants, or paints were sampled and submitted for PCB analysis following EPA 3550C/8082A.

Sample results are compared to the criteria of 50 mg/kg for solids as stated in the PCB Regulation, SOR/2008-273.

### **1.6 Visible Mould**

The presence of mould or water damage was determined by visual inspection of exposed building surfaces. If any mould growth or water damage was concealed within building cavities it was not addressed in this assessment.

Template: Methodology for Hazardous Building Materials Assessment, HAZ, November 23, 2021

## **METHODOLOGY ANNEX A EVALUATION CRITERIA**



## 1.0 EVALUATION CRITERIA AND BASIS OF RECOMMENDATIONS

The detailed asbestos assessment provides information regarding the location, condition, accessibility and friability of the asbestos-containing materials (ACM). In order to make recommendations for compliance with current regulations, Pinchin developed the following criteria.

## 2.0 EVALUATION OF CONDITION

### 2.1 Friable Sprayed or Trowelled Fireproofing, Thermal Insulation and Texture Finishes (Surfacing Materials)

To evaluate the condition of ACM sprayed or trowelled on fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes, the following criteria are applied:

<b>Good</b>	Surface of material shows no significant signs of damage, deterioration or delamination. Good condition includes unencapsulated or unpainted fireproofing or texture finishes, where no or limited delamination or damage is observed, or encapsulated fireproofing or texture finishes where the encapsulant or paint has been applied after the damage or fallout occurred.
<b>Poor</b>	A sprayed material that shows signs of significant damage or is significantly delaminating or deteriorating. This may be limited to surface delamination or some portion of the substrate may be exposed.

In Locations where damage exists in isolated areas, both good and poor condition may be applicable.

The extent of each condition will be recorded. Fair condition is not utilized in the evaluation of ACM sprayed or trowelled fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes.

The evaluation of the above products above ceilings may be limited by the number of observations and by building components such as ducts or full height walls that obstruct the above ceiling observations.

### 2.2 Friable Mechanical or Thermal System Insulation (TSI)

To evaluate the condition of mechanical insulation on vessels, boilers, breeching, ducts, pipes, fan units, equipment etc. the following criteria are applied:

<b>Good</b>	Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor damage (i.e. scuffs or stains), but the jacketing is not penetrated.
<b>Fair</b>	Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges from minor to none. Damage can be repaired.

<b>Poor</b>	Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired. Includes components where insulation may have been removed incompletely.
-------------	---

The evaluation of mechanical insulation may be limited by the number of observations made and building components such as ducts or full height walls that obstruct observations. It is often not possible to observe each foot of mechanical insulation from all angles.

### 2.3 Potentially Friable Materials and Miscellaneous Friable Materials

Potentially friable ACM are products that are basically non-friable while in place but have the potential to generate friable dust upon removal or if significantly disturbed without appropriate procedures. These products may become friable if damaged. Potentially friable materials include materials such as acoustic ceiling tiles and plaster. To evaluate the condition of potentially friable materials, the following criteria are applied:

<b>Good</b>	No significant damage or deterioration. Still serving its intended use as a building material or finish.
<b>Fair</b>	Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked plaster, broken but in place ceiling tile, missing tile or section of plaster etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes.
<b>Poor</b>	Significant deterioration or breaking apart of the material. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material has deteriorated to a point it has become friable. Normally potentially friable ACM in Poor condition is not repairable and requires at least localized removal and replacement.

### 2.4 Non-Friable Materials

Non-friable ACM cover a wide range of products with a wide variation in their tendency to release dust or asbestos fibres to the air. Many of these materials, (particularly where the matrix is an unweathered bitumen, asphalt or tar material) do not release fibres except in very unusual circumstances or during significant disturbance (e.g. use of abrasive power tools). Others with a cementitious matrix (asbestos-cement products) can more readily release dust due to abrasion, demolition, weathering, etc. The potential for asbestos release from non-friable ACM is always lower than from friable ACM. To evaluate the condition of non-friable Materials, the following criteria are applied:

<b>Good</b>	No significant damage or deterioration. Still serving its intended use as a building material or finish.
-------------	--

<b>Fair</b>	Showing signs of some cracking or breakage but is not deteriorating (e.g. cracked vinyl floor tile, missing piece of tile or transite, etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes.
<b>Poor</b>	Significant deterioration or breaking apart of the material to the point at which it cannot be repaired, and it will require at least local removal. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material may have deteriorated to a point where traffic or disturbance may cause it to become friable.

## 2.5 Evaluation of ACM Debris

The identification of the exact location or presence of debris on the top of ceiling tiles is limited by the number of observations made and the presence of building components such as ducts or full height walls that obstruct observations.

The presence of fallen or dislodged ACM is noted separately from the ACM source and is referred to as Debris. Debris may be friable if from a friable ACM source or a badly deteriorated non-friable ACM source. Debris may also be non-friable (such as fallen pieces of transite sheet or mastic fittings, or broken, dislodged floor tiles).

<b>Debris</b>	Debris may be friable or non-friable but is always identified as debris.
---------------	--

## 2.6 Evaluation of Presumed Asbestos-Containing Material (PACM)

Presumed asbestos-containing materials (PACM), are building materials that may contain asbestos but were not sampled or analyzed due to inaccessibility or the need to perform destructive testing to obtain a reasonable sample set. Evaluation of these materials is based on the assumption that these PACM are asbestos-containing.

A list of PACM is provided in the report and they are generally not included in the detailed room by room reports. Typically, they are excluded because they are inaccessible or present in very small quantities. If PACM are evaluated, Pinchin uses the criteria that correspond with the type (and friability) of the material listed above.

### 3.0 EVALUATION OF ACCESSIBILITY

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

<b>Access (A)</b>	Common areas of the building within reach of all building users (approximately 8' - 9' from floor or standard ceiling height). Includes other areas where occupant activities may result in disturbance of material that is not normally within reach from floor level, but may be disturbed by common activities (e.g. gymnasiums, workshops, warehouses).
<b>Access (B)</b>	Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines, and accessible pipe chases.
<b>Access (C) and Visible</b>	Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Only includes ACM that are visible to view without the removal or opening of other building components such as ceiling tiles or service access panels. Visible column on HMIS sheets will say YES.
<b>Access (C) and not Visible</b>	Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Includes ACM that are not visible to view and require the removal of a building component to see, such as ceilings tiles or access panels to view and access. Includes rarely entered crawl spaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. Visible column on HMIS sheets will say NO.
<b>Access (D)</b>	Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc. where demolition of the ceiling, wall or equipment etc. is required to reach the ACM. Material inaccessible due to height or location or is only accessed under unusual situations. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine materials in Access D.

### 4.0 ACTION MATRIX AND DEFINITIONS

Pinchin's evaluation of the viability of a specific asbestos control option is based on the consideration of the friability, condition, accessibility and visibility of a material. The logic used is that damaged ACM located in an area frequently accessed by all building occupants is of a higher priority than damaged ACM located in an infrequently accessed service area. The action matrix considers the potential for fibre release (primarily from friable ACM) and the possible concerns from regulatory bodies and many building occupants to all damaged ACM (including non-friable).

In any building with asbestos, many current regulations require an Asbestos Management Program be implemented. Depending on the condition and the accessibility, more active measures such as repair or removal may be recommended. The following matrix provides guidance for recommended Actions in the absence of renovation or demolition. In the event of construction or maintenance activity which will disturb ACM more aggressive control or removal will be required.

## 4.1 Action Matrix

The following tables outline the action decisions based on the relationship of assessed factors. Table I applies to friable ACM. Table II applies to non-friable ACM.

**Table I Decision Matrix for Friable ACM**

Access	Condition			Debris
	Good	Fair	Poor	
(A)	Action 5 <sup>1</sup>	Action 5 <sup>2</sup>	Action 3	Action 1
(B)	Action 7	Action 6 <sup>3</sup>	Action 3	Action 1
(C) Visible	Action 7	Action 6	Action 3	Action 2
(C) Not Visible	Action 7	Action 7	Action 4	Action 2
(D)	Action 7	Action 7	Action 7	Action 7

**Table II Decision Matrix for Potentially Friable and Non-Friable ACM**

Access	Condition			Debris
	Good	Fair	Poor	
(A)	Action 7	Action 7 <sup>4</sup>	Action 3	Action 1
(B)	Action 7	Action 7	Action 3	Action 1
(C) Visible	Action 7	Action 7	Action 4	Action 2
(C) Not Visible	Action 7	Action 7	Action 4	Action 2
(D)	Action 7	Action 7	Action 7	Action 7

## 4.2 Action Definitions

The following are the definitions in the Action Matrix Table presented above:

### Action Definitions

<b>Action 1</b>	Clean-Up of ACM Debris Restrict access that is likely to cause a disturbance of the ACM Debris and clean up ACM Debris. Utilize appropriate asbestos precautions.
-----------------	--

<sup>1</sup> If friable ACM in access (A)/Good condition is not proactively removed Action 7 (Manage) is recommended.

<sup>2</sup> If friable ACM in access (A)/Fair condition is not proactively removed repair is recommended.

<sup>3</sup> If friable ACM in access (B)/Fair condition is likely to be disturbed after repair proactive removal is recommended.

<sup>4</sup> Action 7 is recommended for all non-friable ACM in Fair condition however some clients may wish to repair or take some action primarily for cosmetic reasons

---

## Action Definitions

---

<b>Action 2</b>	<p>Precautions for Access Which may Disturb ACM Debris</p> <p>Use appropriate means to isolate the debris or to limit entry to the area which may disturb the material. At locations where ACM Debris can remain in place in lieu of removal or clean-up (e.g. Debris on top of ceiling tiles or behind lockable door), Utilize appropriate asbestos precautions to enter the area if this will disturb debris. The precautions will be required until the ACM Debris has been cleaned up.</p>
<b>Action 3</b>	<p>ACM Removal</p> <p>Remove ACM. Utilize asbestos procedures appropriate to the scope of the removal work. Until it is removed, restrict access to the material so it is not disturbed.</p>
<b>Action 4</b>	<p>Precautions for Work Which may Disturb ACM in Poor Condition</p> <p>Utilize appropriate asbestos precautions if ACM may be disturbed by work on or near ACM. This does not require restricting access to the area, only control of work which may contact or disturb the ACM. Removal is the only viable option if work will disturb ACM.</p>
<b>Action 5</b>	<p>Proactive ACM Removal</p> <p>Remove friable ACM where the presence of friable asbestos in Good condition is not desirable. If friable ACM in Fair condition is not removed, then Repair friable ACM.</p>
<b>Action 6</b>	<p>ACM Repair</p> <p>Repair friable ACM in Fair condition which is not likely to be damaged again or disturbed by normal use of the area or room. Pinchin recommends proactive removal if friable ACM is likely to be damaged or disturbed during normal use of the area or room.</p>
<b>Action 7</b>	<p>Asbestos Management Program with Routine Surveillance</p> <p>Implement an Asbestos Management Program, including routine surveillance of ACM. Reassess materials regularly (typically once per year).</p>

---

Master Template: Methodology Annex A to Appendix I Evaluation Criteria, HAZ, January 10, 2020

**APPENDIX IV**  
**Location Summary Report**

**Client:**Upper Canada District School Board  
**Building Name:** Thousand Islands Secondary School  
**Survey Date:** 2011-11-30  
**Building Phases:** A: , C: 1960 , D: 1963 , E: 1967

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Last Re-Assessment:**

Location No.	Name or Description	Area ft <sup>2</sup>	Floor No.	Bldg. Phase	Notes
1	Elevator	50	1	D	
1000	Classroom	955	1	C	
1001	Kitchen	1000	1	C	
1002	Storage	50	1	D	
1003	Freezer	50	1	C	
1004	Storage	25	1	C	
1005	Kitchen Prep	150	1	C	
1006	Storage	25	1	C	
1007	Cafeteria, room no. 100	2000	1	C	
1008	Vestibule	50	1	D	
1009	Kitchen	1142	1	C	
1010	Conference Room	667	1	C	
1011	Cooler	100	1	D	
1012	Washroom	25	1	D	
1013	Storage	100	1	D	
1020	Classroom, room no. 102	864	1	C	
1022	Mechanical Room	61	1	C	
1023	Office	100	1	C	
1030	Student Services, room no. 103	719	1	C	
1031	Staff Lounge	800	1	C	
1032	Washroom	50	1	C	
1033	Washroom	50	1	C	
1035	Office	400	1	C	Location 1034 no longer present, now part of location 1035
1036	Office	100	1	C	
1037	Office	100	1	C	
1038	Office	100	1	C	
1039	Office	100	1	C	
1040	Library, room no. 104	3887	1	E	
1041	Seminar Room	402	1	E	
1042	Office	138	1	E	
1043	Workroom	350	1	E	
1051	Office	100	1	C	
1070	Classroom, room no. 107	675	1	C	
1071	Family Studies, room no. 109	1384	1	C	
1080	Custodian Lunch Room, room no. 110	320	1	C	
1081	Office	50	1	C	
1082	Washroom	40	1	C	
1083	Boiler Room, room no. 108	960	1	C	
1084	Workshop, room no. 108	409	1	C	
1085	Electrical, room no. 108	323	1	C	
1090	Office	1157	1	C	
1091	Corridor	1500	1	C	
1092	Under Stair Storage	100	1	C	
1093	Stairwell	150	1	E	
1094	Electrical Room, room no. 150	87	1	E	
1095	Washroom	86	1	E	
1096	Washroom	100	1	E	
1097	Corridor	1500	1	E	
1098	Vestibule	200	1	C	
1099	Stairwell and Corridor	1000	1	C	
1100	Special Needs	1217	1	C	Formerly Named Developmentally Challenged
1101	Storage	172	1	C	
1102	Washroom	108	1	C	
1110	Drama, room no. 111	1811	1	D	
1112	Office	200	1	D	
1115	Storage	109	1	D	
1120	Classroom, room no. 112	701	1	D	
1150	Drafting, room no. 115	907	1	D	
1170	Music Room, room no. 117	1948	1	D	
1171	Practice Room	75	1	D	
1172	Practice Room	75	1	D	



Location No.	Name or Description	Area ft <sup>2</sup>	Floor No.	Bldg. Phase	Notes
1173	Office	75	1	D	Ceiling open to Location 1170
1190	Classroom	1000	1	D	
1191	Classroom	1000	1	D	
1192	Communication Technology, room no. 119	2724	1	D	
1200	Photography, room no. 120	1627	1	D	
1201	Dark Room	655	1	D	
1220	Woodworking, room no. 122	2339	1	D	Ceiling open to Location 1220
1221	Storage	100	1	D	
1230	Computer Design, room no. 123	483	1	D	
1231	Storage	100	1	D	
1232	Storage	170	1	D	
1233	Classroom	500	1	D	
1240	Woodworking, room no. 124	2964	1	D	
1250	Transportation Technology, room no. 125	4127	1	D	
1251	Storage	150	1	D	
1260	Visual Arts, room no. 126	2733	1	E	
1261	Storage	336	1	E	
1270	Welding Technology, room no. 127	2614	1	E	
1271	Welding Classroom	452	1	E	
1290	Mechanical Room, room no. 129	409	1	E	
1360	Mechanical Room, room no. 136	175	1	D	
1511	Library, room no. 151	1000	1	C	
1530	Workroom, room no. 153	747	1	C	
1710	Mechanical Room, room no. 171	109	1	D	
1711	Mechanical Room	235	1	D	
1721	Storage, room no. 172	328	1	D	
1722	Storage, room no. 172	50	1	D	NO ACCESS
1730	Electrical Room, room no. 173	278	1	D	
1731	Dust Collector Room	156	1	D	
1732	Elevator Machine Room	50	1	D	NO ACCESS
1883	Storage	209	1	C	
1884	Storage	50	1	C	
1885	Storage	224	1	C	
1886	Security/Telecom Equip Room	180	1	C	
1887	Washroom	50	1	C	
1888	Office	50	1	C	
1889	Washroom	100	1	C	
1890	Showers	75	1	C	
1891	Girls Change Room	871	1	C	
1892	Pipe Chase	50	1	C	
1893	Washroom	50	1	C	
1894	Office	50	1	C	
1895	Washroom	200	1	C	
1896	Shower	75	1	C	
1897	Boys Change Room	848	1	C	
1898	Stage	1103	1	C	
1899	Gym A	6351	1	C	
1962	Vestibule and Stairwell	600	1	E	
1963	Storage under Stair	50	1	D	
1964	Stairwell	600	1	D	
1965	Custodial Storage	50	1	D	
1966	Washroom	50	1	D	
1967	Gym D	3165	1	D	
1968	Washroom	30	1	D	
1969	Office	50	1	D	
1970	Washroom	100	1	D	
1971	Shower	50	1	D	
1972	Change Room	745	1	D	
1973	Corridor	6000	1	D	
1974	Corridor	2000	1	D	
1975	Corridor and Stairwell	1500	1	C	

Location No.	Name or Description	Area ft <sup>2</sup>	Floor No.	Bldg. Phase	Notes
1976	Custodial Storage	99	1	C	
1977	Boy's Washroom	303	1	C	
1978	Janitors Room	25	1	C	
1979	Girls Washrooom	276	1	C	
1980	Corridor	5000	1	C	
1981	Passage	75	1	C	
1982	Vestibule	100	1	C	
1983	Corridor	3000	1	C	
1984	Vestibule	75	1	C	
1985	Custodian Storage	50	1	C	
1986	Vestibule	50	1	C	
1987	Washroom	25	1	C	
1988	Health Services	150	1	C	
1989	Office	100	1	C	
1990	Storage	95	1	C	
1991	Copier	269	1	C	
1992	Office	151	1	C	
1993	Waiting	100	1	C	
1994	Office	100	1	C	
1995	Vault	75	1	C	
1996	Office	150	1	C	
1997	Office	245	1	C	
1998	Washroom	25	1	C	
1999	Closet	20	1	C	
2000	Ampitheatre, room no. 200	1665	2	E	
2001	Bood Storage	246	2	C	
2010	Classroom, room no. 201	826	2	E	
2020	Classroom, room no. 202	1351	2	E	
2030	Classroom, room no. 203	713	2	C	
2040	Classroom, room no. 204	1025	2	C	
2050	Classroom, room no. 205	686	2	C	
2070	Classroom, room no. 207	686	2	C	
2080	Classroom, room no. 208	1687	2	C	
2090	Classroom, room no. 209	686	2	C	
2110	Classroom, room no. 211	686	2	C	
2120	Workroom, room no. 212	329	2	C	
2130	Classroom, room no. 213	686	2	C	
2140	Classroom, room no. 214	1636	2	C	
2150	Classroom, room no. 215	710	2	C	
2160	Classroom, room no. 216	1472	2	D	
2161	Storage	258	2	D	
2170	Computer Room, room no. 217	828	2	D	
2171	Office	480	2	D	
2180	Classroom, room no. 218	702	2	D	
2190	Computer Room, room no. 219	730	2	D	
2200	Classroom, room no. 220	696	2	D	
2210	Classroom, room no. 231	725	2	D	
2230	Classroom, room no. 223	730	2	D	
2250	Classroom, room no. 225	675	2	E	
2252	Storage, room no. 225	250	2	E	
2260	Classroom, room no. 226	1005	2	E	
2270	Classroom, room no. 227	677	2	E	
2280	Classroom, room no. 228	678	2	E	
2290	Classroom, room no. 229	680	2	E	
2300	Classroom, room no. 230	688	2	E	
2310	Classroom, room no. 231	680	2	E	
2320	Storage, room no. 232	677	2	E	
2330	Classroom, room no. 233	679	2	E	
2350	Classroom, room no. 235	701	2	E	
2410	Office, room no. 241	290	2	C	
2413	Washroom	0	2	C	
2430	Office, room no. 243	385	2	E	
2440	Office, room no. 244	227	2	E	
2480	Mechanical Room, room no. 248	619	2	D	NO ACCESS
2490	Workroom, room no. 249	435	2	E	
2976	Stairwell	600	2	E	

Location No.	Name or Description	Area ft <sup>2</sup>	Floor No.	Bldg. Phase	Notes
2977	Mechanical Room	186	2	E	
2978	Mechanical Room	81	2	E	
2979	Corridor	6000	2	E	
2980	Stairwell	600	2	D	
2981	Staff Washroom	50	2	D	
2982	Boys Washroom	261	2	D	
2983	Janitor's Room/Pipe Chase	50	2	D	
2984	Girls Washroom	242	2	D	
2985	Corridor	2000	2	D	
2986	Stairwell	500	2	C	
2987	Girls Washroom, room no. 2987	283	2	C	
2988	Pipe Chase	50	2	C	
2989	Boys Washroom	304	2	C	
2990	Custodial Storage	212	2	C	
2991	Corridor	5000	2	C	
2992	Corridor	1500	2	E	
2993	Stairwell	500	2	E	
2994	Custodial Room	59	2	E	
2995	Mechanical Room	85	2	C	
2996	Corridor Ramp and Stairwell	2000	2	C	
2997	Weight Room	2088	2	C	
2998	Bleachers	1510	2	C	
2999	Mechanical Room	413	2	C	
3000	Cafeteria	1649	1	D	
3001	Kitchen Prep	810	1	D	
3002	Classroom	500	1	D	
3003	Office	200	1	C	
3004	Classroom	790	1	D	
3005	Corridor	500	1	E	
3006	Classroom, room no. 206	800	2	C	
3007	Exterior	0	1	E	
3008	Exterior	0	1	C	
3009	Exterior	0	1	D	

## **APPENDIX V**

### **Hazardous Materials Summary Report / Sample Log**

## HAZARDOUS MATERIALS SUMMARY / SAMPLE LOG

Client: Upper Canada District School Board Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: Thousand Islands Secondary School

Survey Date: 2011-11-30

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V0001	Ceiling, Wall   All   Plaster   Plaster	1010,1091,1722,1732,2480	C,D	0	3000	0	100	None Detected	No	
Asbestos	V0002	Wall   All   Drywall And Joint Compound   Drywall Joint Compound	1004,1006,1009,1020,1023,2020,2120,2490,3003	C,E	0	1025	0	0	None Detected	No	
Asbestos	V0003	Piping   All   Aircell   Sweatwrap	1260,1973,2979,2992	D,E	280	0	0	0	None Detected	No	
Asbestos	V0004	Ceiling     Ceiling Tile (mechanically Fastened)   At-3 1 X 1 Mechanically Fastened Ceiling Tiles, Large And Medium Uniform Holes.	1000,1006,1007,1008,1020,1070,1071,1100,1101,1530,1986,1987,1988,1989,1990,1991,2030,2040,2050,2070,2080,2090,2110,2120,2130,2140,2150,2170,2171,2180,2190,2200,2210,2230,2990,3000,3001,3002,3006	C,D	0	25909	0	100	None Detected	No	
Asbestos	V0005	Other, Piping   Debris, All, Rain Water Leader     Sweatwrap	[1892],1081,1082,1084,1090,1091,1270,1511,1883,1885,1886,1975,1978,1981,2430,2985,2988,2991	C,D,E	258	5	0	0	None Detected	No	
Asbestos	V0006	Other, Piping   Debris, All   Parging Cement   Parging Cement	[1892],1022,1080,1081,1082,1084,1085,1091,1097,1099,1101,1115,1170,1191,1192,1200,1220,1233,1240,1250,1260,1270,1290,1530,1711,1721,1883,1885,1962,1964,1973,1974,1975,1978,1980,1981,2250,2260,2270,2290,2300,2310,2320,2440,2480,2977,2979,2985,2990,2991,3005	C,D,E	4	22	732	0	Chrysotile	Yes	F
Asbestos	V0007	Duct   Exhaust   Caposite   Caposite Boiler Exhaust Insulation	[1083]	C	60	0	0	0	Amosite	Yes	F
Asbestos	V0008	Duct   Exhaust   Magnesia Block   Performed Block Insulation	[1083]	C	0	0	6	0	Chrysotile	Yes	F
Asbestos	V0009	Ceiling     Ceiling Tiles (glue-on)   At-4 1 X 1 Glued On Ceiling Tile, Large And Medium Random Pinholes	1030,1031,1032,1033,1035,1036,1037,1038,1039,1051	C	0	2519	0	0	None Detected	No	
Asbestos	V0010	Ceiling   Acoustic Tile   Adhesive/mastic   Ceiling Tile Mastic	1000,1007,1008,1020,1030,1031,1035,1036,1037,1038,1039,1051,1070,1100,1101,1530,1986,1987,1988,1989,1990,1991,3000,3001,3002	C,D	0	12747	0	0	None Detected	No	
Asbestos	V0011	Ceiling     Ceiling Tiles (lay-in)   At-6 2 X 4 Lay In Tile With Textured Finish And Pinholes	[1040],1997	C,E	0	245	0	100	None Detected	No	
Asbestos	V0012	Ceiling   All   Ceiling Tiles (lay-in)   At-7 2 X 4 Lay In Ceiling Tile With Fine Texture Surface	[1091]	C	0	0	0	0	None Detected	No	
Asbestos	V0013	Ceiling     Ceiling Tiles (lay-in)   At-9 2 X 4 Lay In Tiles, Lengthwise Deep Wide Fissures And Pinholes	1998	C	0	25	0	0	None Detected	No	
Asbestos	V0014	Floor   All   Vinyl Floor Tile And Mastic   Vt-7 9 X9 White With Grey Streaks And Mastic	[1989],1995	C	0	820	0	0	Chrysotile	Yes	NF
Asbestos	V0015	Floor     Vinyl Floor Tile And Mastic   Vt-8 9 X9 Teal Floor Tiles And Mastic	[1070],1888,1894	C	0	1139	0	0	Chrysotile	Yes	NF
Asbestos	V0016	Ceiling     Ceiling Tiles (splined)   At-10 1 X 1 Tiles With Fissures And Pinholes	1010,1997	C	0	912	0	0	None Detected	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V0017	Ceiling   All   Ceiling Tiles (splined)   At-12 1 X 1 Tiles With Smooth Textured Finish	1982	C	0	100	0	0	None Detected	No	
Asbestos	V0018	Floor     Vinyl Floor Tile And Mastic   Vt13 9 X9 White With Multicoloured Streaks And Mastic	[1035]	C	0	5	0	0	Chrysotile	Yes	NF
Asbestos	V0019	Floor     Vinyl Floor Tile And Mastic   Vt-14 9 X9 Pinkish Beige With Brown And White Streaks And Mastic	[1070]	C	0	2041	0	0	Chrysotile	Yes	NF
Asbestos	V0020	Ceiling   All   Ceiling Tile (mechanically Fastened)   At-13 1 X 1 Course Texture And Fissures	1110,1112,1115,1710,1965,1966,2983	D	0	568	0	100	None Detected	No	
Asbestos	V0021	Ceiling     Ceiling Tile (mechanically Fastened)   At-15 1 X 1 Tiles With Smooth Surface	1110,1150,2170,2171,2180,2190,2200,2210,2230	D	0	3217	0	100	None Detected	No	
Asbestos	V0022	Floor     Vinyl Floor Tile And Mastic   Vt-15 9 X 9 Grey With White Streaks And Mastic	1710	D	0	109	0	0	Chrysotile	Yes	NF
Asbestos	V0023	Floor     Vinyl Sheet Flooring   Vsf-1 Grey Stone Appearance Vinyl Sheet Flooring And Mastic	1170	D	0	250	0	0	None Detected	No	
Asbestos	V0024	Floor     Vinyl Sheet Flooring   Vsf-2 Large Beige Cubes	1,1261	D,E	0	386	0	0	Chrysotile	Yes	PF
Asbestos	V0025	Floor     Vinyl Sheet Flooring   Vsf-3 Grey Blue And Red Vinyl Sheet Flooring And Mastic	1250	D	0	400	0	0	None Detected	No	
Asbestos	V0026	Other, Piping   Debris, All   Aircell   Aircell Pipe Insulation	[1892]	C	52	2	0	0	Chrysotile	Yes	F
Asbestos	V0027	Floor     Vinyl Floor Tile And Mastic   Vt-16 9 X9 Red With White Streaks And Mastic	[1886]	C,D	0	520	0	0	Chrysotile	Yes	NF
Asbestos	V0028	Floor     Vinyl Floor Tile And Mastic   Vt-17 12 X 12 White With Black And Grey Fleck And Mastic	[1886]	C	0	10	0	0	None Detected	No	
Asbestos	V0029	Ceiling     Ceiling Tile (mechanically Fastened)   At-16 1 X 1 Tiles With Smooth Fissures	2996	C	0	2000	0	0	None Detected	No	
Asbestos	V0030	Floor     Vinyl Floor Tile And Mastic   Vt-19 9 X 9 Brown With Grey And White Streaks And Mastic	[2001]	C,D,E	0	1858	0	0	Chrysotile	Yes	NF
Asbestos	V0031	Floor     Vinyl Sheet Flooring   Vsf-4 Beige Vinyl Sheet Flooring With Large Cubes And Mastic	2020	E	0	1351	0	0	None Detected	No	
Asbestos	V0032	Floor     Vinyl Floor Tile And Mastic   Vt-20 9 X9 Yellow With Brown And White Streaks And Mastic	[2030]	C,D	0	1402	0	0	Chrysotile	Yes	NF
Asbestos	V0033	Floor     Vinyl Floor Tile And Mastic   Vt-21 9 X 9 Green With White Streaks And Mastic	[2230]	D,E	0	483	0	0	Chrysotile	Yes	NF
Asbestos	V0034	Floor     Vinyl Floor Tile And Mastic   Vt-22 9 X 9 Black With White Streaks And Mastic	[2050]	C	0	701	0	0	Chrysotile	Yes	NF
Asbestos	V0035	Floor     Vinyl Floor Tile And Mastic   Vt-23 9 X 9 Blue With White Streaks And Mastic	[2230]	D	0	175	0	0	Chrysotile	Yes	NF
Asbestos	V0036	Ceiling     Ceiling Tiles (lay-in)   At-17 2 X 4	[2252],2250,2260,2270,2280,2290,2300,2310,2320	E	0	14652	0	0	Amosite	Yes	PF

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Textured Finish And Pinholes	2330,2350,2440								
Asbestos	V0037	Floor     Vinyl Floor Tile And Mastic   Vt-24 9 X9 Olive With White And Grey Streaks And Mastic	[2250]	E	0	1858	0	0	Chrysotile	Yes	NF
Asbestos	V0038	Floor     Vinyl Floor Tile And Mastic   Vt-25 9 X9 White With Olive And Grey Streaks And Mastic	[2250]	E	0	2328	0	0	Chrysotile	Yes	NF
Asbestos	V0039	Floor     Vinyl Sheet Flooring   Vsf-5 Vinyl Sheet Flooring With Large Green Cubes	2430	E	0	385	0	0	Chrysotile	Yes	PF
Asbestos	V0040	Floor     Vinyl Floor Tile And Mastic   Vt-26 12 X 12 White With Brown Streaks And Mastic	[2270]	E	0	1708	0	0	Chrysotile	Yes	NF
Asbestos	V0041	Floor     Vinyl Floor Tile And Mastic   Vt-27 12 X 12 Brown With White And Purple Streaks And Mastic	[2270]	E	0	1709	0	0	Chrysotile	Yes	NF
Asbestos	S0042 ABCDEFGH	Floor     Mastic	1009,1012,1013,1040,1090,1094,1120,1200,1201 1260,1886,1989,1992,1994,1998,1999,2000,2410 3004	C,D,E	0	15435	0	0	None Detected	No	
Asbestos	S0043 ABCDEFG	Wall   All   Paint   White	1000,1001,1004,1005,1006,1007,1009,1020,1023 1030,1032,1033,1035,1036,1037,1038,1039,1051 1070,1071,1080,1081,1082,1083,1084,1098,1100 1101,1102,1530,1883,1885,1886,1887,1888,1889 1890,1891,1893,1894,1895,1896,1897,1898,1899 1976,1977,1978,1979,1985,1986,1988,1989,1991 2001,2030,2040,2050,2070,2080,2090,2110,2120 2130,2140,2150,2410,2987,2988,2989,2990,2995 2997,2998,2999,3003,3006	C	0	51400	0	0	None Detected	No	
Asbestos	S0044 ABC	Wall   Door   Caulking   Grey	1009,1170,1200,1233,1250,1260,1270,1898,1981 3001	C,D,E	0	0	10	0	None Detected	No	
Asbestos	S0045 ABC	Wall   Window   Caulking   Light Grey	1009,1010,1020,1023,1030,1031,1035,1070,1090 1110,1112,1120,1150,1170,1191,1192,1200,1220 1233,1240,1250,1260,1270,1992,1994,1996,1997 2000,2020,2030,2040,2050,2070,2080,2090,2110 2120,2130,2140,2150,2160,2170,2171,2180,2190 2200,2210,2230,2250,2252,2260,2270,2280,2290 2300,2310,2320,2330,2350,2430,2440,2490,2976 2980,2993,2998,3003,3004,3006	C,D,E	0	0	207	0	None Detected	No	
Asbestos	S0046 ABC	Wall   Window Liner   Caulking   Butyl Sealant, Black	1009,1170,1190,1270,1967,1975,1982,1990,1991 2985,3001	C,D,E	0	0	43	0	None Detected	No	
Asbestos	S0048 ABCDEFG	Ceiling, Wall, Ceiling, Wall   Bulkhead, All   Drywall And Joint Compound	1012,1110,1171,1172,1190,1191,1192,1200,1201 1220,1221,1230,1232,1964,1973,1974,2161,3002 3004	D	0	6400	0	0	None Detected	No	
Asbestos	S0049 ABCDEFG	Wall     Paint   White	1002,1008,1012,1013,1110,1112,1115,1120,1150 1170,1171,1172,1173,1190,1191,1192,1200,1201 1220,1221,1230,1231,1232,1233,1240,1250,1251 1360,1710,1711,1721,1965,1966,1967,1968,1969 1970,1971,1972,2160,2161,2170,2171,2180,2190 2200,2210,2230,2413,2981,2982,2983,2984,3000	C,D	0	38925	0	0	None Detected	No	



HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
			3001,3004								
Asbestos	S0050 ABC	Ceiling     Ceiling Tiles (lay-in)   2x4 Dense Pinholes And Short/medium Widthwise Fissures, 08/07/20	1002,1012,1013,1090,1996	C,D	0	270	0	0	None Detected	No	
Asbestos	S0051 ABC	Floor     Mastick	1007,1010,1020,1023,1030,1031,1032,1033,1035,1036,1037,1038,1039,1051,1112,1115,1993,1996,1997,2001,2161,2210,2994,3000,3003	C,D,E	0	10091	0	0	None Detected	No	
Asbestos	S0052 ABCDEFG	Ceiling, Wall   Bulkhead, All   Plaster	1001,1003,1023,1092,1250,1251,1360,1721,1730,1971,1972,1981,1984,3003	C,D	0	2120	0	0	Chrysotile	Yes	PF
Asbestos	S0054 ABC	Floor     Mastick	1000,1100,1101,1102,1530,1990,1991,2010,2040,2080,2120,2140,2160,2170,2171,2190,2252,2490,3002,3006	C,D,E	0	15188	0	0	None Detected	No	
Asbestos	S0055 ABCDEFG	Ceiling, Wall, Ceiling, Wall   All, Skylight   Drywall And Joint Compound	1000,1031,1035,1036,1090,1091,1099,1102,1975,1980,1981,1983,1987,1988,1989,1992,1993,1994,2040,2987,2989,2996,3006	C	0	7808	0	0	None Detected	No	
Asbestos	S0056 ABC	Piping   All, Debris   Caposite	1983	C	296	2	0	0	Amosite	Yes	F
Asbestos	S0057 ABCDEFG	Ceiling, Wall, Ceiling, Wall   All   Plaster	1080,1081,1082,1084,1085,1090,1099,1511,1887,1888,1889,1890,1891,1893,1894,1895,1896,1897,1975,1978,1980,1983,1985,1987,1988,1989,1990,1991,1992,1993,1994,1996,1997,1998,1999,2001,2988,2991,2996	C	0	15336	0	0	None Detected	No	
Asbestos	S0058 ABC	Wall   Window Liner   Caulking   Butyl Sealant, Grey	1020,1023,1038,1039,1051,1090,1091,1100,1110,1230,1260,1270,1980,1993,1999,2171,2190,2985,2991,3003,3005	C,D,E	0	0	116	0	Chrysotile	Yes	NF
Asbestos	S0062 ABCDEFG	Ceiling, Wall, Ceiling, Wall   All, Bulkhead   Plaster	1040,1093,1094,1097,1260,1270,1271,1962,2010,2250,2252,2260,2270,2280,2290,2300,2310,2320,2330,2350,2430,2440,2490,2976,2978,2979,2993,3005	E	0	5903	0	0	Chrysotile	Yes	PF
Asbestos	S0063 ABCDEFG	Wall   All   Paint	1040,1041,1042,1043,1093,1094,1095,1096,1097,1260,1261,1270,1271,1290,2000,2010,2020,2250,2252,2260,2270,2280,2290,2300,2310,2320,2330,2350,2430,2440,2490,2976,2977,2978,2992,2993,2994	E	0	30550	0	0	Chrysotile	Yes	NF
Asbestos	S0065 ABCDE	Ceiling, Wall   Bulkhead, All   Drywall And Joint Compound	1040,1041,1094,1270,2020,2252	E	0	2525	0	0	None Detected	No	
Asbestos	S0066 ABC	Wall   Window Liner   Caulking   Butyl Sealant, Grey	1040,1093,2978,2979	E	0	0	32	0	Chrysotile	Yes	NF
Asbestos	S0068 ABC	Floor     Mastick	1041,1042,1043,1070,1110,1150,1511,2030,2050,2070,2090,2110,2130,2150,2180,2200,2230,2250,2260,2270,2280,2290,2300,2310,2320,2330,2350,2440,2978	C,D,E	0	19712	0	0	None Detected	No	
Asbestos	S0069 ABC	Structure     Paint   White	1083	C	0	500	0	0	None Detected	No	
Asbestos	S0070 ABC	Wall   Door   Caulking   White	1084,1101,1192,1220,1240,1967	C,D	0	0	6	0	None	No	



HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
									Detected		
Asbestos	S0071 ABCDE	Wall, Ceiling, Wall   Bulkhead, All   Plaster	1110,1120,1150,1170,1191,1192,1200,1220,1233 1240,1250,1964,1973,1974,2160,2170,2171,2180 2190,2200,2210,2230,2983,2985,3004	D	0	4300	0	0	None Detected	No	
Asbestos	S0073 ABC	Structure   Beam   Fireproofing (cementitious)	2979	E	0	300	0	0	None Detected	No	
Asbestos	S0076 ABC	Wall     Caulking   Butyl Sealant, Black	3007,3008,3009	C,D,E	0	0	0	0	None Detected	No	
Asbestos	S0077 ABC	Wall   Window, Door   Caulking   Grey	3007,3008,3009	C,D,E	156	0	0	0	None Detected	No	
Asbestos	S0078 ABC	Structure   Canopy   Plaster   Textured	3007	E	0	30	0	0	None Detected	No	
Asbestos	S0080 ABC	Structure   Canopy, Soffit   Plaster   Textured, Swirled	3008	C	0	260	0	0	None Detected	No	
Asbestos	S0081 ABC	Structure   Canopy   Plaster   Textured	3009	D	0	220	0	0	Chrysotile	Yes	PF
Asbestos	S0082 ABC	Structure   Canopy   Paint   Beige	3009	D	0	200	0	0	None Detected	No	
Asbestos	S0083 ABC	Wall   Expansion Joint   Caulking   Grey, Hard	3007,3009	D,E	40	0	0	0	Chrysotile	Yes	NF
Asbestos	V9500	Mechanical Equipment   Boiler   Gasket	[1083]	C	0	0	12	0	Presumed Asbestos	Yes	NF
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)	1013	D	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x2 Flecks And Pinholes, 05/21/18	1091	C	0	1000	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling   All   Ceiling Tiles (lay-in)   2x2 Wicker	1899	C	0	6351	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Flecks And Pinholes, Plastic Covering, 03/24/03	1001,1004,1005,1006,1009,1020,1023,3001,3003	C,D	0	4316	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling   All   Ceiling Tiles (lay-in)   2x4 Random Flecks And Pinholes, 03/24/03	1032,1033,1040,1041,1042,1043,1071,1090,1091 1093,1095,1096,1097,1098,1099,1200,1511,1962 1964,1966,1968,1969,1970,1973,1974,1975,1976 1977,1979,1980,1983,1986,1988,1989,1992,1993 1994,1996,1999,2413,2979,2980,2981,2982,2984 2985,2986,2987,2989,2991,2992,2996,2997,3005	C,D,E	0	53339	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling   All   Ceiling Tiles (lay-in)   2x4 Small And Medium Clustered Pinholes, 07/19/94	1000,1002,1007,1010,1030,1031,1035,1036,1037 1038,1039,1051,1070,1081,1082,1100,1110,1112 1120,1150,1170,1192,1200,1220,1230,1231,1232 1233,1240,1250,1251,1260,1270,1271,1290,1530 1886,2000,2001,2010,2020,2030,2040,2050,2070 2080,2090,2110,2120,2130,2140,2150,2160,2161 2170,2171,2180,2190,2200,2210,2230,2410,2990 3000,3001,3002,3004,3006	C,D,E	0	59652	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Small	2410	C	0	90	0	0	Non	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Pinholes And Large Shallow Fissures, 1994							Asbestos		
Asbestos	V0000	Ceiling   All   Ceiling Tiles (lay-in)   2x4 Small Pinholes And Narrow Widthwise Fissures, 09/22/16	1190,1191,1201,1260,1261,2252,2490	D,E	0	5676	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling   All   Ceiling Tiles (lay-in)   2x4 Wicker	2998	C	0	1510	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling   All   Drywall And Joint Compound   Post-2016	1083	C	0	960	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 Beige With Brown And White Smears	1200,1201,1260,1992	C,D,E	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 Beige With Brown, White And Green Flecks	1013	D	0	100	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 Beige With Brown, White And Green Smears	1886	C	0	180	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 Beige With Brown, White And Green Streaks	1012,1989	C,D	0	125	0	0	Non Asbestos	No	
Asbestos	V0000	Floor   All   Vinyl Floor Tile   12x12 Beige With Orange And Green Flecks	1070,1110,1150,1511,2030,2050,2070,2090,2110,2130,2150,2180,2200,2230,2250,2260,2270,2280,2290,2300,2310,2320,2330,2350,2440,2978	C,D,E	0	18822	0	0	Non Asbestos	No	
Asbestos	V0000	Floor   All   Vinyl Floor Tile   12x12 Beige With Orange And Green Streaks	1041,1042,1043	E	0	890	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 Blue	2000	E	0	1665	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 Cream With Beige And White Smears	1000,1100,1101,1102,1530,1990,1991,2010,2040,2080,2120,2140,2160,2170,2171,2190,2252,2490,3002,3006	C,D,E	0	15188	0	0	Non Asbestos	No	
Asbestos	V0000	Floor   All   Vinyl Floor Tile   12x12 Dark Grey With Darker Grey And White Flecks	1090,1994,1998,1999	C	0	1302	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 Light Blue With Grey And White Flecks	1009,1120,3004	C,D	0	2633	0	0	Non Asbestos	No	
Asbestos	V0000	Floor   All   Vinyl Floor Tile   12x12 Light Grey With Dark Grey And White Smears	1007,1010,1020,1023,1030,1031,1035,1036,1037,1038,1039,1051,1112,1115,1993,1996,1997,2001,3000,3003	C,D	0	8949	0	0	Non Asbestos	No	
Asbestos	V0000	Floor   All   Vinyl Floor Tile   12x12 Red	2410	C	0	290	0	0	Non Asbestos	No	
Asbestos	V0000	Floor   All   Vinyl Floor Tile   12x12 Turquoise	1094	E	0	87	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile   12x12 White With Black Flecks	1040	E	0	3887	0	0	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile And Mastic	1009	C	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile And Mastic   12x12 Light Grey With Dark Grey And White Smears	2161,2210	D	0	983	0	0	Non Asbestos	No	
Asbestos	V0000	Floor   All   Vinyl Sheet Flooring   Blue Flecked,	1986,1987,1988	C	0	225	0	0	Non	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Linoleum							Asbestos		
Asbestos	V0000	Wall   Window   Caulking   Grey, Silicone	1040,1041,1042,1043,1081,1530,2996	C,E	0	0	0	0	Non Asbestos	No	
Paint	L0001	Wall   Concrete (precast)   White	1000,1001,1004,1005,1006,1007,1009,1020,1023,1030,1032,1033,1035 1036,1037,1038,1039,1051,1070,1071,1080,1081,1082,1083,1084,1098 1100,1101,1102,1360,1530,1883,1885,1887,1888,1889,1890,1891,1893 1894,1895,1896,1897,1899,1976,1977,1979,1985,1986,1988,1989,1991 2000,2001,2010,2020,2030,2040,2050,2070,2080,2090,2110,2120,2130 2140,2150,2410,2987,2988,2989,2990,2994,2995,2997,2998,3003,3006	C,D,E	0	51650	0	0		No	-
Paint	L0002	Wall   Drywall And Joint Compound   White	1000,1004,1006,1009,1020,1023,1031,1035,1036,1090,1091,1102,1980 1983,1987,1988,1989,1992,1993,1994,2020,2040,2120,2987,2989,2996 3003,3006	C,E	0	8028	0	0		No	-
Paint	L0003	Structure   Metal   Red	1000,1001,1004,1005,1006,1007,1009,1022,1070,1083,1090,1091,1100 1101,1511,1530,1883,1884,1885,1898,1976,1977,1979,1980,1981,1983 1992,1993,1994,1996,1997,1999,2001,2410,2986,2987,2989,2991,2994 2999	C,E	0	30986	0	0	Lead (Low)	Yes	-
Paint	L0004	Wall   Concrete (precast)   White	1002,1008,1012,1013,1110,1112,1115,1150,1170,1171,1172,1173,1190 1191,1192,1220,1221,1230,1231,1232,1233,1240,1250,1251,1710,1711 1965,1966,1967,1968,1969,1970,1971,1972,2160,2161,2170,2171,2180 2190,2200,2210,2230,2981,2982,2983,2984,3000,3001,3004	D	0	33875	0	0		No	-
Paint	L0005	Wall   Drywall And Joint Compound   White	1012,1110,1171,1172,1190,1191,1192,1220,1221,1230,1232,1964,1973 1974,2161,3002,3004	D	0	5200	0	0		No	-
Paint	L0006	Structure   Metal   Red	1002,1008,1012,1013,1110,1112,1115,1120,1150,1170,1190,1191,1192 1200,1201,1220,1230,1231,1232,1233,1240,1250,1251,1711,1963,1964 1968,1969,1970,2160,2161,2170,2171,2180,2190,2200,2210,2230,2980	D	0	36328	0	0	Lead (High)	Yes	-

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
			2981,2982,2984,3000,3001,3002,3004								
Paint	L0007	Ceiling   Plaster   Beige	1360	D	0	175	0	0	Lead (Low)	Yes	-
Paint	L0008	Ceiling   Plaster   White	1001,1003,1010,1080,1081,1082,1084,1085,1099,1511,1888,1889,1890 1891,1894,1895,1896,1897,1975,1978,1983,1984,1985,1987,1988,1989 1990,1991,1992,1993,2001,2988,2991,2996	C	0	11111	0	0	Lead (Low)	Yes	-
Paint	L0009	Floor   Concrete (poured)   Green	1003,1083,1976,1977,1978,1981,1985,2988,2990,2995,2997,2998	C	0	5507	0	0	Lead (Low)	Yes	-
Paint	L0010	Wall   Wood   White	1003	C	0	150	0	0		No	-
Paint	L0011	Floor   Concrete (poured)   Grey	1002,2983	D	0	100	0	0		No	-
Paint	L0012	Wall   Concrete (precast)   Black/beige	1898	C	0	1500	0	0		No	-
Paint	L0013	Wall   Plaster   Grey	1090,1091,1994,1996,1997,1998,1999	C	0	5350	0	0	Lead (Low)	Yes	-
Paint	L0014	Wall   Plaster   Pink	1040,1097	E	0	2000	0	0		No	-
Paint	L0015	Structure   Metal   Red	1040,1041,1042,1043,1093,1095,1096,1097,1260,1261,1290,1962,2000 2010,2250,2252,2260,2270,2280,2290,2300,2310,2320,2330,2350,2440 2490,2976,2977,2979,2992,2993,3005	E	0	31208	0	0	Lead (High)	Yes	-
Paint	L0016	Wall   Concrete (precast)   White	1041,1042,1043,1093,1095,1096,1097,1260,1261,1270,1271,1290,2250 2252,2260,2270,2280,2300,2320,2430,2490,2978,2992	E	0	18400	0	0	Lead (Low)	Yes	-
Paint	L0017	Ceiling   Plaster   White	1093,1094,1260,1270,1271,1962,2010,2250,2252,2260,2270,2280,2290 2300,2310,2320,2330,2350,2430,2440,2490,2976,2978,2979,2993,3005	E	0	3578	0	0	Lead (Low)	Yes	-
Paint	L0018	Wall   Masonry   Purple	1040,1094	E	0	2300	0	0		No	-
Paint	L0019	Wall   Drywall And Joint Compound   Purple	1040,1094	E	0	12019	0	0		No	-
Paint	L0020	Wall   Drywall And Joint Compound   Off-white	1041,1270,2252	E	0	325	0	0		No	-
Paint	L0021	Structure   Concrete (poured)   White	1083	C	0	500	0	0		No	-
Paint	L0022	Wall   Plaster   White	1110,1120,1150,1170,1191,1192,1200,1220,1233,1240,1250,1251,1964 1971,1972,1973,2160,2170,2171,2180,2190,2200,2210,2230,2983,2985 3004	D	0	4450	0	0	Lead (Low)	Yes	-
Paint	L0024	Wall   Concrete (precast)   Green	1200,1201,1721	D	0	2928	0	0		No	-
Paint	L0025	Ceiling   Plaster   Green	1721	D	0	150	0	0	Lead (Low)	Yes	-
Paint	L0027	Wall   Drywall And Joint Compound   Black	1200,1201	D	0	1200	0	0		No	-
Paint	L0028	Floor   Concrete (poured)   Grey	1290,1711	D,E	0	644	0	0	Lead (High)	Yes	-
Paint	L0029	Structure   Plaster   Yellow	3007	E	0	30	0	0		No	-
Paint	L0030	Structure   Plaster   White	3008	C	0	260	0	0		No	-
Paint	L0031	Structure   Plaster   White	3009	D	0	220	0	0	Lead (High)	Yes	-

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Paint	L0032	Structure   Concrete (poured)   Beige	3009	D	0	200	0	0		No	-
Paint	L0033	Structure   Metal   White	3009	D	0	425	0	0	Lead (Low)	Yes	-
Paint	V0000	Ceiling   Drywall And Joint Compound   White, 2016	1083	C	0	960	0	0	-	No	-
Lead Product	V9500	Batteries (other)	1084	C	0	0	0	100	Presumed Lead Product	Yes	-
Lead Product	V9500	Batteries In Emer. Lights	1001,1004,1005,1006,1009,1083,1099,1899,1975,1980,2991	C	0	0	0	100	Presumed Lead Product	Yes	-
Lead Product	V9500	Bell And Spigot Fittings	1008,1080,1115,1233,1511,1969,1978,1980,2080,2991,2997	C,D	0	0	0	100	Presumed Lead Product	Yes	-
PCB	P0001	Caulking	1009,1010,1020,1023,1030,1031,1035,1070,1084,1090,1101,1110,1112 1120,1150,1170,1191,1192,1200,1220,1233,1240,1250,1260,1270,1898 1967,1981,1992,1994,1996,1997,2000,2020,2030,2040,2050,2070,2080 2090,2110,2120,2130,2140,2150,2160,2170,2171,2180,2190,2200,2210 2230,2250,2252,2260,2270,2280,2290,2300,2310,2320,2330,2350,2430 2440,2490,2976,2980,2993,2998,3001,3003,3004,3006	C,D,E	0	0	228	0	-	No	-
PCB	P0002	Caulking   Butyl Sealant, Black	1009,1020,1023,1038,1039,1051,1090,1091,1100,1110,1170,1190,1230 1260,1270,1967,1975,1980,1982,1990,1991,1993,1999,2171,2190,2985 2991,3001,3003,3005	C,D,E	0	0	159	0	-	No	-
PCB	P0003	Caulking   Butyl Sealant, Grey	1040,1093,2978	E	0	0	30	0	-	No	-
PCB	P0004	Caulking   Butyl Sealant, Black	3007,3008,3009	C,D,E	0	0	0	0	-	No	-
PCB	P0005	Caulking   Grey, Window Frames	3007,3008,3009	C,D,E	0	0	0	0	-	No	-
PCB	P0006	Caulking   Grey, Hard, Expansion Joint	3007,3009	D,E	40	0	0	0	-	No	-
PCB	V9500	Light Ballasts	1094,1102,1190,1191,1192,1220,1240,1250,1260,1261,1290,1711,1721 1883,1885,1888,1894,1898,1899,1967,1972,1976,1977,2001,2040,2080 2977,2994,2995,3006	C,D,E	0	0	0	100	Presumed PCB	Yes	-
PCB	V0000	Caulking	1040,1041,1042,1043,1081,1530,2996	C,E	0	0	0	0	-	No	-
PCB	V0000	Light Ballasts	1000,1001,1002,1004,1005,1006,1007,1008,1009,1010,1012,1013,1020 1023,1030,1031,1032,1033,1035,1036,1037,1038,1039,1040,1041,1042	C,D,E	0	0	0	100	-	No	-

## HAZARDOUS MATERIALS SUMMARY / SAMPLE LOG

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
			1043,1051,1070,1071,1080,1081,1082,1083,1084,1090,1093,1095,1096 1097,1098,1099,1100,1101,1110,1112,1115,1120,1150,1170,1171,1172 1173,1200,1201,1230,1231,1232,1233,1251,1270,1271,1511,1530,1889 1890,1891,1895,1896,1897,1962,1964,1966,1968,1969,1970,1973,1974 1975,1979,1982,1986,1987,1988,1989,1990,1991,1992,1993,1994,1996 1997,1998,1999,2000,2010,2020,2030,2050,2070,2090,2110,2120,2130 2140,2150,2160,2161,2170,2171,2180,2190,2200,2210,2230,2250,2252 2260,2270,2280,2290,2300,2310,2320,2330,2350,2410,2430,2440,2490 2976,2978,2979,2980,2981,2982,2984,2985,2987,2988,2989,2990,2992 2993,2996,2997,2998,2999,3000,3001,3002,3003,3004,3005								
PCB	V0000	Transformer	1085,1730	C,D	0	0	0	0	-	No	-
Mould	V9000	Drywall And Joint Compound	1012	D	0	6	0	0	Mould	Yes	-
Mould	V9500	Ceiling Tiles (lay-in)	2160	D	0	16	0	0	Presumed Mould	Yes	-
Hg	V9000	Light Tube	1001,1002,1004,1005,1006,1007,1008,1009,1010,1012,1013,1020,1023 1030,1031,1032,1033,1035,1036,1037,1038,1039,1040,1041,1042,1043 1051,1071,1080,1081,1082,1083,1084,1090,1093,1094,1095,1096,1097 1098,1099,1100,1101,1102,1110,1112,1115,1120,1150,1170,1171,1172 1173,1190,1191,1192,1200,1201,1220,1230,1231,1232,1233,1240,1250 1251,1260,1261,1270,1271,1290,1511,1711,1721,1883,1885,1888,1889 1890,1891,1894,1895,1896,1897,1899,1962,1964,1966,1967,1968,1969 1970,1972,1973,1974,1975,1976,1977,1979,1982,1986,1987,1988,1989 1990,1991,1992,1993,1994,1996,1997,1998,1999,2000,2001,2010,2020 2030,2040,2050,2070,2080,2090,2110,2120,2130,2140,2150,2160,2161 2170,2171,2180,2190,2200,2210,2230,2250,2252,22	C,D,E	0	0	0	100	Hg	Yes	-

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
			60,2270,2280,2290 2300,2310,2320,2330,2350,2410,2430,2440,2490,2976,2977,2978,2979 2980,2981,2982,2984,2985,2987,2988,2989,2990,2992,2993,2994,2995 2996,2997,2998,2999,3000,3001,3003,3004,3005,3006								
Hg	V9500	Boiler Control	1022	C	0	0	0	100	Presumed Hg	Yes	-
Hg	V0000	Thermostat	1220	D	0	0	0	100	-	No	-

## Legend:

Sample number		Units			
S####	Asbestos sample collected	SF	Square feet	NF	Non Friable material.
L####	Paint sample collected	LF	Linear feet	F	Friable material
P####	PCB sample collected	EA	Each	PF	Potentially Friable material
M####	Mould sample collected	%	Percentage		
V####	Material visually similar to numbered sample collected				
V0000	Known non Hazardous Material				
V9000	Material is visually identified as Hazardous Material				
V9500	Material is presumed to be Hazardous Material				
[Loc. No.]	Abated Material				



**APPENDIX VI**  
**HMIS All Data Report**

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1 : Elevator

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Laminate			C	Y										
Floor		Vinyl Sheet Flooring			A	Y		50(7)			SF	V0024	Chrysotile	10-25%	Confirmed Asbestos	PF
Wall	All	Laminate			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1000 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 955

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		955			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		955			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		955			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		955			SF	S0054A	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		955			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Drywall and joint compound		Paint	A	Y		500			SF	S0055A	None Detected	N.D.	None	
Wall		Paint, White			A	Y		300			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1000 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 955

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	300		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	955		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Drywall and joint compound	500		SF	L0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 1 of 353.

# ALL DATA REPORT

**Location: #1000 : Classroom**  
**Survey Date: 2011-11-30**

**Floor: 1**

**School**  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 955**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1001 : Kitchen

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		1000			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Piping	All	Armflex	All Pipe		C	N										
Piping	All	Not Insulated			A	Y										
Structure		Metal		Paint	C	N										
Wall		Paint, White			A	Y		1000			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Plaster			A	Y		50(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1001 : Kitchen

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1000		SF	V0001	White	Pb: 0.0085 %	No	
Wall	Plaster	50		SF	L0008	White	Pb: 0.0339 %	Lead (Low)	
Structure	Metal	1000		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1001 : Kitchen

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1001 : Kitchen

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1001 : Kitchen

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1002 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 dense pinholes and short/medium widthwise fissures			C	Y		25			SF	V0050	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		25			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Concrete (poured)		Paint	A	Y										
Mechanical Equipment		None Found														
Piping	All	Not Insulated			A	Y										
Structure		Metal		Paint	C											
Wall		Paint, White			A	Y		200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1002 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	200		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	50		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Floor	Concrete (poured)	50		SF	L0011	Grey	Pb: 0.0065 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1002 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1002 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1003 : Freezer

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	Y										
Duct		None Found														
Floor	All	Concrete (poured)		Paint	A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Deck	None Found														
Wall		Wood		Paint	A	Y										
Wall		Plaster		Paint	A	Y		100(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (poured)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1003 : Freezer

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Floor	Concrete (poured)	50		SF	L0009	Grey	Pb: 0.0369 %	Lead (Low)	
Wall	Plaster	100		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	
Wall	Wood	100		SF	L0010	White	Pb: 0.0013 %	No	
Ceiling	Wood	50		SF	V0010	White	Pb: 0.0013 %	No	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1004 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		25			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Not Insulated			A	Y										
Structure		Metal		Paint	C	N										
Wall		Paint, White			A	Y		1000			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0002	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1004 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Drywall and joint compound	50		SF	V0002	White	Pb: 0.0005 %	No
Wall	Concrete (precast)	1000		SF	V0001	White	Pb: 0.0085 %	No
Structure	Metal	25		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1004 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1004 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School



**Location: #1004 : Storage**  
**Survey Date: 2011-11-30**

**Floor: 1**

**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 25**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1005 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		150			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Piping	All	Armflex	All Pipe		C	N										
Piping	All	Not Insulated			A	Y										
Structure		Metal		Paint	C	N										
Wall		Paint, White			A	Y		1000			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1005 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1000		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	150		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1005 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1005 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location: #1005 : Kitchen Prep**  
**Survey Date: 2011-11-30**

**Floor: 1**

**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 150**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1006 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		25			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			C	N		100			%	V0004	None Detected	N.D.	None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Not Insulated			A	Y										
Structure		Metal		Paint	C	N										
Wall		Paint, White			A	Y		1000			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0002	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1006 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Drywall and joint compound	50		SF	V0002	White	Pb: 0.0005 %	No
Wall	Concrete (precast)	1000		SF	V0001	White	Pb: 0.0085 %	No
Structure	Metal	25		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1006 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1006 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

## ALL DATA REPORT

**Location: #1006 : Storage**  
**Survey Date: 2011-11-30**

**Floor: 1**

**School**  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 25**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1007 : Cafeteria

**Floor:** 1

**Room #:** 100

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		2000			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		2000			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		2000			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		2000			SF	S0051B	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		2000			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		1200			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1007 : Cafeteria

**Floor:** 1

**Room #:** 100

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1200		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	2000		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1007 : Cafeteria

**Floor:** 1

**Room #:** 100

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1007 : Cafeteria

**Floor:** 1

**Room #:** 100

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1008 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	Y		50			SF	V0004	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		50			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Not Insulated			A	Y										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		100			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1008 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	100		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	50		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1008 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1008 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1008 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50



Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1009 : Kitchen**

**Floor: 1**

**Room #:**

**Area (sqft): 1142**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		1142			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		1142			SF	S0042A	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light blue with grey and white flecks			A	Y		1142			SF	V0000	Non-Asbestos		None	
Floor	All	Rubber			A	Y										
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Piping	All	Armaflex	All Pipe		C	N										
Piping	All	Not Insulated			A	Y										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		1000			SF	S0043A	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0002	None Detected	N.D.	None	
Wall	Door	Caulking, Grey			A	Y		1			EA	S0044A	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		1			EA	S0045A	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, black			A	Y		8			EA	S0046A	None Detected	N.D.	None	

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1009 : Kitchen**

**Floor: 1**

**Room #:**

**Area (sqft): 1142**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	1000		SF	L0001	White	Pb: 0.0085 %	No
Wall	Drywall and joint compound	50		SF	L0002	White	Pb: 0.0005 %	No
Structure	Metal	1142		SF	L0003	Red	Pb: 0.0880 %	Lead (Low)

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1009 : Kitchen**

**Floor: 1**

**Room #:**

**Area (sqft): 1142**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1009 : Kitchen

**Floor:** 1

**Room #:**

**Area (sqft):** 1142

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1009 : Kitchen

**Floor:** 1

**Room #:**

**Area (sqft):** 1142

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	2	EA	P0001	Grey, window/door frames	<5 mg/kg	No
Caulking	8	EA	P0002	Butyl sealant black	<5 mg/kg	No
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1010 : Conference Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 667

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		667			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (splined), 1x1 clustered fissures and pinholes		Ceiling Tiles (lay-in)	C	N		667			SF	V0016	None Detected	N.D.	None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		667			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		667			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Structure		None Found														
Wall	All	Plaster		Paint	A	Y		1000			SF	V0001	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		1			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board  
**Location:** #1010 : Conference Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 667

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	1000		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board  
**Location:** #1010 : Conference Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 667

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board  
**Location:** #1010 : Conference Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 667

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	1	EA	V0001	Grey, window frames	<5 mg/kg	No

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1011 : Cooler

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Metal			C	Y										
Duct		None Found														
Floor	All	Rubber			A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure		None Found														
Wall	All	Metal			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1012 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 dense pinholes and short/medium widthwise fissures, 08/07/20			C	Y		25			SF	S0050AC	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Mastic			D	N		25			SF	S0042B	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown, white and green streaks			A	Y		25			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		50			SF	S0049A	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound			A	Y		100			SF	S0048A	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1012 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Drywall and joint compound	100		SF	L0005	White	Pb: <0.0005 %	No
Wall	Concrete (precast)	50		SF	L0004	White	Pb: 0.0078 %	No
Structure	Metal	25		SF	V0006	Red	Pb: 0.110 %	Lead (High)

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1012 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1012 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1012 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MOULD								
System	Material	Visible	Quantity	Unit	Sample Type	Sample No	Sample Description	Mould
Wall	Drywall And Joint Compound	Y	6	SF	V	9000		Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1013 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 dense pinholes and short/medium widthwise fissures			C	Y		100			SF	S0050B	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	N										
Duct		Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown, white and green flecks			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Fibreglass	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		500			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1013 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	50		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	100		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1013 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1013 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No





# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1020 : Classroom

**Floor:** 1

**Room #:** 102

**Area (sqft):** 864

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		864			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		864			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		864			SF	V0010	None Detected	N.D.	None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		864			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		864			SF	V0000	Non-Asbestos		None	
Floor	All	Rubber			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Structure		None Found														
Structure		None Found														
Wall		Paint, White			A	Y		1000			SF	S0043B	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		200			SF	V0002	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	S0058A	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1020 : Classroom

**Floor:** 1

**Room #:** 102

**Area (sqft):** 864

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	1000		SF	V0001	White		Pb: 0.0085 %	No
Wall	Drywall and joint compound	200		SF	V0002	White		Pb: 0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1020 : Classroom

**Floor:** 1

**Room #:** 102

**Area (sqft):** 864

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1020 : Classroom

**Floor:** 1

**Room #:** 102

**Area (sqft):** 864

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	3	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	1	EA	P0002	Butyl sealant grey	<5 mg/kg	No
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1022 : Mechanical Room

**Floor:** 1

**Room #:**

**Area (sqft):** 61

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Duct		Not Insulated			B	Y										
Floor	All	Concrete (poured)		Paint	B	Y										
Mechanical Equipment	Boiler	1990			B	Y						V0000	Non-Asbestos		None	
Mechanical Equipment	Heating Water Tank	Fibreglass		Metal	B	Y										
Piping	All	Fibreglass	All Pipe	Canvas	B	Y										
Piping	All	Parging Cement	Elbow	Canvas	B	Y		10(7)		5(3)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Not Insulated			B	Y										
Structure		Metal		Paint	C	Y										
Structure	Deck	Concrete (poured)			C	Y										
Wall	All	Concrete (precast)			B	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1022 : Mechanical Room

**Floor:** 1

**Room #:**

**Area (sqft):** 61

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	61		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1022 : Mechanical Room

**Floor:** 1

**Room #:**

**Area (sqft):** 61

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Boiler Control	100	%	V9500	Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1023 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling		Plaster		Ceiling Tiles (lay-in)	C	N		100(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Structure		None Found														
Wall		Paint, White			A	Y		500			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		200			SF	V0002	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		3(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1023 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	500		SF	V0001	White	Pb: 0.0085 %	No	
Wall	Drywall and joint compound	200		SF	V0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1023 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1023 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 28 of 353.

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	3	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	3	EA	V0002	Butyl sealant grey	<5 mg/kg	No
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1030 : Student Services

**Floor:** 1

**Room #:** 103

**Area (sqft):** 719

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		719			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		719			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		719			SF	V0010	None Detected	N.D.	None	
Duct	All	Fibreglass			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		719			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		719			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint			A	Y		2500			SF	V0043	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		5			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1030 : Student Services

**Floor:** 1

**Room #:** 103

**Area (sqft):** 719

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	2500		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1030 : Student Services

**Floor:** 1

**Room #:** 103

**Area (sqft):** 719

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1030 : Student Services

**Floor:** 1

**Room #:** 103

**Area (sqft):** 719

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	5	EA	V0001	Grey, window frames	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1031 : Staff Lounge

**Floor:** 1

**Room #:**

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		800			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		800			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		800			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		800			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		800			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall	All	Drywall and joint compound		Paint	A	Y		1200			SF	S0055G	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1031 : Staff Lounge

**Floor:** 1

**Room #:**

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Drywall and joint compound	1200		SF	L0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1031 : Staff Lounge

**Floor:** 1

**Room #:**

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1031 : Staff Lounge

**Floor:** 1

**Room #:**

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1032 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		50			SF	V0009	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		50			SF	V0051	None Detected	N.D.	None	
Floor	All	Terrazzo			A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		150			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1032 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	150		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1032 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1032 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description		Amount
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1033 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		50			SF	V0009	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		50			SF	V0051	None Detected	N.D.	None	
Floor	All	Terrazzo			A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		150			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1033 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	150		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1033 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1033 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description		Amount
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1035 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 400

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		400			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		400			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		400			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic, 9x9 white with multicolored streaks			A	Y		5			SF	V0018	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		400			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		400			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, White			A	Y		300			SF	V0043	None Detected	N.D.	None	
Wall	All	Drywall and joint compound		Paint	A	Y		500			SF	V0055	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

Location 1034 no longer present, now part of location 1035

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1035 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 400

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Drywall and joint compound	500		SF	V0002	White	Pb: 0.0005 %	No
Wall	Concrete (precast)	300		SF	V0001	White	Pb: 0.0085 %	No

Location 1034 no longer present, now part of location 1035

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1035 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 400

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Location 1034 no longer present, now part of location 1035

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

**Location:** #1035 : Office

**Floor:** 1

**School**

**Room #:**

**Area (sqft):** 400

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Grey, window frames	<5 mg/kg	No

Location 1034 no longer present, now part of location 1035



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1036 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		100			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		100			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, White			A	Y		250			SF	V0043	None Detected	N.D.	None	
Wall	All	Drywall and joint compound		Paint	A	Y		300			SF	V0055	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1036 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Drywall and joint compound	300		SF	V0002	White	Pb: 0.0005 %	No	
Wall	Concrete (precast)	250		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1036 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1036 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

## ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1037 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		100			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		100			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, White			A	Y		250			SF	V0043	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1037 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	250		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1037 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1037 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1038 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		100			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		100			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, White			A	Y		250			SF	V0043	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1038 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	250		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1038 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1038 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0002	Butyl sealant grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1039 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		100			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		100			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Piping	All	None Found														
Wall		Concrete (precast)		Paint	A	Y										
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, White			A	Y		250			SF	V0043	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1039 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	250		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1039 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 46 of 353.

# ALL DATA REPORT

**Location: #1039 : Office**  
**Survey Date: 2011-11-30**

**Floor: 1**

**School**  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 100**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0002	Butyl sealant grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1040 : Library

**Floor:** 1

**Room #:** 104

**Area (sqft):** 3887

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0011	[None]	N.D.	[Abated]	
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			D	Y		3887			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			D	N										
Floor		Mastic		Vinyl Floor Tile	D	N		3887			SF	S0042F	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 white with black flecks			A	Y		3887			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	D	N										
Piping	All	Fibreglass	All Pipe	Paper	D	N										
Structure	Deck	Steel		Paint	C	N										
Structure	Deck	Concrete (poured)			C	N										
Wall		Concrete (precast)		Paint	A	Y										
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, Purple			A	Y		2000(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Drywall and joint compound		Paint	A	Y		2000			SF	V0065	None Detected	N.D.	None	
Wall	All	Plaster		Paint	A	Y		500(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	Window	Caulking, Grey, silicone			A	Y						V0000	Non-Asbestos		None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		18(7)			EA	S0066B	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1040 : Library

**Floor:** 1

**Room #:** 104

**Area (sqft):** 3887

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	3887		SF	V0015	Red	Pb: 0.330 %	Lead (High)
Wall	Plaster	500		SF	V0014	Pink	Pb: 0.0013 %	No
Wall	Drywall and joint compound	2000		SF	L0019	Purple	Pb: 0.0011 %	No
Wall	Concrete (precast)	2000		SF	L0018	Purple	Pb: 0.0082 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1040 : Library

**Floor:** 1

**Room #:** 104

**Area (sqft):** 3887

Survey Date: 2011-11-30

Last Re-Assessment:

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1040 : Library

Floor: 1

Room #: 104

Area (sqft): 3887

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	18	EA	P0003	Butyl sealant, grey	<5 mg/kg	No
Caulking			V0000	Grey, silicone, window frames		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1041 : Seminar Room

**Floor:** 1

**Room #:**

**Area (sqft):** 402

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		402			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		402			SF	S0068A	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green streaks			A	Y		402			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure		Metal			C	N										
Structure	All	Concrete (poured)			C	N		402			SF					
Structure	All	Concrete (poured)			C	N		402			SF					
Wall		Drywall and joint compound		Paint	A	Y		200			SF	S0065D	None Detected	N.D.	None	
Wall		Paint, White			A	Y		300(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Grey, silicone			A	Y						V0000	Non-Asbestos		None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1041 : Seminar Room

**Floor:** 1

**Room #:**

**Area (sqft):** 402

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Drywall and joint compound	200		SF	L0020	Off-white	Pb: <0.0005 %	No	
Structure	Metal	402		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Concrete (precast)	300		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1041 : Seminar Room

**Floor:** 1

**Room #:**

**Area (sqft):** 402

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1041 : Seminar Room

**Floor:** 1

**Room #:**

**Area (sqft):** 402

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking			V0000	Silicone, grey, window frames		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1042 : Office  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 138

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		138			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		138			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green streaks			A	Y		138			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure		Metal			C	N										
Structure	All	Concrete (poured)			C	N		138			SF					
Wall		Paint, White			A	Y		300(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Grey, silicone			A	Y						V0000	Non-Asbestos		None	

**Client:** Upper Canada District School Board  
**Location:** #1042 : Office  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 138

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	138		SF	V0015	Red	Pb: 0.330 %	Lead (High)
Wall	Concrete (precast)	300		SF	V0016	White	Pb: 0.0281 %	Lead (Low)

**Client:** Upper Canada District School Board  
**Location:** #1042 : Office  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 138

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board  
**Location:** #1042 : Office  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 138

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking			V0000	Silicone, grey, window frames		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1043 : Workroom

**Floor:** 1

**Room #:**

**Area (sqft):** 350

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		350			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		350			SF	S0068B	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green streaks			A	Y		350			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure		Metal			C	N										
Structure	All	Concrete (poured)			C	N		350			SF					
Wall		Paint, White			A	Y		600(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Grey, silicone			A	Y						V0000	Non-Asbestos		None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1043 : Workroom

**Floor:** 1

**Room #:**

**Area (sqft):** 350

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	350		SF	V0015	Red	Pb: 0.330 %	Lead (High)
Wall	Concrete (precast)	600		SF	V0016	White	Pb: 0.0281 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1043 : Workroom

**Floor:** 1

**Room #:**

**Area (sqft):** 350

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1043 : Workroom

**Floor:** 1

**Room #:**

**Area (sqft):** 350

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking			V0000	Silicone, grey, window frames		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1051 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole		Ceiling Tiles (lay-in)	C	N		100			SF	V0009	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	D	N		100			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, White			A	Y		250			SF	V0043	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1051 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	250		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1051 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1051 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0002	Butyl sealant grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1070 : Classroom

**Floor:** 1

**Room #:** 107

**Area (sqft):** 675

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium uniform pinhole			C	N		675			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		675			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		675			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Vinyl Floor Tile and Mastic			A	Y		350			SF	V0015	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		325			SF	V0019	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		675			SF	S0068C	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		675			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1070 : Classroom

**Floor:** 1

**Room #:** 107

**Area (sqft):** 675

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	675		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1070 : Classroom

**Floor:** 1

**Room #:** 107

**Area (sqft):** 675

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1071 : Family Studies  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 109  
**Last Re-Assessment:**  
**Area (sqft):** 1384

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes		Ceiling Tiles (lay-in)	C	N		1384			SF	V0004	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		1384			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Rubber			A	Y		1384			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	None Found														
Wall		Paint, White			A	Y		200			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board  
**Location:** #1071 : Family Studies  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 109  
**Last Re-Assessment:**  
**Area (sqft):** 1384

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	200		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board  
**Location:** #1071 : Family Studies  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 109  
**Last Re-Assessment:**  
**Area (sqft):** 1384

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board  
**Location:** #1071 : Family Studies  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 109  
**Last Re-Assessment:**  
**Area (sqft):** 1384

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1080 : Custodian Lunch Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 110  
**Last Re-Assessment:**

**Area (sqft):** 320

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		320			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Rubber			A	Y										
Mechanical Equipment	All	None Found														
Piping		Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		1(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Not Insulated			C	Y										
Structure	All	None Found														
Wall		Paint, White			A	Y		500			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board  
**Location:** #1080 : Custodian Lunch Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 110  
**Last Re-Assessment:**

**Area (sqft):** 320

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	500		SF	V0001	White		Pb: 0.0085 %	No
Ceiling	Plaster	320		SF	V0008	White		Pb: 0.0339 %	Lead (Low)

**Client:** Upper Canada District School Board  
**Location:** #1080 : Custodian Lunch Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 110  
**Last Re-Assessment:**

**Area (sqft):** 320

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board  
**Location:** #1080 : Custodian Lunch Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 110  
**Last Re-Assessment:**

**Area (sqft):** 320

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

# ALL DATA REPORT

**Location: #1080 : Custodian Lunch Room**  
**Survey Date: 2011-11-30**

**Floor: 1**

**Room #: 110**  
**Last Re-Assessment:**

**Area (sqft): 320**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1081 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster		Paint	C	N		50			SF	V0057	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Rubber			A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	N		10(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight	Canvas	C	N		8			LF	V0005	None Detected	N.D.	None	
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Grey, silicone			A	Y						V0000	Non-Asbestos		None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1081 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	50		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1081 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1081 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking			V0000	Grey, silicone, window frames		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1082 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 40

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster		Paint	C	N		40			SF	V0057	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		40			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Rubber			A	Y		40			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight	Unjacketed	C	N			8		LF	V0005	None Detected	N.D.	None	
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1082 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 40

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	40		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1082 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 40

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1082 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 40

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1083 : Boiler Room

**Floor:** 1

**Room #:** 108

**Area (sqft):** 960

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Drywall and joint compound, Post-2016		Paint	C	Y		960			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			B	Y										
Duct	Exhaust	Magnesia block	Fitting	Canvas	B	Y		6			EA	V0008	[None]	10-25%	[Abated]	
Duct	Exhaust	Caposite	Straight	Canvas	B	Y		60			LF	V0007	[None]	10-25%	[Abated]	
Floor	All	Concrete (poured)		Paint	B	Y		960			SF					
Mechanical Equipment	Boiler	2016				Y		3			EA	V0000	Non-Asbestos		None	
Mechanical Equipment	Boiler	Gasket			B	Y		12			EA	V9500	[None]		[Abated]	
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Fibreglass		Polyvinyl chloride (PVC)	B	Y										
Structure		Concrete (poured)		Paint	C	Y										
Structure		Paint, White			C	Y		500			SF	S0069ABC	None Detected	N.D.	None	
Structure	All	Metal		Paint	C	N		960			SF					
Wall		Paint, White			B	Y		1000			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	B	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1083 : Boiler Room

**Floor:** 1

**Room #:** 108

**Area (sqft):** 960

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	960		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Structure	Concrete (poured)	500		SF	L0021	White	Pb: 0.0057 %	No	
Ceiling	Drywall and joint compound	960		SF	V0000	White, 2016		No	
Wall	Concrete (precast)	1000		SF	V0001	White	Pb: 0.0085 %	No	
Floor	Concrete (poured)	960		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1083 : Boiler Room

**Floor:** 1

**Room #:** 108

**Area (sqft):** 960

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1083 : Boiler Room

**Floor:** 1

**Room #:** 108

**Area (sqft):** 960

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1083 : Boiler Room

**Floor:** 1

**Room #:** 108

**Area (sqft):** 960

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1084 : Workshop

**Floor:** 1

**Room #:** 108

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		409			SF	S0057G	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Rubber			A	Y										
Mechanical Equipment	All	None Found														
Piping		Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	N		10(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight	Canvas	C	N		30	10		LF	V0005	None Detected	N.D.	None	
Piping	All	Not Insulated			C	Y										
Structure	All	None Found														
Wall		Paint, White			A	Y		700			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, White			A	Y		1			EA	V0070	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1084 : Workshop

**Floor:** 1

**Room #:** 108

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	700		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	409		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1084 : Workshop

**Floor:** 1

**Room #:** 108

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries (other)	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1084 : Workshop

**Floor:** 1

**Room #:** 108

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1084 : Workshop

**Floor:** 1

**Room #:** 108

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0001	White, door frame	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1085 : Electrical

**Floor:** 1

**Room #:** 108

**Area (sqft):** 323

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		323			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Mechanical Equipment	All	None Found														
Piping		Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	A	Y		18(5)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	A	Y		4(5)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Not Insulated			C	Y										
Structure	All	None Found														
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1085 : Electrical

**Floor:** 1

**Room #:** 108

**Area (sqft):** 323

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description			Hazard
Ceiling	Plaster	323		SF	V0008	White			Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1085 : Electrical

**Floor:** 1

**Room #:** 108

**Area (sqft):** 323

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description		PCB
Transformer			V0000			No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1090 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 1157

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 dense pinholes and short/medium widthwise fissures, 08/07/20			C	Y		20			SF	V0050	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		1157			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		1157			SF	S0042D	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 dark grey with darker grey and white flecks			A	Y		1157			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Sweatwrap	Straight	Unjacketed	C	N			10		LF	V0005	None Detected	N.D.	None	
Structure	All	Metal		Paint	C	N		1157			SF					
Wall		Drywall and joint compound		Paint	A	Y		200			SF	V0055	None Detected	N.D.	None	
Wall	All	Plaster		Paint	A	Y		800			SF	V0057	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		14(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1090 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 1157

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	1157		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Plaster	800		SF	L0013	Grey	Pb: 0.0320 %	Lead (Low)	
Wall	Drywall and joint compound	200		SF	V0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1090 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 1157

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School



## ALL DATA REPORT

**Location: #1090 : Office**  
**Survey Date: 2011-11-30**

**Floor: 1**

**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 1157**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	14	EA	V0002	Butyl sealant grey	<5 mg/kg	No

## ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1091 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		500			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in), 2x2 flecks and pinholes, 05/21/18			C	Y		1000			SF	V0000	Non-Asbestos		None	
Ceiling	All	Ceiling Tiles (lay-in), Textured surface			C	Y						V0012	[None]	N.D.	[Abated]	
Duct	All	Fibreglass		Foil Face	C	N										
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Piping <sup>1</sup>		Parging Cement	Elbow		C	N				1(4)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Sweatwrap	Straight	Canvas	C	N						V0005	None Detected	N.D.	None	
Piping <sup>2</sup>	Debris	Parging Cement			C	N				2(2)	SF	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure		Concrete (poured)			C	N										
Structure	Deck	Metal		Paint	C	N										
Wall		Drywall and joint compound		Paint	A	Y		200			SF	V0055	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										
Wall	All	Plaster		Paint	A	Y		2000			SF	V0001	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		20(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Outside of location 1010

2 - Outside of location 1010

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1091 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	1500		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Plaster	2000		SF	V0013	Grey	Pb: 0.0320 %	Lead (Low)	
Wall	Drywall and joint compound	200		SF	V0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1091 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	20	EA	V0002	Butyl sealant grey	<5 mg/kg	No

## ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1092 : Under Stair Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster			A	Y						V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct		None Found														
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Piping	All	Parging Cement	Fitting	Canvas	A	Y		8		2	EA	V0006	[None]	5-10%	[Abated]	
Piping	All	Sweatwrap	Straight	Canvas	A	Y		10		2	LF	V0005	[None]	N.D.	[Abated]	
Piping	All	Not Insulated			A	Y										
Structure	Not Accessible	None Found														
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1093 : Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		150			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		150			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure		Metal		Paint	C	N										
Structure	All	Concrete (poured)			C	N		150			SF					
Wall		Plaster		Paint	A	Y		25(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall		Paint, White			A	Y		500(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		6(7)			EA	S0066A	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1093 : Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	150		SF	V0015	Red	Pb: 0.330 %	Lead (High)
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)
Wall	Concrete (precast)	500		SF	V0016	White	Pb: 0.0281 %	Lead (Low)

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1093 : Stairwell

Floor: 1

Room #:

Area (sqft): 150

Survey Date: 2011-11-30

Last Re-Assessment:

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1093 : Stairwell

Floor: 1

Room #:

Area (sqft): 150

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	6	EA	P0003	Butyl sealant, grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1094 : Electrical Room

**Floor:** 1

**Room #:** 150

**Area (sqft):** 87

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		87(7)			SF	S0062B	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		87			SF	S0042E	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 turquoise			A	Y		87			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Masonry		Paint	A	Y										
Wall		Paint, Purple			A	Y		300(7)			SF	S0063C	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Drywall and joint compound		Paint	A	Y		100			SF	S0065A	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1094 : Electrical Room

**Floor:** 1

**Room #:** 150

**Area (sqft):** 87

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Ceiling	Plaster	87		SF	L0017	White	Pb: 0.0123 %	Lead (Low)	
Wall	Masonry	300		SF	L0018	Purple	Pb: 0.0082 %	No	
Wall	Drywall and joint compound	10019		SF	L0019	Purple	Pb: 0.0011 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1094 : Electrical Room

**Floor:** 1

**Room #:** 150

**Area (sqft):** 87

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1094 : Electrical Room

**Floor:** 1

**Room #:** 150

**Area (sqft):** 87

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1095 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 86

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		86			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		86			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure		Concrete (poured)			C	N										
Structure	All	Metal		Paint	C	N		86			SF					
Wall		Paint, White			A	Y		500(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1095 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 86

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	500		SF	V0016	White		Pb: 0.0281 %	Lead (Low)
Structure	Metal	86		SF	V0015	Red		Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1095 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 86

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1095 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 86

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1096 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		100			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		100			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure		Concrete (poured)			C	N										
Structure	All	Metal		Paint	C	N		100			SF					
Wall		Paint, White			A	Y		500(7)			SF	S0063B	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1096 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	500		SF	V0016	White		Pb: 0.0281 %	Lead (Low)
Structure	Metal	100		SF	V0015	Red		Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1096 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1096 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1097 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		1500			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		1500			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement, Not jacketed	Elbow	Canvas	C	N		7(7)	20(7)	1(4)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement, Not jacketed	Tee	Canvas	C	N			2(7)		EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure		Metal		Paint	C	N										
Structure	All	Concrete (poured)			C	N		1500			SF					
Wall		Concrete (precast)		Paint	A	Y										
Wall		Paint, White			A	Y		2000(7)			SF	S0063A	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Plaster		Paint	A	Y		1500(7)			SF	S0062A	Chrysotile	0.5-5%	Confirmed Asbestos	PF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1097 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	1500		SF	L0014	Pink	Pb: 0.0013 %	No	
Structure	Metal	1500		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Concrete (precast)	2000		SF	L0016	White	Pb: 0.0281 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1097 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1097 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 81 of 353.

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1098 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		200			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		200			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal			C	N		200			SF					
Wall		Paint, White			A	Y		100			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1098 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	100		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1098 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1098 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1099 : Stairwell and Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		900			SF	V0000	Non-Asbestos		None	
Ceiling		Plaster		Paint	C	Y		100			SF	V0057	None Detected	N.D.	None	
Duct		None Found														
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	N		6(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Concrete (poured)			C	N										
Wall		Drywall and joint compound			C	N		400			SF	S0055C	None Detected	N.D.	None	
Wall		Ceramic Tiles			A	Y										
Wall	All	Concrete (precast)			A	Y										
Wall	All	Plaster		Paint	A	Y		400			SF	V0057	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1099 : Stairwell and Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Ceiling	Plaster	100		SF	V0008	White	Pb: 0.0339 %	Lead (Low)
Wall	Plaster	400		SF	V0008	White	Pb: 0.0339 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1099 : Stairwell and Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1099 : Stairwell and Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1099 : Stairwell and Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1100 : Special Needs

**Floor:** 1

**Room #:**

**Area (sqft):** 1217

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium uniform pinhole			C	N		1217			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1217			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		1217			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		1217			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		1217			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		1500			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

Formerly Named Developmentally Challenged

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1100 : Special Needs

**Floor:** 1

**Room #:**

**Area (sqft):** 1217

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1500		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	1217		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

Formerly Named Developmentally Challenged

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1100 : Special Needs

**Floor:** 1

**Room #:**

**Area (sqft):** 1217

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Formerly Named Developmentally Challenged

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

# ALL DATA REPORT

**Location: #1100 : Special Needs**  
**Survey Date: 2011-11-30**

**Floor: 1**

**School**  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 1217**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0002	Butyl sealant grey	<5 mg/kg	No

Formerly Named Developmentally Challenged



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1101 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 172

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium uniform pinhole			C	N		172			SF	V0004	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		172			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		172			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		172			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		Parging Cement	Elbow	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		600			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, White			A	Y		1			EA	S0070A	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1101 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 172

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description			Hazard
Wall	Concrete (precast)	600		SF	V0001	White			No
Structure	Metal	172		SF	V0003	Red			Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1101 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 172

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1101 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 172

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	P0001	White, door frame	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1102 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 108

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Drywall and joint compound		Paint	C	Y		108			SF	S0055E	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		90			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		90			SF	V0000	Non-Asbestos		None	
Floor	All	Ceramic Tiles			A	Y		108			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1102 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 108

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Drywall and joint compound	103		SF	L0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1102 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 108

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1102 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 108

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts	100	%	V9500	T12	Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1110 : Drama

**Floor:** 1

**Room #:** 111

**Area (sqft):** 1811

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened)			C	N		100			%	V0021	None Detected	N.D.	None	
Ceiling <sup>1</sup>		Ceiling Tile (mechanically fastened), 1x1 coarse fissures			C	N		100			%	V0020	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1811			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		1811			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		1811			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		1811			SF					
Wall		Drywall and joint compound		Paint	A	Y		200			SF	V0048	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		1200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

1 - Sampled in location 1111 (location no longer present)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1110 : Drama

**Floor:** 1

**Room #:** 111

**Area (sqft):** 1811

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)
Wall	Concrete (precast)	1200		SF	V0004	White	Pb: 0.0078 %	No
Wall	Drywall and joint compound	200		SF	V0005	White	Pb: <0.0005 %	No
Structure	Metal	1811		SF	V0006	Red	Pb: 0.110 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1110 : Drama

**Floor:** 1

**Room #:** 111

**Area (sqft):** 1811

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1110 : Drama

**Floor:** 1

**Room #:** 111

**Area (sqft):** 1811

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	1	EA	V0002	Butyl sealant grey	<5 mg/kg	No

# ALL DATA REPORT

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1112 : Office**

**Floor: 1**

**Room #:**

**Area (sqft): 200**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened), 1x1 coarse fissures			C	N		200			SF	V0020	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		200			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		200			SF	V0051	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		200			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		200			SF					
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		1			EA	V0045	None Detected	N.D.	None	

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1112 : Office**

**Floor: 1**

**Room #:**

**Area (sqft): 200**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No
Structure	Metal	200		SF	V0006	Red	Pb: 0.110 %	Lead (High)

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1112 : Office**

**Floor: 1**

**Room #:**

**Area (sqft): 200**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1112 : Office**

**Floor: 1**

**Room #:**

**Area (sqft): 200**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1115 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 109

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened), 1x1 coarse fissures			C	N		109			SF	V0020	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		109			SF	V0051	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		109			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		12(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Joint	Canvas	C	Y		2(7)		1(3)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	End	Canvas	A	Y		1(5)		1(3)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		109			SF					
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1115 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 109

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	800		SF	V0004	White		Pb: 0.0078 %	No
Structure	Metal	109		SF	V0006	Red		Pb: 0.110 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1115 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 109

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School



# ALL DATA REPORT

**Location: #1115 : Storage**  
**Survey Date: 2011-11-30**

**Floor: 1**

**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 109**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1115 : Storage**  
**Survey Date: 2011-11-30**

**Floor: 1**

**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 109**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1120 : Classroom

**Floor:** 1

**Room #:** 112

**Area (sqft):** 701

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		701			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		701			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light blue with grey and white flecks			A	Y		701			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		701			SF					
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		5			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1120 : Classroom

**Floor:** 1

**Room #:** 112

**Area (sqft):** 701

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	
Structure	Metal	701		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1120 : Classroom

**Floor:** 1

**Room #:** 112

**Area (sqft):** 701

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1120 : Classroom

**Floor:** 1

**Room #:** 112

**Area (sqft):** 701

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	5	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1150 : Drafting

**Floor:** 1

**Room #:** 115

**Area (sqft):** 907

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		907			SF	V0021	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		907			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		907			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		907			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		907			SF					
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		1200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1150 : Drafting

**Floor:** 1

**Room #:** 115

**Area (sqft):** 907

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	
Wall	Concrete (precast)	1200		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	907		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1150 : Drafting

**Floor:** 1

**Room #:** 115

**Area (sqft):** 907

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1150 : Drafting

**Floor:** 1

**Room #:** 115

**Area (sqft):** 907

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1170 : Music Room

**Floor:** 1

**Room #:** 117

**Area (sqft):** 1948

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1948			SF	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Plaster		Paint	C	Y		200			SF	V0071	None Detected	N.D.	None	
Duct	All	Not Insulated			C	Y										
Floor		Vinyl Sheet Flooring, Large grey stone appearance			A	Y		250			SF	V0023	None Detected		None	
Floor	All	Wood			A	Y		1948			SF					
Mechanical Equipment	Air Handling Unit	Not Insulated			C	Y										
Mechanical Equipment	Air Handling Unit	Not Insulated			A	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		14(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		1948			SF					
Wall		Paint, White			A	Y		2000			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, Grey			A	Y		1			EA	S0044C	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Black, butyl sealant			A	Y		2			EA	S0046C	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1170 : Music Room

**Floor:** 1

**Room #:** 117

**Area (sqft):** 1948

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Ceiling	Plaster	200		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	
Wall	Concrete (precast)	2000		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	1948		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1170 : Music Room

**Floor:** 1

**Room #:** 117

**Area (sqft):** 1948

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1170 : Music Room

Floor: 1

Room #: 117

Area (sqft): 1948

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	P0001	Grey, window/door frames	<5 mg/kg	No
Caulking	2	EA	P0002	Butyl sealant, black	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1171 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Drywall and joint compound		Paint	C	Y		75			SF	V0048	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Wood			A	Y		75			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		300			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1171 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Ceiling	Drywall and joint compound	75		SF	V0005	White	Pb: <0.0005 %	No	
Wall	Concrete (precast)	300		SF	V0004	White	Pb: 0.0078 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1171 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1171 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1172 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Drywall and joint compound		Paint	C	Y		75			SF	V0048	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Wood			A	Y		75			SF					
Mechanical Equipment	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		300			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1172 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Ceiling	Drywall and joint compound	75		SF	V0005	White	Pb: <0.0005 %	No	
Wall	Concrete (precast)	300		SF	V0004	White	Pb: 0.0078 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1172 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1172 : Practice Room

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1173 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct	All	None Found														
Floor	All	Wood			A	Y		75			SF					
Mechanical Equipment	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		300			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

Ceiling open to Location 1170

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1173 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	300		SF	V0004	White	Pb: 0.0078 %	No	

Ceiling open to Location 1170

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1173 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Ceiling open to Location 1170

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1173 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

Ceiling open to Location 1170

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1190 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small pinholes and narrow widthwise fissures, 09/22/16			C	Y		1000			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Wood			A	Y		1000			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N		1000			SF					
Wall		Drywall and joint compound		Paint	A	Y		600			SF	S0048F	None Detected	N.D.	None	
Wall		Paint, White			A	Y		600			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window Liner	Caulking, Black, butyl sealant			A	Y		4			EA	V0046	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1190 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	600		SF	V0004	White	Pb: 0.0078 %	No	
Wall	Drywall and joint compound	600		SF	V0005	White	Pb: <0.0005 %	No	
Structure	Metal	1000		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1190 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1190 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	4	EA	V0002	Butyl sealant, black	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1191 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small pinholes and narrow widthwise fissures, 09/22/16			C	Y		1000			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Wood			A	Y		1000			SF					
Mechanical Equipment	Air Handling Unit	Not Insulated			C	Y										
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		10(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	None Found														
Structure	All	Metal		Paint	C	N		1000			SF					
Wall		Drywall and joint compound		Paint	A	Y		600			SF	V0048	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		600			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1191 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	600		SF	V0004	White	Pb: 0.0078 %	No	
Wall	Drywall and joint compound	600		SF	V0005	White	Pb: <0.0005 %	No	
Structure	Metal	1000		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1191 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

# ALL DATA REPORT

**Location: #1191 : Classroom**
**Floor: 1**
**Room #:**
**Area (sqft): 1000**
**Survey Date: 2011-11-30**
**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	4	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1192 : Communication Technology  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 119  
**Area (sqft):** 2724  
**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		2724			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Wood			A	Y		2724			SF					
Mechanical Equipment	Air Handling Unit	Not Insulated			C	Y										
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		12(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		5(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		2724			SF					
Wall		Drywall and joint compound		Paint	A	Y		500			SF	S0048C	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		1100			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, White			A	Y		1			EA	S0070B	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board  
**Location:** #1192 : Communication Technology  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 119  
**Area (sqft):** 2724  
**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	1100		SF	V0004	White	Pb: 0.0078 %	No
Structure	Metal	2724		SF	V0006	Red	Pb: 0.110 %	Lead (High)
Wall	Drywall and joint compound	500		SF	L0005	White	Pb: <0.0005 %	No
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)

**Client:** Upper Canada District School Board  
**Location:** #1192 : Communication Technology  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 119  
**Area (sqft):** 2724  
**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1192 : Communication Technology

**Floor:** 1

**Room #:** 119

**Area (sqft):** 2724

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	1	EA	P0001	White, door frame	<5 mg/kg	No
Caulking	3	EA	V0001	Grey, window frames	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1200 : Photography

**Floor:** 1

**Room #:** 120

**Area (sqft):** 1627

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			D	Y		627			SF	V0000	Non-Asbestos		None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			D	Y		1000			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor		Mastic		Vinyl Floor Tile	D	N		1627			SF	S0042C	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown and white smears			A	Y						V0000	Non-Asbestos		None	
Mechanical Equipment	Air Handling Unit	Not Insulated			C	Y										
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		11(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		3(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		1627			SF					
Wall		Drywall and joint compound		Paint	A	Y		600			SF	V0048	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, Black			A	Y		1200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, Grey			A	Y		1			EA	V0044	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1200 : Photography

**Floor:** 1

**Room #:** 120

**Area (sqft):** 1627

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1200		SF	L0024	Black	Pb: 0.0021 %	No	
Wall	Drywall and joint compound	600		SF	L0027	Black	Pb: 0.0066 %	No	
Structure	Metal	1627		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1200 : Photography

**Floor:** 1

**Room #:** 120

**Area (sqft):** 1627

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1200 : Photography

Floor: 1

Room #: 120

Area (sqft): 1627

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey, window/door frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1201 : Dark Room

**Floor:** 1

**Room #:**

**Area (sqft):** 655

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small pinholes and narrow widthwise fissures, 09/22/16			D	Y		655			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor		Mastic		Vinyl Floor Tile	D	N		655			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown and white smears			A	Y						V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass			C	Y										
Structure	All	Metal		Paint	C	N		655			SF					
Wall		Drywall and joint compound		Paint	A	Y		600			SF	V0048	None Detected	N.D.	None	
Wall		Paint, Black			A	Y		500			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1201 : Dark Room

**Floor:** 1

**Room #:**

**Area (sqft):** 655

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	500		SF	V0024	Black	Pb: 0.0021 %	No	
Wall	Drywall and joint compound	600		SF	V0027	Black	Pb: 0.0066 %	No	
Structure	Metal	655		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1201 : Dark Room

**Floor:** 1

**Room #:**

**Area (sqft):** 655

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1201 : Dark Room

**Floor:** 1

**Room #:**

**Area (sqft):** 655

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1220 : Woodworking

**Floor:** 1

**Room #:** 122

**Area (sqft):** 2339

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		2339			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Wood			A	Y		2339			SF					
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		10(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		1(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		2339			SF					
Wall		Drywall and joint compound		Paint	A	Y		300			SF	S0048G	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		1100			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, White			A	Y		1			EA	V0070	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1220 : Woodworking

**Floor:** 1

**Room #:** 122

**Area (sqft):** 2339

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1100		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	2339		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Drywall and joint compound	300		SF	V0005	White	Pb: <0.0005 %	No	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1220 : Woodworking

**Floor:** 1

**Room #:** 122

**Area (sqft):** 2339

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes
Thermostat	100	%	V0000	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

# ALL DATA REPORT

**Location: #1220 : Woodworking**  
**Survey Date: 2011-11-30**

**Floor: 1**

**School**  
**Room #: 122**  
**Last Re-Assessment:**

**Area (sqft): 2339**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	1	EA	V0001	White, door frame	<5 mg/kg	No
Caulking	3	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1221 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Duct	All	None Found														
Floor	All	Concrete (poured)			A	Y		100			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Concrete (precast)			A	Y										
Wall		Paint, White			A	Y		300			SF	V0049	None Detected	N.D.	None	
Wall	All	Drywall and joint compound		Paint	A	Y		300			SF	V0048	None Detected	N.D.	None	

Ceiling open to Location 1220

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1221 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Drywall and joint compound	300		SF	V0005	White	Pb: <0.0005 %	No
Wall	Concrete (precast)	300		SF	V0004	White	Pb: 0.0078 %	No

Ceiling open to Location 1220

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1230 : Computer Design

**Floor:** 1

**Room #:** 123

**Area (sqft):** 483

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		483			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Wood			A	Y		483			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		483			SF					
Wall		Drywall and joint compound		Paint	A	Y		250			SF	S0048E	None Detected	N.D.	None	
Wall		Paint, White			A	Y		700			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window Liner	Caulking, Grey, butyl sealant			A	Y		4(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1230 : Computer Design

**Floor:** 1

**Room #:** 123

**Area (sqft):** 483

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	700		SF	V0004	White	Pb: 0.0078 %	No	
Wall	Drywall and joint compound	250		SF	V0005	White	Pb: <0.0005 %	No	
Structure	Metal	483		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1230 : Computer Design

**Floor:** 1

**Room #:** 123

**Area (sqft):** 483

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1230 : Computer Design

**Floor:** 1

**Room #:** 123

**Area (sqft):** 483

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No
Caulking	4	EA	V0002	Grey, butyl sealant	<5 mg/kg





# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1231 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		100			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Wood			A	Y		100			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		100			SF					
Wall		Paint, White			A	Y		500			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1231 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	500		SF	V0004	White	Pb: 0.0078 %	No
Structure	Metal	100		SF	V0006	Red	Pb: 0.110 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1231 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1231 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1232 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 170

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		170			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Wood			A	Y		170			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		170			SF					
Wall		Drywall and joint compound		Paint	A	Y		250			SF	V0048	None Detected	N.D.	None	
Wall		Paint, White			A	Y		500			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1232 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 170

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	500		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	170		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Drywall and joint compound	250		SF	V0005	White	Pb: <0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1232 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 170

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1232 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 170

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1233 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			D	Y		1000			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor		Concrete (poured)			A	Y										
Mechanical Equipment	Air Handling Unit	Not Insulated			C	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		12(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		5(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		500			SF					
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		1200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, Grey			A	Y		1			EA	V0044	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1233 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1200		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	500		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1233 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1233 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 500

Survey Date: 2011-11-30

Last Re-Assessment:

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary  
School

Location: #1233 : Classroom

Floor: 1

Room #:

Area (sqft): 500

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	1	EA	P0001	Grey, door frame	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1240 : Woodworking

**Floor:** 1

**Room #:** 124

**Area (sqft):** 2964

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		2964			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Wood			A	Y		2964			SF					
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		12(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		5(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		2964			SF					
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		1100			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, White			A	Y		1			EA	S0070C	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1240 : Woodworking

**Floor:** 1

**Room #:** 124

**Area (sqft):** 2964

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1100		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	2964		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1240 : Woodworking

**Floor:** 1

**Room #:** 124

**Area (sqft):** 2964

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1240 : Woodworking

**Floor:** 1

**Room #:** 124

**Area (sqft):** 2964

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	1	EA	V0001	White, door frame	<5 mg/kg	No
Caulking	2	EA	V0001	Grey, window frames	<5 mg/kg	No

## ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1250 : Transportation Technology  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 125  
**Last Re-Assessment:**

**Area (sqft):** 4127

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		4127			SF	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Plaster		Paint	C	Y		200(7)			SF	S0052G	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	Not Insulated			C	Y										
Floor		Vinyl Sheet Flooring, Small grey stone appearance			A	Y		400			SF	V0025	None Detected		None	
Floor	All	Concrete (poured)			A	Y		4127			SF					
Mechanical Equipment	Air Handling Unit	Not Insulated			C	Y										
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		15(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	Y		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		4127			SF					
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		2400			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, Light grey			A	Y		1			EA	V0044	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board  
**Location:** #1250 : Transportation Technology  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 125  
**Last Re-Assessment:**

**Area (sqft):** 4127

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	2400		SF	V0004	White		Pb: 0.0078 %	No
Structure	Metal	4127		SF	V0006	Red		Pb: 0.110 %	Lead (High)
Wall	Plaster	50		SF	V0022	White		Pb: 0.0092 %	Lead (Low)
Ceiling	Plaster	200		SF	V0022	White		Pb: 0.0092 %	Lead (Low)

**Client:** Upper Canada District School Board  
**Location:** #1250 : Transportation Technology  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 125  
**Last Re-Assessment:**

**Area (sqft):** 4127



MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1250 : Transportation Technology

Floor: 1

Room #: 125

Area (sqft): 4127

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	1	EA	V0001	White, door frame	<5 mg/kg	No
Caulking	4	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1251 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		150			SF	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Plaster		Paint	C	Y		50(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Floor	All	Wood			A	Y		150			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		150			SF					
Wall		Paint, White			A	Y		500			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1251 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	500		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	150		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Ceiling	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1251 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1251 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1260 : Visual Arts

**Floor:** 1

**Room #:** 126

**Area (sqft):** 2733

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small pinholes and narrow widthwise fissures, 09/22/16			D	Y		2000			SF	V0000	Non-Asbestos		None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		733			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			D	N										
Floor		Mastic		Vinyl Floor Tile	D	N		2733			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown and white smears			A	Y						V0000	Non-Asbestos		None	
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		5(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Aircell	Straight	Sweatwrap	C	Y				10	LF	V0003	None Detected	N.D.	None	
Structure	All	Metal		Paint	D	N		2733			SF					
Wall		Concrete (precast)		Paint	A	Y										
Wall		Plaster		Paint	A	Y		500(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall		Masonry		Paint	A	Y										
Wall		Paint, White			A	Y		1600(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Door	Caulking, Light grey			A	Y		1			EA	V0044	None Detected	N.D.	None	
Wall	Window	Caulking, Grey			A	Y		8			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Grey, butyl sealant			A	Y		14(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1260 : Visual Arts

**Floor:** 1

**Room #:** 126

**Area (sqft):** 2733

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Masonry	600		SF	V0016	White		Pb: 0.0281 %	Lead (Low)
Wall	Concrete (precast)	1000		SF	V0016	White		Pb: 0.0281 %	Lead (Low)
Wall	Plaster	500		SF	V0017	White		Pb: 0.0123 %	Lead (Low)
Structure	Metal	2733		SF	V0015	Red		Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1260 : Visual Arts

**Floor:** 1

**Room #:** 126

**Area (sqft):** 2733

Survey Date: 2011-11-30

Last Re-Assessment:

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1260 : Visual Arts

Floor: 1

Room #: 126

Area (sqft): 2733

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	1	EA	V0001	Light grey, door frame	<5 mg/kg	No
Caulking	8	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	14	EA	V0002	Grey, butyl sealant	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1261 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 336

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small pinholes and narrow widthwise fissures, 09/22/16			D	Y		336			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			D	N										
Floor		Vinyl Sheet Flooring, Large brown cubes			A	Y		336(7)			SF	V0024	Chrysotile	10-25%	Confirmed Asbestos	PF
Mechanical Equipment		None Found														
Piping	All	Fibreglass			C	Y										
Structure	All	Metal		Paint	D	N		336			SF					
Wall		Concrete (precast)		Paint	A	Y										
Wall		Masonry		Paint	A	Y										
Wall		Paint, White			A	Y		600(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1261 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 336

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Masonry	200		SF	V0016	White		Pb: 0.0281 %	Lead (Low)
Wall	Concrete (precast)	400		SF	V0016	White		Pb: 0.0281 %	Lead (Low)
Structure	Metal	336		SF	V0015	Red		Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1261 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 336

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1261 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 336

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description		Amount
Light Ballasts	100	%	V9500	T12		Presumed



# ALL DATA REPORT

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1270 : Welding Technology**

**Floor: 1**

**Room #: 127**

**Area (sqft): 2614**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		2614			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Concrete (poured)			A	Y		2614			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	N		5(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Elbow	Canvas	C	N		5(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight		C	N				10	LF	V0005	None Detected	N.D.	None	
Structure	All	Metal		Paint	C	N		2614			SF					
Wall		Concrete (precast)		Paint	A	Y										
Wall		Drywall and joint compound		Paint	C	Y		50			SF	S0065B	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		500(7)			SF	S0062D	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall		Masonry		Paint	A	Y										
Wall		Paint, White			A	Y		1600(7)			SF	S0063D	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Plaster		Paint	A	Y		400(7)			SF	S0062C	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	Door	Caulking, Light grey			A	Y		1			EA	V0044	None Detected	N.D.	None	
Wall	Window	Caulking, Grey			A	Y		4			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, black			A	Y		1			EA	V0046	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Grey, butyl sealant			A	Y		16(7)			EA	S0058C	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1270 : Welding Technology**

**Floor: 1**

**Room #: 127**

**Area (sqft): 2614**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Masonry	600		SF	L0016	White	Pb: 0.0281 %	Lead (Low)
Wall	Concrete (precast)	1000		SF	V0016	White	Pb: 0.0281 %	Lead (Low)
Wall	Drywall and joint compound	50		SF	V0020	Off-white	Pb: <0.0005 %	No
Wall	Plaster	500		SF	L0017	White	Pb: 0.0123 %	Lead (Low)

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary**

# ALL DATA REPORT

**Location: #1270 : Welding Technology**      **Floor: 1**      **School**  
**Survey Date: 2011-11-30**      **Room #: 127**      **Area (sqft): 2614**  
**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client: Upper Canada District School Board**      **Site: 2510 Parkedale Avenue, Brockville, ON**      **Building Name: 36 : Thousand Islands Secondary**  
**Location: #1270 : Welding Technology**      **Floor: 1**      **School**  
**Survey Date: 2011-11-30**      **Room #: 127**      **Area (sqft): 2614**  
**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0001	Light grey, door frame	<5 mg/kg	No
Caulking	4	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	17	EA	V0002	Black and grey, butyl sealant	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1271 : Welding Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 452

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		452			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Concrete (poured)			A	Y		452			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	Y										
Structure	All	Metal		Paint	C	N		452			SF					
Wall		Concrete (precast)		Paint	A	Y										
Wall		Plaster		Paint	A	Y		10(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall		Masonry		Paint	A	Y										
Wall		Paint, White			A	Y		450(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1271 : Welding Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 452

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Masonry	250		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Wall	Concrete (precast)	250		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Wall	Plaster	10		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1271 : Welding Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 452

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1271 : Welding Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 452

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1290 : Mechanical Room

**Floor:** 1

**Room #:** 129

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		409			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Concrete (poured)		Paint	B	Y		409			SF					
Mechanical Equipment	Compressor	Not Insulated			B	Y										
Mechanical Equipment	Unit Heater	Not Insulated			B	Y										
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		409			SF					
Wall		Paint, White			B	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	B	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1290 : Mechanical Room

**Floor:** 1

**Room #:** 129

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Floor	Concrete (poured)	409		SF	L0028	Grey	Pb: 0.111 %	Lead (High)
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)
Structure	Metal	409		SF	V0015	Red	Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1290 : Mechanical Room

**Floor:** 1

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1290 : Mechanical Room

**Floor:** 1

**Area (sqft):** 409

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1360 : Mechanical Room

**Floor:** 1

**Room #:** 136

**Area (sqft):** 175

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		175(7)			SF	S0052ABC	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct		None Found														
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment	Unit Heater	Not Insulated			C	Y										
Piping	All	Not Insulated			A	Y										
Structure	Not Accessible	None Found														
Wall		Paint			A	Y		600			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1360 : Mechanical Room

**Floor:** 1

**Room #:** 136

**Area (sqft):** 175

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Ceiling	Plaster	175		SF	L0007	Beige	Pb: 0.0262 %	Lead (Low)
Wall	Concrete (precast)	600		SF	V0001	White	Pb: 0.0085 %	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1511 : Library

**Floor:** 1

**Room #:** 151

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		1000			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		1000			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		1000			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping		Sweatwrap			C	N						V0005	None Detected	N.D.	None	
Piping	All	Fibreglass			C	N										
Structure		Concrete (poured)			C	N										
Structure	All	Metal		Paint	C	N		1000			SF					
Wall	All	Plaster		Paint	A	Y		1200			SF	V0057	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1511 : Library

**Floor:** 1

**Room #:** 151

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	1200		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	
Structure	Metal	1000		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1511 : Library

**Floor:** 1

**Room #:** 151

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1511 : Library

**Floor:** 1

**Room #:** 151

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1511 : Library

**Floor:** 1

**Room #:** 151

**Area (sqft):** 1000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

## ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1530 : Workroom

**Floor:** 1

**Room #:** 153

**Area (sqft):** 747

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium uniform pinhole			C	N		747			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		747			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		747			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		747			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		747			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	N		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Grey, silicone			A	Y						V0000	Non-Asbestos		None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1530 : Workroom

**Floor:** 1

**Room #:** 153

**Area (sqft):** 747

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	747		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1530 : Workroom

**Floor:** 1

**Room #:** 153

**Area (sqft):** 747

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking			V0000	Grey, silicone, window frames		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1710 : Mechanical Room

**Floor:** 1

**Room #:** 171

**Area (sqft):** 109

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tile (mechanically fastened), 1x1 coarse fissures			C	Y		109			SF	V0020	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic, 9x9 grey with white streaks			A	Y		109(7)			SF	V0022	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	Y										
Structure	All	None Found														
Wall		Paint, White			A	Y		100			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1710 : Mechanical Room

**Floor:** 1

**Room #:** 171

**Area (sqft):** 109

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	100		SF	V0004	White	Pb: 0.0078 %	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1711 : Mechanical Room

**Floor:** 1

**Room #:**

**Area (sqft):** 235

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Duct	All	Not Insulated			C	Y										
Floor	All	Concrete (poured)		Paint	B	Y		235			SF					
Mechanical Equipment	Tank	Fibreglass		Metal	B	Y										
Mechanical Equipment	Tank	Not Insulated			C	Y										
Piping		Parging Cement	Tee	Canvas	B	Y		14(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Fibreglass			B	Y										
Piping	All	Parging Cement	Elbow	Canvas	B	Y		35(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	Y		235			SF					
Wall		Paint, White			B	Y		700			SF	S0049D	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	B	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1711 : Mechanical Room

**Floor:** 1

**Room #:**

**Area (sqft):** 235

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	700		SF	L0004	White	Pb: 0.0078 %	No	
Floor	Concrete (poured)	235		SF	L0028	Grey	Pb: 0.111 %	Lead (High)	
Structure	Metal	235		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1711 : Mechanical Room

**Floor:** 1

**Room #:**

**Area (sqft):** 235

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1711 : Mechanical Room

**Floor:** 1

**Room #:**

**Area (sqft):** 235

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1721 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 328

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Ceiling	Bulkhead	Plaster		Paint	C	Y		150(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	Not Insulated			A	Y										
Floor	All	Concrete (poured)			A	Y		328			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	Y										
Piping	All	Parging Cement	Elbow	Canvas	C	Y		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Concrete (poured)			C	Y		328			SF					
Wall		Paint, Green			A	Y		900			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1721 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 328

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	900		SF	L0024	Green	Pb: 0.0021 %	No	
Structure	Concrete (poured)	328		SF	V0024	Green	Pb: 0.0021 %	No	
Ceiling	Plaster	150		SF	L0025	Green	Pb: 0.0094 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1721 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 328

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1721 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 328

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts	100	%	V9500	T12	Presumed



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1722 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS - NO ACCESS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster			C	Y		100			%	V0001	None Detected	N.D.	None	
Floor	All	Concrete (poured)			A	Y										
Piping	All	Fibreglass	All Pipe	Canvas	C	Y										
Piping	All	Not Insulated			C	Y										
Structure	Not Accessible	None Found														
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1722 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS - NO ACCESS				
Component	Quantity	Unit	Sample	Hazard

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1722 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY - NO ACCESS				
Component	Quantity	Unit	Sample	Hazard

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1722 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB - NO ACCESS						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1722 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ODS - NO ACCESS					
Component	Type	Quantity	Unit	Sample	Hazard

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1722 : Storage

**Floor:** 1

**Room #:** 172

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MOULD - NO ACCESS								
System	Material	Visible	Quantity	Unit	Sample Type	Sample No	Sample Description	Mould

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1722 : Storage

Floor: 1

Room #: 172

Area (sqft): 50

Survey Date: 2011-11-30

Last Re-Assessment:

TANK - NO ACCESS								
------------------	--	--	--	--	--	--	--	--

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1730 : Electrical Room

Floor: 1

Room #: 173

Area (sqft): 278

Survey Date: 2011-11-30

Last Re-Assessment:

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Ceiling	Bulkhead	Plaster			C	Y		150(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	Not Insulated			C	Y										
Floor	All	Concrete (poured)			B	Y		278			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Concrete (poured)			C	Y		278			SF					
Wall	All	Concrete (precast)			B	Y										

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1730 : Electrical Room

Floor: 1

Room #: 173

Area (sqft): 278

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Transformer			V0000			No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1731 : Dust Collector Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 156

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Duct	All	Not Insulated			B	Y										
Floor	All	Concrete (poured)			B	Y		156			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			B	Y										
Structure	All	Concrete (poured)			C	Y		156			SF					
Wall	All	Concrete (precast)			B	Y										

**Client:** Upper Canada District School Board  
**Location:** #1732 : Elevator Machine Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 50

ASBESTOS - NO ACCESS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster			C	Y		100			%	V0001	None Detected	N.D.	None	
Duct	All	Not Insulated			C	Y										
Floor	All	Terrazzo			A	Y										
Piping	All	Fibreglass	All Pipe	Paper	C	Y										
Structure	Not Accessible	None Found														
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board  
**Location:** #1732 : Elevator Machine Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 50

PB PRODUCTS - NO ACCESS																
Component					Quantity					Unit			Sample		Hazard	

**Client:** Upper Canada District School Board  
**Location:** #1732 : Elevator Machine Room  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 50

MERCURY - NO ACCESS																
Component					Quantity					Unit			Sample		Hazard	

**Client:** Upper Canada District School Board  
**Location:** #1732 : Elevator Machine Room

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Area (sqft):** 50



# ALL DATA REPORT

Survey Date: 2011-11-30

Last Re-Assessment:

PCB - NO ACCESS						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1732 : Elevator Machine Room

Floor: 1

Room #:

Area (sqft): 50

Survey Date: 2011-11-30

Last Re-Assessment:

ODS - NO ACCESS					
Component	Type	Quantity	Unit	Sample	Hazard

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1732 : Elevator Machine Room

Floor: 1

Room #:

Area (sqft): 50

Survey Date: 2011-11-30

Last Re-Assessment:

MOULD - NO ACCESS								
System	Material	Visible	Quantity	Unit	Sample Type	Sample No	Sample Description	Mould

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1732 : Elevator Machine Room

Floor: 1

Room #:

Area (sqft): 50

Survey Date: 2011-11-30

Last Re-Assessment:

TANK - NO ACCESS									
------------------	--	--	--	--	--	--	--	--	--

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #1883 : Storage

Floor: 1

Room #:

Area (sqft): 209

Survey Date: 2011-11-30

Last Re-Assessment:

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		None Found														
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	A	Y										
Piping	All	Parging Cement	Elbow	Canvas	A	Y		13(5)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	A	Y		2(5)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight	Canvas	A	Y		10			LF	V0005	None Detected	N.D.	None	
Structure	Deck	Steel		Paint	C	Y										
Wall		Paint, White			A	Y		600			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 152 of 353.

# ALL DATA REPORT

Location: #1883 : Storage  
Survey Date: 2011-11-30

Floor: 1

School  
Room #:  
Last Re-Assessment:

Area (sqft): 209

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	209		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)
Wall	Concrete (precast)	600		SF	V0001	White	Pb: 0.0085 %	No

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary  
School

Location: #1883 : Storage  
Survey Date: 2011-11-30

Floor: 1

Room #:  
Last Re-Assessment:

Area (sqft): 209

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary  
School

Location: #1883 : Storage  
Survey Date: 2011-11-30

Floor: 1

Room #:  
Last Re-Assessment:

Area (sqft): 209

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1884 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Duct	All	None Found														
Floor	All	Concrete (poured)			A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			A	Y										
Structure	All	None Found		Paint	D	Y		50			SF					
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1884 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	50		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1885 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 224

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		None Found														
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	A	Y										
Piping	All	Parging Cement	Elbow	Canvas	A	Y		15(5)		1(3)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	A	Y		2(5)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight	Canvas	A	Y		10			LF	V0005	None Detected	N.D.	None	
Structure	Deck	Steel		Paint	C	Y										
Wall		Paint, White			A	Y		600			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1885 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 224

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Structure	Metal	224		SF	V0003	Red		Pb: 0.0880 %	Lead (Low)
Wall	Concrete (precast)	600		SF	V0001	White		Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1885 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 224

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1885 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 224

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts	100	%	V9500	T12	Presumed



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1886 : Security/Telecom Equip Room

**Floor:** 1

**Room #:**

**Area (sqft):** 180

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		180			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Vinyl Floor Tile and Mastic			A	Y		170			SF	V0027	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		10			SF	V0028	[None]	N.D.	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		180			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown, white and green smears			A	Y		180			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Sweatwrap	Straight	Canvas	C	N		25			LF	V0005	None Detected	N.D.	None	
Piping	All	Not Insulated			C	N										
Structure	Deck	Concrete (poured)			C	N										
Wall		Paint, White			A	Y		500			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1887 : Washrooom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Ceramic Tiles	C	Y		50			SF	V0057	None Detected	N.D.	None	
Duct		None Found														
Floor		Terrazzo			A	Y										
Floor	All	Ceramic Tiles			A	Y										
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Paint, White			A	Y		50			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Ceramic Tiles	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1887 : Washrooom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	50		SF	V0001	White	Pb: 0.0085 %	No	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1888 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	A	Y		50			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic, 9x9 teal with grey and white streaks			A	Y		50(7)			SF	V0015	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	Not Accessible	None Found														
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		200			SF	V0043	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1888 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	200		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	50		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1888 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1888 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V9500	T12		Presumed



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1889 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		100			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		100			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1889 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	L0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	100		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1889 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1889 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1890 : Showers

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		75			SF	S0057B	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		75			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1890 : Showers

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Ceiling	Plaster	75		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1890 : Showers

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1890 : Showers

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1891 : Girls Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 871

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		871			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		871			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1891 : Girls Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 871

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	871		SF	L0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1891 : Girls Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 871

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1891 : Girls Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 871

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1892 : Pipe Chase

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated														
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment		None Found														
Other	Debris				A	Y				5	SF	V0005	[None]	N.D.	[Abated]	
Other	Debris	Parging Cement			A	Y				20	SF	V0006	[None]	5-10%	[Abated]	
Other	Debris	Aircell			A	Y				2	SF	V0026	[None]	10-25%	[Abated]	
Piping	All	Fibreglass	All Pipe	Canvas	A	Y										
Piping	All	Parging Cement	Fitting	Unjacketed	A	Y				50	EA	V0006	[None]	5-10%	[Abated]	
Piping	All	Parging Cement	Straight	Unjacketed	A	Y				4	LF	V0006	[None]	5-10%	[Abated]	
Piping	All	Aircell	Straight	Canvas	A	Y		50		2	LF	V0026	[None]	10-25%	[Abated]	
Piping	All	Sweatwrap	Straight	Canvas	A	Y		50		5	LF	V0005	[None]	N.D.	[Abated]	
Structure	Deck	Concrete (poured)			C	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1892 : Pipe Chase

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%		

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1893 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Ceramic Tiles	C	Y		50			SF	V0057	None Detected	N.D.	None	
Duct		None Found														
Floor		Terrazzo			A	Y										
Floor	All	Ceramic Tiles			A	Y										
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Paint, White			A	Y		50			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Ceramic Tiles	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1893 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	50		SF	V0001	White	Pb: 0.0085 %	No	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1894 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	A	Y		50			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic, 9x9 teal with grey and white streaks			A	Y		50(7)			SF	V0015	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	Not Accessible	None Found														
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		200			SF	V0043	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1894 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	200		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	50		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1894 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1894 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1895 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		200			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		200			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1895 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	200		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1895 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1895 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1896 : Shower

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		75			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		75			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1896 : Shower

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	75		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1896 : Shower

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1896 : Shower

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1897 : Boys Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 848

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		848			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		848			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1897 : Boys Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 848

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Plaster	848		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1897 : Boys Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 848

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1897 : Boys Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 848

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1898 : Stage

**Floor:** 1

**Room #:**

**Area (sqft):** 1103

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Duct	All	Not Insulated			D	Y										
Floor	All	Wood			A	Y		1103			SF					
Mechanical Equipment	All	None Found														
Piping	All	Not Insulated			C	Y										
Structure	All	Metal		Paint	D	Y		1103			SF					
Wall		Paint, Black/beige			A	Y		1500			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, Grey			A	Y		1			EA	V0044	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1898 : Stage

**Floor:** 1

**Room #:**

**Area (sqft):** 1103

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	1103		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Concrete (precast)	1500		SF	L0012	Black/beige	Pb: 0.0018 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1898 : Stage

**Floor:** 1

**Room #:**

**Area (sqft):** 1103

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
		SF	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1898 : Stage

**Floor:** 1

**Room #:**

**Area (sqft):** 1103

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube				

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1898 : Stage

**Floor:** 1

**Room #:**

**Area (sqft):** 1103

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	1	EA	V0001	Grey, window/door frames	<5 mg/kg	No
Light Ballasts			V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1899 : Gym A

**Floor:** 1

**Room #:**

**Area (sqft):** 6351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x2 wicker			D	Y		6351			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Wood			A	Y		6351			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		5000			SF	S0043C	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1899 : Gym A

**Floor:** 1

**Room #:**

**Area (sqft):** 6351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	5000		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1899 : Gym A

**Floor:** 1

**Room #:**

**Area (sqft):** 6351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1899 : Gym A

**Floor:** 1

**Room #:**

**Area (sqft):** 6351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1899 : Gym A

**Floor:** 1

**Room #:**

**Area (sqft):** 6351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #1962 : Vestibule and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 600

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		600			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		600			SF					
Mechanical Equipment	All	None Found														
Piping	All	Parging Cement	Elbow	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		600			SF					
Wall		Plaster		Paint	A	Y		20(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board  
**Location:** #1962 : Vestibule and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 600

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	20		SF	V0017	White	Pb: 0.0123 %	Lead (Low)
Structure	Metal	600		SF	V0015	Red	Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board  
**Location:** #1962 : Vestibule and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 600

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board  
**Location:** #1962 : Vestibule and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 1

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**  
**Area (sqft):** 600

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1963 : Storage under Stair

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found									SF					
Duct	All	None Found														
Floor	All	Concrete (poured)			B	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure		Metal		Paint	B	Y										
Structure	All	Concrete (poured)			B	Y		50			SF					
Wall	All	Concrete (precast)			B	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1963 : Storage under Stair

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall		100		%				No	
Structure	Metal	50		SF	L0006	Red	Pb: 0.110 %	Lead (High)	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1964 : Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster		Paint	C	Y		100			SF	V0071	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		600			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		600			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	N		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	C	N		1(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		600			SF					
Wall		Drywall and joint compound		Paint	A	Y		25			SF	V0048	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1964 : Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Drywall and joint compound	25		SF	V0005	White	Pb: <0.0005 %	No
Structure	Metal	600		SF	V0006	Red	Pb: 0.110 %	Lead (High)
Ceiling	Plaster	97	3	SF	V0022	White	Pb: 0.0092 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1964 : Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1964 : Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**



PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

## ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1965 : Custodial Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tile (mechanically fastened), 1x1 coarse fissures			C	Y		50			SF	V0020	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Concrete (poured)		Paint	A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	Not Insulated			A	Y										
Structure	All	None Found														
Wall		Paint, White			A	Y		100			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1965 : Custodial Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Floor	Concrete (poured)	50		SF	V0023	Grey		No	
Wall	Concrete (precast)	100		SF	V0004	White	Pb: 0.0078 %	No	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1966 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened), 1x1 coarse fissures		Ceiling Tiles (lay-in)	C	N		50			SF	V0020	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Rubber			A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	None Found														
Wall		Paint, White			A	Y		200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1966 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	200		SF	V0004	White	Pb: 0.0078 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1966 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1966 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1967 : Gym D

**Floor:** 1

**Room #:**

**Area (sqft):** 3165

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Acoustic panel, Wicker			D	Y		3165			SF					
Duct	All	None Found														
Floor	All	Wood			A	Y		3165			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		2400			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, White			A	Y		1			EA	V0070	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Black, butyl sealant			A	Y		1			EA	V0046	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1967 : Gym D

**Floor:** 1

**Room #:**

**Area (sqft):** 3165

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	2400		SF	V0004	White	Pb: 0.0078 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1967 : Gym D

**Floor:** 1

**Room #:**

**Area (sqft):** 3165

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1967 : Gym D

**Floor:** 1

**Room #:**

**Area (sqft):** 3165

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed
Caulking	1	EA	V0001	White, door frame	<5 mg/kg	No
Caulking	1	EA	V0002	Butyl sealant, black	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1968 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 30

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		30			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		30			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		30			SF					
Wall		Ceramic Tiles			A	Y										
Wall		Paint, White			A	Y		400			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1968 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 30

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	30		SF	V0006	Red	Pb: 0.110 %	Lead (High)
Wall	Concrete (precast)	400		SF	V0004	White	Pb: 0.0078 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1968 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 30

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1968 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 30

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1969 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Not Insulated			C	N										
Structure	All	Metal		Paint	C	N		50			SF					
Wall		Paint, White			A	Y		400			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1969 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	50		SF	V0006	Red	Pb: 0.110 %	Lead (High)
Wall	Concrete (precast)	400		SF	V0004	White	Pb: 0.0078 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1969 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1969 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1969 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1970 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		100			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		100			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		100			SF					
Wall		Paint, White			A	Y		400			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1970 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	100		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Concrete (precast)	400		SF	V0004	White	Pb: 0.0078 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1970 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1970 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1971 : Shower

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		50(7)			SF	S0052F	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1971 : Shower

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	200		SF	V0004	White	Pb: 0.0078 %	No
Ceiling	Plaster	200		SF	L0022	White	Pb: 0.0092 %	Lead (Low)

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1972 : Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 745

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		745(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		745			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		600			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1972 : Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 745

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	200		SF	V0004	White	Pb: 0.0078 %	No	
Ceiling	Plaster	600		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1972 : Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 745

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1972 : Change Room

**Floor:** 1

**Room #:**

**Area (sqft):** 745

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1973 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		6000			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		6000			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		50(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Aircell	Straight	Sweatwrap	C	N		200			LF	V0003	None Detected	N.D.	None	
Structure	All	Metal		Paint	C	N		6000			SF					
Wall		Drywall and joint compound		Paint	A	Y		500			SF	V0048	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		1000			SF	S0071B	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1973 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	1000		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	
Wall	Drywall and joint compound	500		SF	V0005	White	Pb: <0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1973 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1973 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1974 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		2000			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		2000			SF					
Mechanical Equipment	All	None Found														
Piping		Armaflex			C	N										
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		30(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		2000			SF					
Wall		Drywall and joint compound		Paint	A	Y		1000			SF	V0048	None Detected	N.D.	None	
Wall		Plaster		Drywall and joint compound	D	N		1000			SF	S0071C	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1974 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Drywall and joint compound	1000		SF	L0005	White	Pb: <0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1974 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1974 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1975 : Corridor and Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		900			SF	V0000	Non-Asbestos		None	
Ceiling		Plaster		Paint	C	Y		100			SF	V0057	None Detected	N.D.	None	
Duct		None Found														
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	N		20(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight	Canvas	C	N		15			LF	V0005	None Detected	N.D.	None	
Piping	All	Armaflex			C	N										
Structure	Deck	Concrete (poured)			C	N										
Wall		Drywall and joint compound			C	N		400			SF	V0055	None Detected	N.D.	None	
Wall		Ceramic Tiles			A	Y										
Wall	All	Concrete (precast)			A	Y										
Wall	All	Plaster		Paint	A	Y		400			SF	V0057	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, black			A	Y		14			EA	V0046	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1975 : Corridor and Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	400		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	
Ceiling	Plaster	100		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1975 : Corridor and Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1975 : Corridor and Stairwell

**Floor:** 1

**Room #:**

**Area (sqft):** 1500

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #1975 : Corridor and Stairwell**

**Floor: 1**

**Room #:**

**Area (sqft): 1500**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	14	EA	V0002	Butyl sealant black	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1976 : Custodial Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 99

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		99			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Concrete (poured)		Paint	A	Y		99			SF					
Mechanical Equipment	All	None Found														
Piping	All	Not Insulated			A	Y										
Structure	All	Metal		Paint	C	N		99			SF					
Wall		Paint, White			A	Y		400			SF	S0043D	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1976 : Custodial Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 99

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Floor	Concrete (poured)	99		SF	L0009	Grey	Pb: 0.0369 %	Lead (Low)	
Structure	Metal	99		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1976 : Custodial Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 99

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1976 : Custodial Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 99

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1977 : Boy's Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 303

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		303			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor	All	Concrete (poured)		Paint	A	Y		303			SF					
Mechanical Equipment	All	None Found														
Piping	All	Not Insulated			A	Y										
Structure	All	Metal		Paint	C	N		303			SF					
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1977 : Boy's Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 303

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	
Floor	Concrete (poured)	303		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	
Structure	Metal	303		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1977 : Boy's Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 303

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1977 : Boy's Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 303

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1978 : Janitors Room

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		25			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Concrete (poured)		Paint	A	Y		25			SF					
Mechanical Equipment	All	None Found														
Piping		Parging Cement	Elbow	Canvas	B	Y		8(7)	13(6)	3(3)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping		Parging Cement	Tee		B	Y		10(7)	3(6)	1(3)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping		Sweatwrap			B	Y						V0005	None Detected	N.D.	None	
Piping	All	Not Insulated			B	Y										
Structure	All	None Found														
Wall		Paint, White			A	Y		150			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1978 : Janitors Room

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Floor	Concrete (poured)	25		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	
Ceiling	Plaster	25		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1978 : Janitors Room

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1979 : Girls Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 276

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		276			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		276			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		276			SF					
Wall		Paint, White			A	Y		400			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1979 : Girls Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 276

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	276		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Concrete (precast)	400		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1979 : Girls Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 276

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1979 : Girls Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 276

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1980 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		5000			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		50(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Metal		Paint	C	N										
Wall		Drywall and joint compound		Paint	A	Y		2000			SF	V0055	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										
Wall	All	Plaster		Drywall and joint compound	A	Y		2000			SF	V0057	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		6(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1980 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	5000		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)
Wall	Drywall and joint compound	2000		SF	V0002	White	Pb: 0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1980 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1980 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	6	EA	V0002	Butyl sealant grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1981 : Passage

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster			C	Y		75(7)			SF	S0052D	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	Not Insulated			A	Y										
Floor	All	Concrete (poured)		Paint	A	Y										
Piping		Sweatwrap	Straight	Canvas	A	Y						V0005	None Detected	N.D.	None	
Piping	All	Fibreglass	All Pipe	Canvas	A	Y										
Piping	All	Parging Cement	Elbow	Canvas	A	Y		6(5)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Not Insulated			A	Y										
Structure		Metal		Paint	C	Y										
Wall	All	Concrete (precast)			A	Y										
Wall	All	Drywall and joint compound			A	Y		100			SF	S0055B	None Detected	N.D.	None	
Wall	Door	Caulking, Grey			A	Y		1			EA	V0044	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1981 : Passage

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Floor	Concrete (poured)	75		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	
Structure	Metal	75		SF	L0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1981 : Passage

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	2	EA	V0001	Grey, window/door frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1982 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (splined), 1x1 smooth, textured surface			C	Y		100			SF	V0017	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		100			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall	All	Concrete (precast)			A	Y										
Wall	Window Liner	Caulking, Butyl sealant, black			A	Y		6			EA	V0046	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1982 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1982 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	6	EA	V0002	Butyl sealant black	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1983 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 3000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		3000			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Caposite			C	N		294(7)		2(4)	LF	S0056ABC	Amosite	50-75%	Confirmed Asbestos	F
Piping	Debris	Caposite			C	N				2(2)	SF	V0056	Amosite	50-75%	Confirmed Asbestos	F
Structure	Deck	Steel			C	N										
Structure	Deck	Metal		Paint	C	N										
Wall		Drywall and joint compound		Paint	A	Y		200			SF	V0055	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										
Wall	All	Plaster		Paint	A	Y		1000			SF	S0057A	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1983 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 3000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	3000		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)
Wall	Plaster	1000		SF	V0008	White	Pb: 0.0339 %	Lead (Low)
Wall	Drywall and joint compound	200		SF	V0002	White	Pb: 0.0005 %	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1984 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster		Paint	C	Y		75(7)			SF	S0052E	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct		None Found														
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Not Insulated			A	Y										
Structure	Not Accessible	None Found														
Wall		Masonry			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1984 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Ceiling	Plaster	75		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1985 : Custodian Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		50			SF	V0057	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Concrete (poured)		Paint	A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		150			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1985 : Custodian Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Ceiling	Plaster	50		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	
Floor	Concrete (poured)	50		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	
Wall	Concrete (precast)	150		SF	V0001	White	Pb: 0.0085 %	No	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1986 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		50			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		50			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Vinyl Sheet Flooring, Blue flecked, linoleum			A	Y		50			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		100			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1986 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	100		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1986 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1986 : Vestibule

**Floor:** 1

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1987 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		25			SF	V0004	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		25			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Vinyl Sheet Flooring, Blue flecked, linoleum			A	Y		25			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Plaster		Paint	A	Y		50			SF	V0057	None Detected	N.D.	None	
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0055	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1987 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Drywall and joint compound	50		SF	V0002	White	Pb: 0.0005 %	No	
Wall	Plaster	50		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1987 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1987 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1988 : Health Services

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		150			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		150			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		150			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Vinyl Sheet Flooring, Blue flecked, linoleum			A	Y		150			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Plaster		Paint	A	Y		300			SF	V0057	None Detected	N.D.	None	
Wall		Paint, White			A	Y		100			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0055	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1988 : Health Services

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	100		SF	V0001	White	Pb: 0.0085 %	No
Wall	Plaster	300		SF	V0008	White	Pb: 0.0339 %	Lead (Low)
Wall	Drywall and joint compound	50		SF	V0002	White	Pb: 0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1988 : Health Services

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1988 : Health Services

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1989 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		100			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		100			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		50			SF	V0014	[None]	0.5-5%	[Abated]	
Floor		Mastic			D	N		100			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown, white and green streaks			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Plaster		Paint	A	Y		300			SF	V0057	None Detected	N.D.	None	
Wall		Paint, White			A	Y		100			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0055	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1989 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	100		SF	L0001	White		Pb: 0.0085 %	No
Wall	Plaster	300		SF	V0008	White		Pb: 0.0339 %	Lead (Low)
Wall	Drywall and joint compound	50		SF	V0002	White		Pb: 0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1989 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1989 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100



Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1990 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 95

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		95			SF	V0004	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		95			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		95			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		95			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Plaster		Paint	A	Y		300			SF	V0057	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, black			A	Y		4			EA	V0046	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1990 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 95

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	300		SF	V0008	White	Pb: 0.0339 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1990 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 95

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1990 : Storage

**Floor:** 1

**Room #:**

**Area (sqft):** 95

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0002	Butyl sealant black	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1991 : Copier

**Floor:** 1

**Room #:**

**Area (sqft):** 269

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		269			SF	V0004	None Detected	N.D.	None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		269			SF	V0010	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		269			SF	S0054C	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		269			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Plaster		Paint	A	Y		300			SF	V0057	None Detected	N.D.	None	
Wall		Paint, White			A	Y		100			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window Liner	Caulking, Butyl sealant, black			A	Y		1			EA	V0046	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1991 : Copier

**Floor:** 1

**Room #:**

**Area (sqft):** 269

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	100		SF	V0001	White	Pb: 0.0085 %	No	
Wall	Plaster	300		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1991 : Copier

**Floor:** 1

**Room #:**

**Area (sqft):** 269

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1991 : Copier

**Floor:** 1

**Room #:**

**Area (sqft):** 269

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0002	Butyl sealant black	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1992 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 151

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		151			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		151			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		151			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with brown and white smears			A	Y						V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N										
Wall		Plaster		Paint	A	Y		300			SF	V0057	None Detected	N.D.	None	
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0055	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		1			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1992 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 151

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	300		SF	V0008	White	Pb: 0.0339 %	Lead (Low)
Wall	Drywall and joint compound	50		SF	V0002	White	Pb: 0.0005 %	No
Structure	Metal	151		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1992 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 151

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1992 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 151

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0001	Grey, window frame	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1993 : Waiting

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		100			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		100			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N										
Wall		Plaster		Paint	A	Y		300			SF	V0057	None Detected	N.D.	None	
Wall	All	Drywall and joint compound		Paint	A	Y		50			SF	V0055	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1993 : Waiting

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	300		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	
Wall	Drywall and joint compound	50		SF	V0002	White	Pb: 0.0005 %	No	
Structure	Metal	100		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1993 : Waiting

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1993 : Waiting

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**



PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0002	Butyl sealant grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1994 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		100			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		100			SF	V0042	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 dark grey with darker grey and white flecks			A	Y		100			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		100			SF					
Wall		Drywall and joint compound		Paint	A	Y		100			SF	V0055	None Detected	N.D.	None	
Wall	All	Plaster		Paint	A	Y		100			SF	V0057	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		1			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1994 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	100		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Plaster	100		SF	V0013	Grey	Pb: 0.0320 %	Lead (Low)	
Wall	Drywall and joint compound	100		SF	V0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1994 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1994 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 100

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	1	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1995 : Vault

**Floor:** 1

**Room #:**

**Area (sqft):** 75

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Duct	All	None Found														
Floor	All	Vinyl Floor Tile and Mastic, 9x9 white with grey streaks			A	Y		75(7)			SF	V0014	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Concrete (poured)			C	Y		75			SF					
Wall	All	Masonry			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1996 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 dense pinholes and short/medium widthwise fissures, 08/07/20			C	Y		100			SF	V0050	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		150			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		150			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		150			SF					
Wall	All	Plaster		Paint	A	Y		800			SF	V0057	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		1			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1996 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	150		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Plaster	800		SF	V0013	Grey	Pb: 0.0320 %	Lead (Low)	

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1996 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1996 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 150

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1997 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 245

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x2 textured surface with pinholes			C	Y		245			SF	V0011	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (splined), 1x1 clustered fissures and pinholes		Ceiling Tiles (lay-in)	C	N		245			SF	V0016	None Detected	N.D.	None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		245			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		245			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		245			SF					
Wall	All	Plaster		Paint	A	Y		800			SF	V0057	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		1			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1997 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 245

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	245		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Plaster	800		SF	V0013	Grey	Pb: 0.0320 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1997 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 245

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1997 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 245

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1998 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 lengthwise fissures and pinholes			C	Y		25			SF	V0013	None Detected	N.D.	None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		25			SF	V0042	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 dark grey with darker grey and white flecks			A	Y		25			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		25			SF					
Wall	All	Plaster		Paint	A	Y		50			SF	V0057	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1998 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	50		SF	V0013	Grey	Pb: 0.0320 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1998 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1998 : Washroom

**Floor:** 1

**Room #:**

**Area (sqft):** 25

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1999 : Closet

**Floor:** 1

**Room #:**

**Area (sqft):** 20

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		20			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		20			SF	V0042	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 dark grey with darker grey and white flecks			A	Y		20			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		20			SF					
Wall	All	Plaster		Paint	A	Y		800			SF	V0057	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		1(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1999 : Closet

**Floor:** 1

**Room #:**

**Area (sqft):** 20

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	20		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Plaster	800		SF	V0013	Grey	Pb: 0.0320 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1999 : Closet

**Floor:** 1

**Room #:**

**Area (sqft):** 20

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #1999 : Closet

**Floor:** 1

**Room #:**

**Area (sqft):** 20

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0002	Butyl sealant grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2000 : Ampitheatre

**Floor:** 2

**Room #:** 200

**Area (sqft):** 1665

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1665			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	Y										
Floor		Mastic		Vinyl Floor Tile	D	N		1665			SF	S0042H	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 blue			A	Y		1665			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N		1665			SF					
Wall		Paint, White			A	Y		1200(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2000 : Ampitheatre

**Floor:** 2

**Room #:** 200

**Area (sqft):** 1665

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1200		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	1665		SF	V0015	Red	Pb: 0.330 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2000 : Ampitheatre

**Floor:** 2

**Room #:** 200

**Area (sqft):** 1665

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2000 : Ampitheatre

**Floor:** 2

**Room #:** 200

**Area (sqft):** 1665

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2001 : Bood Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 246

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		246			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		246			SF	V0030	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		246			SF	V0051	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		246			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N		246			SF					
Wall		Plaster		Paint	A	Y		100			SF	S0057F	None Detected	N.D.	None	
Wall		Paint, White			A	Y		600			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2001 : Bood Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 246

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	100		SF	L0008	White	Pb: 0.0339 %	Lead (Low)
Wall	Concrete (precast)	600		SF	V0001	White	Pb: 0.0085 %	No
Structure	Metal	246		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2001 : Bood Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 246

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2001 : Bood Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 246

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2010 : Classroom

**Floor:** 2

**Room #:** 201

**Area (sqft):** 826

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		826			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	C	N		826			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		826			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N		826			SF					
Wall		Plaster		Paint	A	Y		100(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall		Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2010 : Classroom

**Floor:** 2

**Room #:** 201

**Area (sqft):** 826

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	100		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	826		SF	V0015	Red	Pb: 0.330 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2010 : Classroom

**Floor:** 2

**Room #:** 201

**Area (sqft):** 826

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2010 : Classroom

**Floor:** 2

**Room #:** 201

**Area (sqft):** 826

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2020 : Classroom

**Floor:** 2

**Room #:** 202

**Area (sqft):** 1351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1351			SF	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound		Paint	C	Y		100			SF	S0065E	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Vinyl Sheet Flooring, Large beige cubes			A	Y		1351			SF	V0031	None Detected		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N		1351			SF					
Wall		Drywall and joint compound		Paint	A	Y		200			SF	V0002	None Detected	N.D.	None	
Wall		Paint, White			A	Y		1200(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2020 : Classroom

**Floor:** 2

**Room #:** 202

**Area (sqft):** 1351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1200		SF	V0001	White	Pb: 0.0085 %	No	
Wall	Drywall and joint compound	200		SF	V0002	White	Pb: 0.0005 %	No	
Ceiling	Drywall and joint compound	100		SF	V0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2020 : Classroom

**Floor:** 2

**Room #:** 202

**Area (sqft):** 1351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2020 : Classroom

**Floor:** 2

**Room #:** 202

**Area (sqft):** 1351

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2030 : Classroom

**Floor:** 2

**Room #:** 203

**Area (sqft):** 713

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		713			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		713			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		350			SF	V0019	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		363			SF	V0032	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		713			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		713			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2030 : Classroom

**Floor:** 2

**Room #:** 203

**Area (sqft):** 713

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2030 : Classroom

**Floor:** 2

**Room #:** 203

**Area (sqft):** 713

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2030 : Classroom

**Floor:** 2

**Room #:** 203

**Area (sqft):** 713

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2040 : Classroom

**Floor:** 2

**Room #:** 204

**Area (sqft):** 1025

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1670			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		1670			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	C	N		1670			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		1670			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Drywall and joint compound		Paint	A	Y		150			SF	V0055	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2040 : Classroom

**Floor:** 2

**Room #:** 204

**Area (sqft):** 1025

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No
Wall	Drywall and joint compound	150		SF	V0002	White	Pb: 0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2040 : Classroom

**Floor:** 2

**Room #:** 204

**Area (sqft):** 1025

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2040 : Classroom

**Floor:** 2

**Room #:** 204

**Area (sqft):** 1025

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V9500	T12		Presumed
Caulking	3	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2050 : Classroom

**Floor:** 2

**Room #:** 205

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		686			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		686			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0014	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		346			SF	V0034	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		686			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		686			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2050 : Classroom

**Floor:** 2

**Room #:** 205

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2050 : Classroom

**Floor:** 2

**Room #:** 205

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2050 : Classroom

**Floor:** 2

**Room #:** 205

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2070 : Classroom

**Floor:** 2

**Room #:** 207

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		686			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		686			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0019	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		346			SF	V0015	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		686			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		686			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2070 : Classroom

**Floor:** 2

**Room #:** 207

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2070 : Classroom

**Floor:** 2

**Room #:** 207

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2070 : Classroom

**Floor:** 2

**Room #:** 207

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #2080 : Classroom  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 208  
**Area (sqft):** 1687  
**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1687			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		1687			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	C	N		1687			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		1687			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		6			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board  
**Location:** #2080 : Classroom  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 208  
**Area (sqft):** 1687  
**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board  
**Location:** #2080 : Classroom  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 208  
**Area (sqft):** 1687  
**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board  
**Location:** #2080 : Classroom  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:** 208  
**Area (sqft):** 1687  
**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2080 : Classroom

**Floor:** 2

**Room #:** 208

**Area (sqft):** 1687

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V9500	T12		Presumed
Caulking	6	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2090 : Classroom

**Floor:** 2

**Room #:** 209

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		686			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		686			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0019	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		346			SF	V0032	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		686			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		686			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Structure	Not Accessible	None Found														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	S0045C	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2090 : Classroom

**Floor:** 2

**Room #:** 209

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2090 : Classroom

**Floor:** 2

**Room #:** 209

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2090 : Classroom

**Floor:** 2

**Room #:** 209

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 244 of 353.

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2110 : Classroom

**Floor:** 2

**Room #:** 211

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		686			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		686			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		343			SF	V0015	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		343			SF	V0019	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		686			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		686			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2110 : Classroom

**Floor:** 2

**Room #:** 211

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2110 : Classroom

**Floor:** 2

**Room #:** 211

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2110 : Classroom

**Floor:** 2

**Room #:** 211

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2120 : Workroom

**Floor:** 2

**Room #:** 212

**Area (sqft):** 329

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		329			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		329			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	C	N		329			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		329			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		75			SF	V0002	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2120 : Workroom

**Floor:** 2

**Room #:** 212

**Area (sqft):** 329

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No	
Wall	Drywall and joint compound	75		SF	L0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2120 : Workroom

**Floor:** 2

**Room #:** 212

**Area (sqft):** 329

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2120 : Workroom

**Floor:** 2

**Room #:** 212

**Area (sqft):** 329

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2130 : Classroom

**Floor:** 2

**Room #:** 213

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		686			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		686			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		343			SF	V0032	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		343			SF	V0019	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		686			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		686			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Structure	Not Accessible	None Found														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2130 : Classroom

**Floor:** 2

**Room #:** 213

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2130 : Classroom

**Floor:** 2

**Room #:** 213

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2130 : Classroom

**Floor:** 2

**Room #:** 213

**Area (sqft):** 686

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 250 of 353.

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2140 : Classroom

**Floor:** 2

**Room #:** 214

**Area (sqft):** 1636

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1636			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		1636			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	C	N		1636			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		1636			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		6			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2140 : Classroom

**Floor:** 2

**Room #:** 214

**Area (sqft):** 1636

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	L0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2140 : Classroom

**Floor:** 2

**Room #:** 214

**Area (sqft):** 1636

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2140 : Classroom

**Floor:** 2

**Room #:** 214

**Area (sqft):** 1636

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	6	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2150 : Classroom

**Floor:** 2

**Room #:** 215

**Area (sqft):** 710

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		710			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		710			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		355			SF	V0014	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		355			SF	V0034	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		710			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		710			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Paint, White			A	Y		800			SF	S0043E	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2150 : Classroom

**Floor:** 2

**Room #:** 215

**Area (sqft):** 710

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	L0001	White	Pb: 0.0085 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2150 : Classroom

**Floor:** 2

**Room #:** 215

**Area (sqft):** 710

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2150 : Classroom

**Floor:** 2

**Room #:** 215

**Area (sqft):** 710

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Light grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2160 : Classroom

**Floor:** 2

**Room #:** 216

**Area (sqft):** 1472

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1472			SF	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	C	N		1472			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		1472			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		Armaflex			C	N										
Structure		Metal			C	N										
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	S0049G	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2160 : Classroom

**Floor:** 2

**Room #:** 216

**Area (sqft):** 1472

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	1472		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2160 : Classroom

**Floor:** 2

**Room #:** 216

**Area (sqft):** 1472

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2160 : Classroom

**Floor:** 2

**Room #:** 216

**Area (sqft):** 1472

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001		<5 mg/kg	No

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #2160 : Classroom

Floor: 2

Room #: 216

Area (sqft): 1472

Survey Date: 2011-11-30

Last Re-Assessment:

MOULD								
System	Material	Visible	Quantity	Unit	Sample Type	Sample No	Sample Description	Mould
Ceiling	Ceiling Tiles (lay-in)	Y	16	SF	V	9500	Water stained	Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2161 : Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 258

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		258			SF	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound		Paint	C	Y		25			SF	S0048D	None Detected	N.D.	None	
Duct		Not Insulated			C	N										
Floor		Vinyl Floor Tile and Mastic			A	Y		258			SF	V0030	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic, 12x12 light grey with dark grey and white smears			A	Y		258			SF	V0000	Non-Asbestos		None	
Floor		Mastic		Vinyl Floor Tile	D	N		258			SF	V0051	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure		Metal			C	N										
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2161 : Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 258

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No
Structure	Metal	258		SF	V0006	Red	Pb: 0.110 %	Lead (High)
Ceiling	Drywall and joint compound	25		SF	V0005	White	Pb: <0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2161 : Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 258

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2161 : Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 258

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2170 : Computer Room

**Floor:** 2

**Room #:** 217

**Area (sqft):** 828

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		828			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes			C	N		430			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		330			SF	V0021	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Mastic		Vinyl Floor Tile	C	N		828			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		828			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Plaster		Paint	A	Y		50			SF	S0071D	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	S0049E	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2170 : Computer Room

**Floor:** 2

**Room #:** 217

**Area (sqft):** 828

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	828		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2170 : Computer Room

**Floor:** 2

**Room #:** 217

**Area (sqft):** 828

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

# ALL DATA REPORT

**Location: #2170 : Computer Room**  
**Survey Date: 2011-11-30**

**Floor: 2**

**Room #: 217**  
**Last Re-Assessment:**

**Area (sqft): 828**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001		<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2171 : Office

**Floor:** 2

**Room #:**

**Area (sqft):** 480

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		480			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes			C	N		430			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		330			SF	V0021	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Mastic		Vinyl Floor Tile	C	N		480			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		480			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	S0049F	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Grey butyl sealant			A	Y		5(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2171 : Office

**Floor:** 2

**Room #:**

**Area (sqft):** 480

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	480		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2171 : Office

**Floor:** 2

**Room #:**

**Area (sqft):** 480

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 262 of 353.

# ALL DATA REPORT

**Location: #2171 : Office**  
**Survey Date: 2011-11-30**

**Floor: 2**

**School**  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft): 480**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001		<5 mg/kg	No
Caulking	5	EA	V0002	Butyl sealant grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2180 : Classroom

**Floor:** 2

**Room #:** 218

**Area (sqft):** 702

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		702			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes			C	N		430			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		330			SF	V0021	None Detected	N.D.	None	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		352			SF	V0030	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		175			SF	V0027	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		175			SF	V0032	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		702			SF	V0068	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		702			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2180 : Classroom

**Floor:** 2

**Room #:** 218

**Area (sqft):** 702

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	800		SF	V0004	White		Pb: 0.0078 %	No
Structure	Metal	702		SF	V0006	Red		Pb: 0.110 %	Lead (High)
Wall	Plaster	50		SF	V0022	White		Pb: 0.0092 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2180 : Classroom

**Floor:** 2

**Room #:** 218

**Area (sqft):** 702

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2180 : Classroom

**Floor:** 2

**Room #:** 218

**Area (sqft):** 702

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001		<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2190 : Computer Room

**Floor:** 2

**Room #:** 219

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		730			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes			C	N		430			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		330			SF	V0021	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Mastic		Vinyl Floor Tile	C	N		730			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		730			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Grey butyl sealant			A	Y		5(7)			EA	S0058B	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2190 : Computer Room

**Floor:** 2

**Room #:** 219

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	730		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	L0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2190 : Computer Room

**Floor:** 2

**Room #:** 219

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2190 : Computer Room

**Floor:** 2

**Room #:** 219

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001		<5 mg/kg	No
Caulking	5	EA	V0002	Butyl sealant grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2200 : Classroom

**Floor:** 2

**Room #:** 220

**Area (sqft):** 696

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		696			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes			C	N		430			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		330			SF	V0021	None Detected	N.D.	None	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		346			SF	V0030	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		175			SF	V0027	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		175			SF	V0032	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		696			SF	V0068	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		696			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2200 : Classroom

**Floor:** 2

**Room #:** 220

**Area (sqft):** 696

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	696		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2200 : Classroom

**Floor:** 2

**Room #:** 220

**Area (sqft):** 696

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2200 : Classroom

**Floor:** 2

**Room #:** 220

**Area (sqft):** 696

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001		<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2210 : Classroom

**Floor:** 2

**Room #:** 231

**Area (sqft):** 725

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		725			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes			C	N		430			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		330			SF	V0021	None Detected	N.D.	None	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic, 12x12 light grey with dark grey and white smears			A	Y		725			SF	V0000	Non-Asbestos		None	
Floor		Mastic		Vinyl Floor Tile	D	N		725			SF	S0051C	None Detected	N.D.	None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2210 : Classroom

**Floor:** 2

**Room #:** 231

**Area (sqft):** 725

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	725		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2210 : Classroom

**Floor:** 2

**Room #:** 231

**Area (sqft):** 725

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

# ALL DATA REPORT

**Location: #2210 : Classroom**  
**Survey Date: 2011-11-30**

**Floor: 2**

**Room #: 231**  
**Last Re-Assessment:**

**Area (sqft): 725**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001		<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2230 : Classroom

**Floor:** 2

**Room #:** 223

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		730			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 large and medium uniform pinholes			C	N		430			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth surface			C	N		330			SF	V0021	None Detected	N.D.	None	
Duct		None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		380			SF	V0030	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		175			SF	V0033	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		175			SF	V0035	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		730			SF	V0068	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		730			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Not Accessible	None Found														
Wall		Plaster		Paint	A	Y		50			SF	V0071	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	S0045B	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2230 : Classroom

**Floor:** 2

**Room #:** 223

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	L0004	White	Pb: 0.0078 %	No	
Structure	Metal	730		SF	V0006	Red	Pb: 0.110 %	Lead (High)	
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2230 : Classroom

**Floor:** 2

**Room #:** 223

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2230 : Classroom

**Floor:** 2

**Room #:** 223

**Area (sqft):** 730

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	P0001		<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2250 : Classroom

**Floor:** 2

**Room #:** 225

**Area (sqft):** 675

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured surface with pinholes			C	Y		675(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		337			SF	V0037	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		338			SF	V0038	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		675			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		675			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2250 : Classroom

**Floor:** 2

**Room #:** 225

**Area (sqft):** 675

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Structure	Metal	675		SF	L0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2250 : Classroom

**Floor:** 2

**Room #:** 225

**Area (sqft):** 675

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 274 of 353.

# ALL DATA REPORT

**Location: #2250 : Classroom**  
**Survey Date: 2011-11-30**

**Floor: 2**

**School**  
**Room #: 225**  
**Last Re-Assessment:**

**Area (sqft): 675**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2252 : Storage

**Floor:** 2

**Room #:** 225

**Area (sqft):** 250

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		250			SF	V0036	[None]	0.5-5%	[Abated]	
Ceiling		Ceiling Tiles (lay-in), 2x4 small pinholes and narrow widthwise fissures, 09/22/16			C	Y		250			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		250			SF	V0038	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		250			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		250			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		2			EA	V0006	[None]	5-10%	[Abated]	
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound			A	Y		75			SF	S0065C	None Detected	N.D.	None	
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2252 : Storage

**Floor:** 2

**Room #:** 225

**Area (sqft):** 250

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	L0016	White	Pb: 0.0281 %	Lead (Low)	
Structure	Metal	250		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	
Wall	Drywall and joint compound	75		SF	L0020	Off-white	Pb: <0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2252 : Storage

**Floor:** 2

**Room #:** 225

**Area (sqft):** 250

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2252 : Storage

**Floor:** 2

**Room #:** 225

**Area (sqft):** 250

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	2	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2260 : Classroom

**Floor:** 2

**Room #:** 226

**Area (sqft):** 1005

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		1005(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		500			SF	V0037	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		500			SF	V0038	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		1005			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		1005			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		1(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2260 : Classroom

**Floor:** 2

**Room #:** 226

**Area (sqft):** 1005

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Structure	Metal	1005		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2260 : Classroom

**Floor:** 2

**Room #:** 226

**Area (sqft):** 1005

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 278 of 353.

# ALL DATA REPORT

**Location: #2260 : Classroom**  
**Survey Date: 2011-11-30**

**Floor: 2**

**School**  
**Room #: 226**  
**Last Re-Assessment:**

**Area (sqft): 1005**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2270 : Classroom

**Floor:** 2

**Room #:** 227

**Area (sqft):** 677

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		677(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		338			SF	V0040	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		339			SF	V0041	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		677			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		677			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2270 : Classroom

**Floor:** 2

**Room #:** 227

**Area (sqft):** 677

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Structure	Metal	677		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2270 : Classroom

**Floor:** 2

**Room #:** 227

**Area (sqft):** 677

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 280 of 353.

# ALL DATA REPORT

**Location: #2270 : Classroom**  
**Survey Date: 2011-11-30**

**Floor: 2**

**School**  
**Room #: 227**  
**Last Re-Assessment:**

**Area (sqft): 677**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2280 : Classroom

**Floor:** 2

**Room #:** 228

**Area (sqft):** 678

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		678(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		339			SF	V0037	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		339			SF	V0038	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		678			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		678			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	S0063F	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2280 : Classroom

**Floor:** 2

**Room #:** 228

**Area (sqft):** 678

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Structure	Metal	678		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2280 : Classroom

**Floor:** 2

**Room #:** 228

**Area (sqft):** 678

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2280 : Classroom

**Floor:** 2

**Room #:** 228

**Area (sqft):** 678

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 282 of 353.

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2290 : Classroom

**Floor:** 2

**Room #:** 229

**Area (sqft):** 680

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		680(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0040	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0041	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		680			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		680			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2290 : Classroom

**Floor:** 2

**Room #:** 229

**Area (sqft):** 680

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	680		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2290 : Classroom

**Floor:** 2

**Room #:** 229

**Area (sqft):** 680

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

# ALL DATA REPORT

**Location: #2290 : Classroom**
**Floor: 2**
**Room #: 229**
**Area (sqft): 680**
**Survey Date: 2011-11-30**
**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2300 : Classroom

**Floor:** 2

**Room #:** 230

**Area (sqft):** 688

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		688(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		344			SF	V0037	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		344			SF	V0038	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		688			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		688			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2300 : Classroom

**Floor:** 2

**Room #:** 230

**Area (sqft):** 688

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Structure	Metal	688		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	
Structure	Metal	688		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2300 : Classroom

**Floor:** 2

**Room #:** 230

**Area (sqft):** 688

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #2300 : Classroom

Floor: 2

Room #: 230

Area (sqft): 688

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001	Grey	<5 mg/kg	No
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2310 : Classroom

**Floor:** 2

**Room #:** 231

**Area (sqft):** 680

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		680(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0040	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0041	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		680			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		680			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		2(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2310 : Classroom

**Floor:** 2

**Room #:** 231

**Area (sqft):** 680

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	680		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2310 : Classroom

**Floor:** 2

**Room #:** 231

**Area (sqft):** 680

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

# ALL DATA REPORT

**Location: #2310 : Classroom**
**Floor: 2**
**Room #: 231**
**Area (sqft): 680**
**Survey Date: 2011-11-30**
**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2320 : Storage

**Floor:** 2

**Room #:** 232

**Area (sqft):** 677

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		677(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		338			SF	V0037	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		339			SF	V0038	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		677			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		677			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2320 : Storage

**Floor:** 2

**Room #:** 232

**Area (sqft):** 677

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Structure	Metal	677		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2320 : Storage

**Floor:** 2

**Room #:** 232

**Area (sqft):** 677

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 290 of 353.

## ALL DATA REPORT

**Location: #2320 : Storage**  
**Survey Date: 2011-11-30****Floor: 2****School**  
**Room #: 232**  
**Last Re-Assessment:****Area (sqft): 677**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2330 : Classroom

**Floor:** 2

**Room #:** 233

**Area (sqft):** 679

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		679(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		340			SF	V0040	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		339			SF	V0041	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		679			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		679			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	S0063G	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2330 : Classroom

**Floor:** 2

**Room #:** 233

**Area (sqft):** 679

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	679		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2330 : Classroom

**Floor:** 2

**Room #:** 233

**Area (sqft):** 679

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2330 : Classroom

**Floor:** 2

**Room #:** 233

**Area (sqft):** 679

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 292 of 353.

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2350 : Classroom

**Floor:** 2

**Room #:** 235

**Area (sqft):** 701

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		701(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Ceiling	Bulkhead	Plaster		Paint	C	Y		25(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		350			SF	V0040	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		351			SF	V0041	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		701			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		701			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2350 : Classroom

**Floor:** 2

**Room #:** 235

**Area (sqft):** 701

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	701		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	
Ceiling	Plaster	25		SF	L0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2350 : Classroom

**Floor:** 2

**Room #:** 235

**Area (sqft):** 701

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 294 of 353.

# ALL DATA REPORT

**Location: #2350 : Classroom**  
**Survey Date: 2011-11-30**

**Floor: 2**

**School**  
**Room #: 235**  
**Last Re-Assessment:**

**Area (sqft): 701**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2410 : Office

**Floor:** 2

**Room #:** 241

**Area (sqft):** 290

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small pinholes and large shallow fissures, 1994			C	Y		90			SF	V0000	Non-Asbestos		None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		200			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	C	N		290			SF	S0042G	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 red			A	Y		290			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	N		290			SF					
Wall		Paint, White			A	Y		600			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2410 : Office

**Floor:** 2

**Room #:** 241

**Area (sqft):** 290

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	600		SF	V0001	White	Pb: 0.0085 %	No	
Structure	Metal	290		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2410 : Office

**Floor:** 2

**Room #:** 241

**Area (sqft):** 290

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2410 : Office

**Floor:** 2

**Room #:** 241

**Area (sqft):** 290

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #2413 : Washroom**

**Floor: 2**

**Room #:**

**Area (sqft): 0**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct		None Found														
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #2430 : Office**

**Floor: 2**

**Room #: 243**

**Area (sqft): 385**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster		Paint	C	Y		385(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Sheet Flooring, Large green cubes			A	Y		385(7)			SF	V0039	Chrysotile	10-25%	Confirmed Asbestos	PF
Mechanical Equipment	All	None Found														
Piping		Sweatwrap			A	Y						V0005	None Detected	N.D.	None	
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		2			EA	V0045	None Detected	N.D.	None	

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #2430 : Office**

**Floor: 2**

**Room #: 243**

**Area (sqft): 385**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Ceiling	Plaster	385		SF	V0017	White	Pb: 0.0123 %	Lead (Low)

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #2430 : Office

Floor: 2

Room #: 243

Area (sqft): 385

Survey Date: 2011-11-30

Last Re-Assessment:

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

Client: Upper Canada District School Board

Site: 2510 Parkedale Avenue, Brockville, ON

Building Name: 36 : Thousand Islands Secondary School

Location: #2430 : Office

Floor: 2

Room #: 243

Area (sqft): 385

Survey Date: 2011-11-30

Last Re-Assessment:

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No
Caulking	2	EA	V0001	Grey	<5 mg/kg

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2440 : Office

**Floor:** 2

**Room #:** 244

**Area (sqft):** 227

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 textured with pinholes			C	Y		227(7)			SF	V0036	Amosite	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		227			SF	V0033	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	C	N		227			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		227			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	N		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2440 : Office

**Floor:** 2

**Room #:** 244

**Area (sqft):** 227

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	227		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2440 : Office

**Floor:** 2

**Room #:** 244

**Area (sqft):** 227

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2440 : Office

**Floor:** 2

**Room #:** 244

**Area (sqft):** 227

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 300 of 353.

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2480 : Mechanical Room

**Floor:** 2

**Room #:** 248

**Area (sqft):** 619

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS - NO ACCESS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster			C	Y		100			%	V0001	None Detected	N.D.	None	
Duct	All	Fibreglass		Canvas	A	Y										
Duct	All	Not Insulated			A	Y										
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment	Air Handling Unit	Not Insulated			A	Y										
Mechanical Equipment	Heating Water Tank	Not Insulated			A	Y										
Piping	All	Fibreglass	All Pipe	Canvas	C	Y										
Piping	All	Parging Cement	Fitting	Canvas	C	Y		30(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Not Insulated			C	Y										
Structure	Not Accessible	None Found														
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2480 : Mechanical Room

**Floor:** 2

**Room #:** 248

**Area (sqft):** 619

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS - NO ACCESS				
Component	Quantity	Unit	Sample	Hazard

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2480 : Mechanical Room

**Floor:** 2

**Room #:** 248

**Area (sqft):** 619

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY - NO ACCESS				
Component	Quantity	Unit	Sample	Hazard

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2480 : Mechanical Room

**Floor:** 2

**Room #:** 248

**Area (sqft):** 619

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB - NO ACCESS						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2480 : Mechanical Room

**Floor:** 2

**Room #:** 248

**Area (sqft):** 619

# ALL DATA REPORT

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

ODS - NO ACCESS					
Component	Type	Quantity	Unit	Sample	Hazard

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #2480 : Mechanical Room**

**Floor: 2**

**Room #: 248**

**Area (sqft): 619**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

MOULD - NO ACCESS								
System	Material	Visible	Quantity	Unit	Sample Type	Sample No	Sample Description	Mould

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #2480 : Mechanical Room**

**Floor: 2**

**Room #: 248**

**Area (sqft): 619**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

TANK - NO ACCESS								
------------------	--	--	--	--	--	--	--	--

**Client: Upper Canada District School Board**

**Site: 2510 Parkedale Avenue, Brockville, ON**

**Building Name: 36 : Thousand Islands Secondary School**

**Location: #2490 : Workroom**

**Floor: 2**

**Room #: 249**

**Area (sqft): 435**

**Survey Date: 2011-11-30**

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		435			SF	V0036	[None]	0.5-5%	[Abated]	
Ceiling		Ceiling Tiles (lay-in), 2x4 small pinholes and narrow widthwise fissures, 09/22/16			C	Y		435			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		217			SF	V0030	[None]	0.5-5%	[Abated]	
Floor		Vinyl Floor Tile and Mastic			A	Y		218			SF	V0038	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		435			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		435			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Drywall and joint compound, Drywall no longer present										V0002	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		50(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2490 : Workroom

**Floor:** 2

**Room #:** 249

**Area (sqft):** 435

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0016	White	Pb: 0.0281 %	Lead (Low)
Structure	Metal	435		SF	V0015	Red	Pb: 0.330 %	Lead (High)
Wall	Plaster	50		SF	V0017	White	Pb: 0.0123 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2490 : Workroom

**Floor:** 2

**Room #:** 249

**Area (sqft):** 435

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2490 : Workroom

**Floor:** 2

**Room #:** 249

**Area (sqft):** 435

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2976 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		600			SF	V0036	[None]	0.5-5%	[Abated]	
Duct	All	None Found														
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	C	Y		25(7)			SF	S0062F	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2976 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Structure	Metal	600		SF	L0015	Red		Pb: 0.330 %	Lead (High)
Wall	Plaster	25		SF	V0017	White		Pb: 0.0123 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2976 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2976 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2977 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 186

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Duct	All	Fibreglass		Foil Face	A	Y										
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment	Air Handling Unit	Not Insulated			A	Y										
Piping	All	Fibreglass	All Pipe	Canvas	A	Y										
Piping	All	Parging Cement	Elbow	Canvas	A	Y		9(5)	1(5)		EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Parging Cement	Tee	Canvas	A	Y		9(5)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	Deck	Steel		Paint	C	N										
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		500(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2977 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 186

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall		100		%				No
Structure	Metal	186		SF	V0015	Red	Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2977 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 186

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2977 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 186

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V9500	T12		Presumed



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2978 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 81

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		81(7)			SF	S0062G	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		81			SF	V0033	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		81			SF	V0068	None Detected	N.D.	None	
Floor	All	Vinyl Floor Tile, 12x12 beige with orange and green flecks			A	Y		81			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Not Insulated			A	Y										
Structure	All	None Found														
Wall		Paint, White			A	Y		400(7)			SF	S0063E	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window Liner	Caulking, Grey, butyl sealant			A	Y		6(7)			EA	V0066	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2978 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 81

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	400		SF	V0016	White	Pb: 0.0281 %	Lead (Low)
Ceiling	Plaster	81		SF	V0017	White	Pb: 0.0123 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2978 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 81

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2978 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 81

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	6	EA	V0003	Grey, butyl sealant	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2979 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)			C	Y		6000			SF	V0036	[None]	0.5-5%	[Abated]	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		6000			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor	All	Terrazzo			A	Y		6000			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		18(7)		2(4)	EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Aircell	Straight	Sweatwrap	C	N			10		LF	V0003	None Detected	N.D.	None	
Structure	All	Metal		Paint	C	N		6000			SF					
Structure	Beam	Fireproofing (Cementitious)			B	N		300			SF	S0073ABC	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		1000(7)			SF	S0062E	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)			A	Y										
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		2(7)			EA	S0066C	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2979 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Plaster	1000		SF	V0017	White		Pb: 0.0123 %	Lead (Low)
Structure	Metal	6000		SF	V0015	Red		Pb: 0.330 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2979 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2979 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 6000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



## ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2980 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		600			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Deck	Steel		Paint	C	N										
Wall	All	Concrete (precast)			A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2980 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	600		SF	L0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2980 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2980 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 600

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001		<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2981 : Staff Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		50			SF	V0000	Non-Asbestos		None	
Duct		None Found														
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping		None Found														
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		200			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2981 : Staff Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	200		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	50		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2981 : Staff Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2981 : Staff Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2982 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 261

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		261			SF	V0000	Non-Asbestos		None	
Duct		None Found														
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		500			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2982 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 261

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	500		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	261		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2982 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 261

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2982 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 261

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #2983 : Janitor's Room/Pipe Chase  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft):** 50

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened), 1x1 coarse fissures			C	Y		50			SF	V0020	None Detected	N.D.	None	
Duct		None Found														
Floor	All	Concrete (poured)		Paint	A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe		A	Y										
Piping	All	Not Insulated			A	Y										
Structure	Not Accessible	None Found														
Wall		Paint, White			A	Y		75			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Plaster			A	Y		50			SF	V0071	None Detected	N.D.	None	

**Client:** Upper Canada District School Board  
**Location:** #2983 : Janitor's Room/Pipe Chase  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft):** 50

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	75		SF	V0004	White	Pb: 0.0078 %	No
Wall	Plaster	50		SF	V0022	White	Pb: 0.0092 %	Lead (Low)
Floor	Concrete (poured)	50		SF	V0011	Grey	Pb: 0.0065 %	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2984 : Girls Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 242

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		242			SF	V0000	Non-Asbestos		None	
Duct		None Found														
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		500			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2984 : Girls Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 242

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	500		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	242		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2984 : Girls Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 242

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2984 : Girls Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 242

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2985 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		2000			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		2000			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Parging Cement	Fitting	Canvas	C	N		8(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	Sweatwrap	Straight	Unjacketed	C	N			4		LF	V0005	None Detected	N.D.	None	
Structure	All	Metal		Paint	C	N		2000			SF					
Wall		Plaster		Paint	A	Y		1000			SF	S0071E	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										
Wall	Window Liner	Caulking, Grey, butyl sealant			A	Y		6(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window Liner	Caulking, Black, butyl sealant			A	Y	Y	1			EA	V0046	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2985 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	1000		SF	V0022	White	Pb: 0.0092 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2985 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2985 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 2000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	7	EA	V0002	Grey/black, butyl sealant	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2986 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		500			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		500			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Duct	All	Fibreglass		Foil Face	C	N										
Duct	All	Not Insulated			C	N										
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Floor	All	Terrazzo			A	Y										
Piping		Not Insulated			C	Y										
Piping		Not Insulated			C	Y										
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Metal		Paint	C	N										
Structure	Deck	Metal		Paint	C	N										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2986 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	500		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2987 : Girls Washroom

**Floor:** 2

**Room #:** 2987

**Area (sqft):** 283

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		283			SF	V0000	Non-Asbestos		None	
Ceiling	Skylight	Drywall and joint compound		Paint	C	Y		25			SF	V0055	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		283			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		283			SF					
Wall		Paint, White			A	Y		600			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2987 : Girls Washroom

**Floor:** 2

**Room #:** 2987

**Area (sqft):** 283

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	600		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Drywall and joint compound	25		SF	V0002	White	Pb: 0.0005 %	No	
Structure	Metal	283		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2987 : Girls Washroom

**Floor:** 2

**Room #:** 2987

**Area (sqft):** 283

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2987 : Girls Washroom

**Floor:** 2

**Room #:** 2987

**Area (sqft):** 283

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2988 : Pipe Chase

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Plaster		Paint	C	Y		50			SF	S0057C	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Concrete (poured)		Paint	A	Y		50			SF					
Mechanical Equipment	All	None Found														
Piping	All	Sweatwrap	Straight	Canvas	A	Y		10		1	LF	V0005	None Detected	N.D.	None	
Structure	All	None Found														
Wall		Paint, White			A	Y		150			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2988 : Pipe Chase

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	150		SF	V0001	White	Pb: 0.0085 %	No	
Floor	Concrete (poured)	50		SF	L0009	Grey	Pb: 0.0369 %	Lead (Low)	
Ceiling	Plaster	50		SF	L0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2988 : Pipe Chase

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2988 : Pipe Chase

**Floor:** 2

**Room #:**

**Area (sqft):** 50

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2989 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 304

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		304			SF	V0000	Non-Asbestos		None	
Ceiling	Skylight	Drywall and joint compound		Paint	C	Y		25			SF	V0055	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		304			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		304			SF					
Wall		Paint, White			A	Y		600			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2989 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 304

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	600		SF	V0001	White	Pb: 0.0085 %	No	
Ceiling	Drywall and joint compound	25		SF	V0002	White	Pb: 0.0005 %	No	
Structure	Metal	304		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2989 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 304

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2989 : Boys Washroom

**Floor:** 2

**Room #:**

**Area (sqft):** 304

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2990 : Custodial Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 212

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		212			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		212			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor	All	Concrete (poured)			A	Y										
Mechanical Equipment	All	None Found														
Piping	All	Parging Cement	Fitting	Canvas	C	N		4(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		800			SF	S0043F	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2990 : Custodial Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 212

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No
Floor	Concrete (poured)	212		SF	L0009	Green	Pb: 0.0369 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2990 : Custodial Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 212

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2990 : Custodial Storage

**Floor:** 2

**Room #:**

**Area (sqft):** 212

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2991 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		5000			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Piping	All	Parging Cement	Elbow	Canvas	C	N		10(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Piping	Rain Water Leader	Sweatwrap	Straight	Canvas	C	N		40			LF	V0005	None Detected	N.D.	None	
Structure	Deck	Metal		Paint	C	N										
Wall		Plaster		Paint	C	Y		1000			SF	S0057D	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		6(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2991 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	5000		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Plaster	1000		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2991 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed
Batteries In Emer. Lights	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2991 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 5000

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	6	EA	V0002	Butyl sealant grey	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2992 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		1500			SF	V0000	Non-Asbestos		None	
Duct	All	Fibreglass		Foil Face	C	N										
Floor	All	Terrazzo			A	Y		1500			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Piping	All	Aircell	Straight	Sweatwrap	C	N			60		LF	V0003	None Detected	N.D.	None	
Structure	All	Metal		Paint	C	N		1500			SF					
Wall		Paint			A	Y		1000(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)			A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2992 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Structure	Metal	1500		SF	V0015	Red		Pb: 0.330 %	Lead (High)
Wall	Concrete (precast)	1000		SF	V0016	White		Pb: 0.0281 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2992 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2992 : Corridor

**Floor:** 2

**Room #:**

**Area (sqft):** 1500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2993 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Duct	All	None Found														
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass	All Pipe	Foil Face	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Plaster		Paint	C	Y		25(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Paint, White			A	Y		800(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Light grey			A	Y		4			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2993 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	500		SF	V0015	Red	Pb: 0.330 %	Lead (High)	
Wall	Plaster	25		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2993 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2993 : Stairwell

**Floor:** 2

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	4	EA	V0001	Grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2994 : Custodial Room

**Floor:** 2

**Room #:**

**Area (sqft):** 59

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct	All	None Found														
Floor		Vinyl Floor Tile and Mastic			A	Y		59			SF	V0030	[None]	0.5-5%	[Abated]	
Floor		Mastic		Vinyl Floor Tile	D	N		59			SF	V0051	None Detected	N.D.	None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal		Paint	C	Y		59			SF					
Wall		Paint, White			A	Y		600(7)			SF	V0063	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2994 : Custodial Room

**Floor:** 2

**Room #:**

**Area (sqft):** 59

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description		Amount	Hazard
Wall	Concrete (precast)	600		SF	V0001	White		Pb: 0.0085 %	No
Structure	Metal	59		SF	V0003	Red		Pb: 0.0880 %	Lead (Low)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2994 : Custodial Room

**Floor:** 2

**Room #:**

**Area (sqft):** 59

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2994 : Custodial Room

**Floor:** 2

**Room #:**

**Area (sqft):** 59

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2995 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 85

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	None Found														
Duct	All	Not Insulated			A	Y										
Floor	All	Concrete (poured)		Paint	A	Y		85			SF					
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			A	Y										
Structure	All	Concrete (poured)			C	Y		85			SF					
Wall		Masonry			A	Y										
Wall		Paint, White			A	Y		200			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2995 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 85

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Floor	Concrete (poured)	85		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	
Wall	Concrete (precast)	200		SF	V0001	White	Pb: 0.0085 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2995 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 85

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2995 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 85

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100	%	V9500	T12		Presumed

# ALL DATA REPORT

**Client:** Upper Canada District School Board  
**Location:** #2996 : Corridor Ramp and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft):** 2000

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened), 1x1 smooth			C	N		2000			SF	V0029	None Detected	N.D.	None	
Ceiling		Drywall and joint compound		Paint	C	Y		1000			SF	S0055D	None Detected	N.D.	None	
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		1000			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Terrazzo			A	Y		2000			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Plaster		Paint	A	Y		200			SF	S0057E	None Detected	N.D.	None	
Wall	All	Concrete (precast)			A	Y										
Wall	Window	Caulking, Grey, silicone			A	Y						V0000	Non-Asbestos		None	

**Client:** Upper Canada District School Board  
**Location:** #2996 : Corridor Ramp and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft):** 2000

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	200		SF	V0008	White	Pb: 0.0339 %	Lead (Low)	
Ceiling	Drywall and joint compound	1000		SF	V0002	White	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board  
**Location:** #2996 : Corridor Ramp and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft):** 2000

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board  
**Location:** #2996 : Corridor Ramp and Stairwell  
**Survey Date:** 2011-11-30

**Site:** 2510 Parkedale Avenue, Brockville, ON  
**Floor:** 2

**Building Name:** 36 : Thousand Islands Secondary School  
**Room #:**  
**Last Re-Assessment:**

**Area (sqft):** 2000

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking			V0000	Grey, silicone		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2997 : Weight Room

**Floor:** 2

**Room #:**

**Area (sqft):** 2088

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			D	Y		2088			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Concrete (poured)			A	Y		2088			SF					
Mechanical Equipment	All	None Found														
Piping	All	Not Insulated			A	Y										
Structure	All	None Found														
Wall		Paint, White			A	Y		2000			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2997 : Weight Room

**Floor:** 2

**Room #:**

**Area (sqft):** 2088

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	2000		SF	V0001	White	Pb: 0.0085 %	No	
Floor	Concrete (poured)	2088		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2997 : Weight Room

**Floor:** 2

**Room #:**

**Area (sqft):** 2088

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PB PRODUCTS				
Component	Quantity	Unit	Sample	Hazard
Bell And Spigot Fittings	100	%	V9500	Presumed

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2997 : Weight Room

**Floor:** 2

**Room #:**

**Area (sqft):** 2088

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2997 : Weight Room

**Floor:** 2

**Room #:**

**Area (sqft):** 2088

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2998 : Bleachers

**Floor:** 2

**Room #:**

**Area (sqft):** 1510

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 wicker			C	Y		1510			SF	V0000	Non-Asbestos		None	
Duct	All	None Found														
Floor	All	Concrete (poured)		Paint	A	Y		1510			SF					
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	None Found														
Wall		Paint, White			A	Y		2000			SF	S0043G	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2998 : Bleachers

**Floor:** 2

**Room #:**

**Area (sqft):** 1510

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1000		SF	V0001	White	Pb: 0.0085 %	No	
Floor	Concrete (poured)	1510		SF	V0009	Grey	Pb: 0.0369 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2998 : Bleachers

**Floor:** 2

**Room #:**

**Area (sqft):** 1510

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2998 : Bleachers

**Floor:** 2

**Room #:**

**Area (sqft):** 1510

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001	Light grey, window	<5 mg/kg	No



## ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2999 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 413

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct	All	Fibreglass		Canvas	B	Y										
Duct	All	Not Insulated			B	Y										
Floor	All	Concrete (poured)			B	Y										
Mechanical Equipment	Air Handling Unit	Not Insulated			B	Y										
Piping	All	Fibreglass	All Pipe	Paper	B	Y										
Piping	All	Fibreglass	All Pipe	Polyvinyl chloride (PVC)	B	Y										
Structure	Deck	Steel		Paint	C	Y										
Wall		Paint, White			B	Y		1000			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	B	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2999 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 413

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Metal	413		SF	V0003	Red	Pb: 0.0880 %	Lead (Low)	
Wall	Concrete (precast)	1000		SF	V0043	White		No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2999 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 413

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #2999 : Mechanical Room

**Floor:** 2

**Room #:**

**Area (sqft):** 413

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB					
Component	Quantity	Unit	Sample	Sample Description	Amount
Light Ballasts			V0000	T8	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3000 : Cafeteria

**Floor:** 1

**Room #:**

**Area (sqft):** 1649

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		1649			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		1649			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		1649			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		1649			SF	S0051A	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		1649			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Paint, White			A	Y		1000			SF	S0049B	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3000 : Cafeteria

**Floor:** 1

**Room #:**

**Area (sqft):** 1649

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	1000		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	1649		SF	V0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3000 : Cafeteria

**Floor:** 1

**Room #:**

**Area (sqft):** 1649

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3000 : Cafeteria

**Floor:** 1

**Room #:**

**Area (sqft):** 1649

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3001 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 810

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	Y		810			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		810			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		810			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		810			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y										
Mechanical Equipment		None Found														
Piping	All	Not Insulated			A	Y										
Structure		Metal		Paint	C											
Wall		Paint, White			A	Y		600			SF	V0049	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door	Caulking, Grey			A	Y		1			EA	S0044B	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, black			A	Y		1			EA	S0046B	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3001 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 810

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Concrete (precast)	600		SF	V0004	White	Pb: 0.0078 %	No	
Structure	Metal	810		SF	L0006	Red	Pb: 0.110 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3001 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 810

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3001 : Kitchen Prep

**Floor:** 1

**Room #:**

**Area (sqft):** 810

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	1	EA	V0001	Grey, door frame	<5 mg/kg	No
Caulking	1	EA	V0002	Butyl sealant black	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3002 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling tiles (glue-on), 1x1 large and medium random pinhole			C	N		500			SF	V0004	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		500			SF	V0000	Non-Asbestos		None	
Ceiling	Acoustic Tile	Adhesive/mastic			C	N		500			SF	V0010	None Detected	N.D.	None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		500			SF	S0054B	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		500			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Canvas	C	N										
Structure	Deck	Steel		Paint	C	N										
Wall		Drywall and joint compound		Paint	A	Y		200			SF	S0048B	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3002 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Metal	500		SF	V0006	Red	Pb: 0.110 %	Lead (High)
Wall	Drywall and joint compound	200		SF	V0005	White	Pb: <0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3002 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3003 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 flecks and pinholes, plastic covering, 03/24/03			C	Y		200			SF	V0000	Non-Asbestos		None	
Ceiling		Plaster		Ceiling Tiles (lay-in)	C	N		200(7)			SF	V0052	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Duct	All	Fibreglass		Foil Face	C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		200			SF	V0051	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light grey with dark grey and white smears			A	Y		200			SF	V0000	Non-Asbestos		None	
Mechanical Equipment		None Found														
Piping	All	Fibreglass	All Pipe	Paper	C	N										
Structure		None Found														
Wall		Paint, White			A	Y		500			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	All	Drywall and joint compound		Paint	A	Y		200			SF	V0002	None Detected	N.D.	None	
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	
Wall	Window Liner	Caulking, Butyl sealant, grey			A	Y		3(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3003 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	500		SF	V0001	White	Pb: 0.0085 %	No
Wall	Drywall and joint compound	200		SF	V0002	White	Pb: 0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3003 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 200

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3003 : Office

**Floor:** 1

**Room #:**

**Area (sqft):** 200

2023-08-30

Quantities shown above are based on visual approximations only and may be subject to variation. Copyright Pinchin Ltd. 2023

Page 342 of 353.

Survey Date: 2011-11-30

Last Re-Assessment:

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking	3	EA	V0001	Grey, window frames	<5 mg/kg	No
Caulking	3	EA	V0002	Butyl sealant grey	<5 mg/kg	No
Light Ballasts			V0000	T8		No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3004 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 790

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		790			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor		Mastic		Vinyl Floor Tile	D	N		790			SF	V0042	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 light blue with grey and white flecks			A	Y		790			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	Fibreglass			C	N										
Structure	All	Metal		Paint	C	N		790			SF					
Wall		Drywall and joint compound		Paint	A	Y		200			SF	V0048	None Detected	N.D.	None	
Wall		Plaster		Paint	A	Y		50			SF	S0071A	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	S0049C	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3004 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 790

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Plaster	50		SF	L0022	White	Pb: 0.0092 %	Lead (Low)
Wall	Concrete (precast)	800		SF	V0004	White	Pb: 0.0078 %	No
Wall	Drywall and joint compound	200		SF	V0005	White	Pb: <0.0005 %	No
Structure	Metal	790		SF	V0006	Red	Pb: 0.110 %	Lead (High)

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3004 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 790

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3004 : Classroom

**Floor:** 1

**Room #:**

**Area (sqft):** 790

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	3	EA	V0001	Grey, window frames	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3005 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	All	Ceiling Tiles (lay-in), 2x4 random flecks and pinholes, 03/24/03			C	Y		500			SF	V0000	Non-Asbestos		None	
Duct	All	Not Insulated			C	N										
Floor	All	Terrazzo			A	Y		500			SF					
Mechanical Equipment	All	None Found														
Piping	All	Parging Cement	Elbow	Canvas	C	N		5(7)			EA	V0006	Chrysotile	5-10%	Confirmed Asbestos	F
Structure	All	Metal		Paint	C	N		500			SF					
Wall		Plaster		Paint	A	Y		20(7)			SF	V0062	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Wall	All	Concrete (precast)			A	Y										
Wall	Window Liner	Caulking, Grey, butyl sealant			A	Y		6(7)			EA	V0058	Chrysotile	0.5-5%	Confirmed Asbestos	NF

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3005 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Wall	Plaster	20		SF	V0017	White	Pb: 0.0123 %	Lead (Low)	
Structure	Metal	500		SF	V0015	Red	Pb: 0.330 %	Lead (High)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3005 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3005 : Corridor

**Floor:** 1

**Room #:**

**Area (sqft):** 500

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V0000	T8		No
Caulking	6	EA	V0002	Grey, butyl sealant	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3006 : Classroom

**Floor:** 2

**Room #:** 206

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 small and medium clustered pinholes, 07/19/94			C	Y		800			SF	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened), 1x1 medium and large uniform pinholes			C	N		800			SF	V0004	None Detected	N.D.	None	
Duct	All	None Found														
Floor		Mastic		Vinyl Floor Tile	C	N		800			SF	V0054	None Detected	N.D.	None	
Floor		Vinyl Floor Tile, 12x12 cream with beige and white smears			A	Y		800			SF	V0000	Non-Asbestos		None	
Mechanical Equipment	All	None Found														
Piping	All	None Found														
Structure	All	Metal														
Wall		Drywall and joint compound		Paint	A	Y		150			SF	S0055F	None Detected	N.D.	None	
Wall		Paint, White			A	Y		800			SF	V0043	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Window	Caulking, Light grey			A	Y		3			EA	V0045	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3006 : Classroom

**Floor:** 2

**Room #:** 206

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	800		SF	V0001	White	Pb: 0.0085 %	No
Wall	Drywall and joint compound	150		SF	V0002	White	Pb: 0.0005 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3006 : Classroom

**Floor:** 2

**Room #:** 206

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Tube	100	%	V9000	Yes

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3006 : Classroom

**Floor:** 2

**Room #:** 206

**Area (sqft):** 800

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts			V9500	T12		Presumed
Caulking	3	EA	V0001	Light grey	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3007 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Structure	Canopy	Plaster, Textured		Paint	C	Y		15	15		SF	S0078ABC	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y										
Wall		Masonry			A	Y										
Wall		Caulking, Butyl sealant, black			A	Y						S0076A	None Detected	N.D.	None	
Wall		Caulking, Grey, prefab concrete panels			D	Y		156			LF	V0077	None Detected	N.D.	None	
Wall	Expansion Joint	Caulking, Grey, hard			A	Y		20(7)			LF	S0083B	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Grey			A	Y						S0077A	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3007 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Plaster	15	15	SF	L0029	Yellow	Pb: 0.0005 %	No	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3007 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking			P0004	Butyl sealant, black	<5 mg/kg	No
Caulking			P0005	Grey, window frames	<5 mg/kg	No
Caulking	20	LF	P0006	Grey, hard, expansion joint	<5 mg/kg	No

# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3008 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Structure	Canopy	Wood			C	Y										
Structure	Canopy	Plaster, Textured, swirled		Paint	C	Y		60			SF	S0080ABC	None Detected	N.D.	None	
Structure	Soffit	Plaster, Textured, swirled		Paint	D	Y		200			SF	V0080	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y										
Wall		Masonry			A	Y										
Wall		Caulking, Butyl sealant, black			A	Y						S0076BC	None Detected	N.D.	None	
Wall	Door	Caulking, Grey			A	Y						V0077	None Detected	N.D.	None	
Wall	Window	Caulking, Grey			A	Y						S0077B	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3008 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT								
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Structure	Plaster	260		SF	L0030	White	Pb: 0.0015 %	No

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3008 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking			P0004	Butyl sealant, black	<5 mg/kg	No
Caulking			P0005	Grey, window frames	<5 mg/kg	No



# ALL DATA REPORT

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3009 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Structure	Canopy	Concrete (poured)		Paint	C	Y										
Structure	Canopy	Plaster, Textured		Paint	C	Y		220(7)			SF	S0081ABC	Chrysotile	0.5-5%	Confirmed Asbestos	PF
Structure	Canopy	Metal		Paint	C	Y										
Structure	Canopy	Paint, Beige			C	Y		200			SF	S0082ABC	None Detected	N.D.	None	
Wall		Caulking, Butyl sealant, black			A	Y						V0076	None Detected	N.D.	None	
Wall	Door	Caulking, Grey			A	Y						V0077	None Detected	N.D.	None	
Wall	Expansion Joint	Caulking, Grey, hard			A	Y		20(7)			LF	S0083AC	Chrysotile	0.5-5%	Confirmed Asbestos	NF
Wall	Window	Caulking, Grey			A	Y						S0077C	None Detected	N.D.	None	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3009 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PAINT									
System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard	
Structure	Plaster	220		SF	L0031	White	Pb: 0.138 %	Lead (High)	
Structure	Concrete (poured)	200		SF	L0032	Beige	Pb: 0.0037 %	No	
Structure	Metal	100	325	SF	L0033	White	Pb: 0.0556 %	Lead (Low)	

**Client:** Upper Canada District School Board

**Site:** 2510 Parkedale Avenue, Brockville, ON

**Building Name:** 36 : Thousand Islands Secondary School

**Location:** #3009 : Exterior

**Floor:** 1

**Room #:**

**Area (sqft):** 0

**Survey Date:** 2011-11-30

**Last Re-Assessment:**

PCB						
Component	Quantity	Unit	Sample	Sample Description	Amount	PCB
Caulking			P0004	Butyl sealant, black	<5 mg/kg	No
Caulking			V0005	Grey, window frames	<5 mg/kg	No
Caulking	20	LF	P0006	Grey, hard, expansion joint	<5 mg/kg	No

## Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
L####	Paint sample collected	LF	Linear feet	V	Visible
P####	PCB sample collected	EA	Each	AP	Air Plenum
M####	Mould sample collected	%	Percentage	F	Friable material
V####	Material is visually identified to be identical to S####	LF	Linear feet	NF	Non Friable material
V0000	Known non hazardous material			PF	Potentially Friable material
V9000	Material visually identified as a Hazardous Material			Pb	Lead
V9500	Material is presumed to be a hazardous material			Hg	Mercury
				As	Arsenic
				Cr	Chromium

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material

Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.

Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				